

ASS. REC BY: T. W. J. M.

REF: 03/SUM R 22007902/Tcy S

ASSIGNMENT

From: _____ Date: _____
Estimate lost: _____
OD / TP / IS / TP RES / OD RES / EVA / INV / MV
To Inspected/vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SUM A 3464R Yr Regn: 2018, June
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Honda Shuttle C.C. 1496
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: GP71212511
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 185/60R15
R: _____

(Policy condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 984K
IDAC Accident Report: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Finenza
Front 6 mm Rear 6 mm
R/Bal. _____ mm R/Bal. _____ mm
L/Bal. 6 mm L/Bal. _____ mm
D.O.A. _____ D.O.I. 19/8/22
Survey held at Bijpost
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>By King week</u>

Date/Time, File Pass to? : Preli. Report
1) : Final Report
Date/Time, File Return to?

Days Of Repair: _____
Resurvey No. of Trip: _____

2) _____
Report Format: _____
Lump Sum / I.B.L. (%) _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	
Transportation:	
S + RS. Sl.	
Photos	
Others	
TOTAL	

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT
 #01-49 SINGAPORE 415875
 Tel: +65 64524457
 Fax: +65 64524584
 Company Reg No: 201929175W

Repair Estimate

Vehicle number: SMA3464R
 Make & Model: Honda Shuttle
 Chassis number: GP71212511

Date of survey:
 Name of surveyor:
 Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Tailgate	1	\$ <i>bt</i> 1,209.00
2	Tailgate windscreen glass rubber moulding	1	\$ <i>rec</i> 149.00
3	Tailgate centre emblem	1	\$ <i>rec</i> 43.00
4	Tailgate "Shuttle" emblem	1	\$ <i>na</i> 57.00
5	Tailgate "Hybrid" emblem	1	\$ <i>rec</i> 68.00
6	Tailgate chrome moulding garnish	1	\$ <i>cut</i> 321.00
7	Tailgate RH lamp assy	1	\$ <i>cut</i> 441.00
8	Tailgate RH lamp gasket	1	\$ <i>rec</i> 25.00
9	Tailgate LH lamp assy	1	\$ <i>cut</i> 441.00
10	Tailgate LH lamp gasket	1	\$ <i>rec</i> 25.00
11	Tailgate lock	1	\$ <i>bt</i> 181.00
12	Tailgate lock catch	1	\$ <i>bt</i> 43.00
13	Tailgate inner trim board	1	\$ <i>cut</i> 342.00
14	Tailgate weatherstrip	1	\$ <i>mi</i> 187.00
15	Tailgate pull handle	1	\$ <i>na</i> 28.00
16	Tailgate wiper motor	1	\$ <i>X</i> 432.00
17	Tailgate RH number plate lamp	1	\$ <i>X</i> 28.00
18	Tailgate LH number plate lamp	1	\$ <i>X</i> 28.00
19	Tailgate RH hinge	1	\$ <i>?</i> 67.00
20	Tailgate LH hinge	1	\$ <i>?</i> 67.00
21	Tailgate RH absorber stay	1	\$ <i>?</i> 178.00
22	Tailgate LH absorber stay	1	\$ <i>mis</i> 178.00
23	Rear bumper	1	\$ <i>dis</i> 1,152.00
24	Rear bumper towing cover	1	\$ <i>mis</i> 25.00
25	Rear bumper LH reflector	1	\$ <i>mis</i> 56.00
26	Rear bumper LH reflector garnish	1	\$ <i>mis</i> 68.00
27	Rear bumper LH inner sponge	1	\$ <i>X</i> 92.00
28	Rear bumper LH bracket	1	\$ <i>X</i> 45.00
29	Rear bumper LH lower cover	1	\$ <i>X</i> 101.00
30	Rear bumper RH lower cover	1	\$ <i>X</i> 101.00
31	End panel (outer)	1	\$ <i>cut</i> 573.00
32	End panel (inner)	1	\$ <i>cut</i> 483.00
33	End panel buzzer sensor	1	\$ <i>?</i> 156.00
34	End panel antenna sensor	1	\$ <i>?</i> 94.00
35	RH taillamp assy	1	\$ <i>cut</i> 556.00
36	RH taillamp lock clips	1	\$ <i>X</i> 52.00
37	RH taillamp panel	1	\$ <i>X</i> 213.00
38	LH taillamp assy	1	\$ <i>cut</i> 556.00
39	LH taillamp lock clips	1	\$ <i>X</i> 52.00

16	Rear LH fender inner trim board clips	1set	\$ 300 80.00
17	Rear LH fender inner upper trim board clips	1set	\$ X 60.00
18	Rear LH fender inner panel joint sealant	1	\$ X 80.00
19	Rear LH fender glass sealant	1	\$ 740 80.00
20	Rear LH fender glass inner seal	1	\$ 370 60.00
21	Rear LH door sealant	1	\$ X 100.00
22	LH side rocker panel garnish clips		\$ X 80.00
Total:			\$ 2,710.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1800 2,800.00
2	Spray painting on affected areas and panels	\$ 1800 2,200.00
3	Check wiring and lighting system on affected areas	\$ 30 120.00
4	Apply rust coating chemical on affected areas and panels	\$ 100 180.00
5	Replace tailgate windscreen glass to assist repair	\$ 120 200.00
6	Remove and replace tailgate reverse camera to assist repair	\$ X 180.00
7	Remove and reinstall fuel tank, pipes, sensors and hoses to assist repair	\$ 60 220.00
8	Remove and replace rear bumper reverse sensors to assist repair	\$ 30 100.00
9	Remove and replace rear inner trims, garnish and boards to assist repair	\$ 80 350.00
10	Remove and replace exhaust silencer and gasket to assist repair	\$ X 180.00
11	Test drive and adjust rear undercarriage parts to assist repair	\$ X 650.00
12	Remove and replace rear unddercarriage parts to assist repair <i>pluto</i>	\$ 7200 550.00
13	Remove and replace roof lining, seat, seat belt and carpet to assist repair	\$ 80 480.00
14	Remove and replace rear LH fender glass to assist repair	\$ 80 180.00
15	Remove and reinstall hybrid battery and wire harness to assist repair <i>photo?</i>	\$ 400 1,200.00
16	Diagnose fault code and reset control system	\$ 150 550.00
Total:		\$ 10,140.00

Agreed Amount: _____ (Part by Part / Lump sum)
 Working days: _____

Spare Parts: \$ 18,485.60

Special Nett: \$ 2,710.00
Labour: \$ 10,140.00
Total Amount: \$ 31,335.60

Taufik 97495749
WP 19/8/22 @ 1115
L/S Resurvey after repair
taufik@lkhauto.com
To check consistency of accident
To check part prices
14 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT
 #01-49 SINGAPORE 415875
 Tel: +65 64524457
 Fax: +65 64524584
 Company Reg No: 201929175W

Repair Supplementary Estimate

Vehicle number: SMA3464R
 Make & Model: Honda Shuttle
 Chassis number:

Date of survey:
 Name of surveyor:
 Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Rear RH fender inner trim board	1	\$ 505.00
1	Hybrid battery	1	\$ 15,783.60

in dis

** To Reserve New battery & old battery together*
22/8/22 05 pm
hupha

	\$ 16,288.60
Parts less 20%	\$ 3,257.72
Total	\$ 13,030.88

No.	Special Nett Items	Qty	Amount S\$
1	Rear RH fender inner trim board clips	1set	\$ 80.00

3D no

Total: \$ 80.00

No.	Labour and painting	Amount S\$

Total: \$ -

Agreed Amount: _____ (Part by Part / Lump sum)
 Working days: _____

Spare Parts:	\$ 13,030.88
Special Nett:	\$ 80.00
Labour:	\$ -
Total Amount:	\$ 13,110.88

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 428D

Vehicle Details

Vehicle No.: SMA3464R
Vehicle to be Exported: Yes
Intended Deregistration Date: 17 Aug 2022
Vehicle Make: HONDA
Vehicle Model: SHUTTLE HYBRID 1.5 AUTO
Primary Colour: Black
Manufacturing Year: 2018
Engine No.: LEB6555170
Chassis No.: GP71212511
Maximum Power Output: 101.0 kW (135 bhp)
Open Market Value: \$20,434.00
Original Registration Date: 04 Jun 2018
First Registration Date: 04 Jun 2018
Transfer Count: 1
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 03 Jun 2028
PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 03 Jun 2028
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$37,010.00
COE Rebate Amount: \$21,450.00
Total Rebate Amount: \$25,200.00

The information contained herein is correct as at 16 Aug 2022

OK

VEHICLE NO: SMA 3464 R

MAKE & MODEL : Honda shuttle Hybrid ^{AUTO} MANUAL

DATE OF ACCIDENT	15 10 2022	C.C.
TIME OF ACCIDENT	bet 6.00 - 6.30 AM / (PM)	
LOCATION OF ACCIDENT	Bukit Timah Road turn to Swiss Club Road	
EXACT PURPOSE USED AT TIME OF ACCIDENT	EMPLOYMENT / PRIVATE USE / (PRIVATE HIRE)	
NAME OF OWNER	Tan Boon Wan	
EMAIL:	tanbw1402@outlook.com	Office. MOBILE: 93366300
NRIC	S 1607428D	
CLAIM TYPE	OD / (THIRD PARTY) / REPORTING ONLY	
FLEET POLICY:	YES / (NO)?	
INSURANCE CO.	China TAPPING	
TYPE OF COVERAGE	Comprehensive / Third Party / Third Party Fire & Theft	
POLICY NO.	DMHCSNW00014222100	
NAME OF DRIVER	(AS ABOVE) / IF NO:	
NRIC	S 1607428D	
DATE OF BIRTH	14 02 1963	
ANY PASSENGER	(YES) / NO:	
NAME OF PASSENGER	Noel	
GENDER OF PASSENGER	(MALE) / FEMALE	
OCCUPATION	(Outdoor) / Indoor	
DATE OF DRIVING PASS	02 03 1985	
GENDER	(Male) / Female	
CONTACT NO.	Mobile: 93366300	Office:
EMAIL:	tanbw1402@outlook.com	
ADDRESS	71 Jurong West Central 3 #12-16 S(648335)	
DOES DRIVER OWN OTHER VEHICLES?	(NO) / If yes: Reg No.	INSURER:
RELATIONSHIP	Employee / (If No.) OWNER	
WEATHER CONDITION	(Clear) / Raining / Other:	
ROAD SURFACE	(Dry) / Wet / Other:	
ANY INJURIES	No (If yes: Who? 1) DRIVER (M) 2) NOEL (M)	
CONVEYED BY AMBULANCE	(No) / If yes: Who?	
POLICE REPORT	No / (If yes: Where?	
NOTICE OF INTENDED PROSECUTION GIVEN?	NO / IF YES: WHO?	
VEHICLE B NO.	SHB 451 B	Any Passenger:
NAME		
CONTACT NO.		
VEHICLE C NO.		Any Passenger:
VEHICLE D NO.		Any Passenger:
VEHICLE E NO.		Any Passenger:
VEHICLE F NO.		Any Passenger:
ANY WITNESS		
WITNESS CONTACT NO.		
WAS THERE ANY VIDEO CAPTURE?	(YES) / NO	
WAS THERE ANY AUDIO RECORDED?	(YES) / NO	
SCENE ACCIDENT PHOTOS TAKEN?	(YES) / NO	
Who is Reporting	Driver / Owner / Both	
Original Language Used	English / Mandarin / Others:	
Have you been approach by unknown person soliciting (\$) / offering accident claims assistance?	YES (NO)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



Describe Circumstance of the Accident

On the above date and time, I was travelling in Bukit Rd turning into Swiss Club road on approaching the junction of Dunearn road I slow down and ^{stop} as the traffic is red.

When the traffic turn green and I start to move off suddenly I felt a very hard impact from my rear left, thereafter as I alight and check I realize that vehicle ^B had dash red light along Dunearn road and cause the collision.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999



T/20220816/2012

1 of 3

Report No. T/20220816/2012

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/08/2022 11:10	Vide Report No.:	Station Diary No.: 49
--	------------------	--------------------------

Informant's Particulars

Name of Informant: TAN BOON WAH		Address: 71 JURONG WEST CENTRAL 3 #12-16 SINGAPORE 648335	
ID Type / ID No.: NRIC NO / S1607428D		Contact No.: Home/Office:	Mobile: 93366300
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 59	Date of Birth: 14/02/1963	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: GRAB DRIVER		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 15/08/2022 18:15	Type of Location: Straight Road
Location: SWISS CLUB ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHB451B	Car				Slightly Damaged	0
SMA3464R	Car	HONDA	SHUTTLE HYBRID 1.5 AUTO	Black	Seriously Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMA3464R	CHINA TAIHING INSURANCE (SINGAPORE) PTE. LTD.	DMHCSNW000142 22100	04/12/2021	03/12/2022



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999



T/20220816/2012

2 of 3

Report No. T/20220816/2012

CONTINUATION OF REPORT

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	SOH CHIN WAN		ID No.	S1293364I
Related Vehicle	SHB451B (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	
Driver				
Name	TAN BOON WAH		ID No.	S1607428D
Related Vehicle	SMA3464R (Car)		Contact No.	93366300
Hospital/Clinic	MOUNT ELIZABETH HOSPITAL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	16/08/2022	Date Discharge	16/08/2022	
No. of Days granted Medical Leave	07	Degree of Injury	Slight	

Brief Details.

On 15/08/2022 at about 1815hrs, I was driving my Grab vehicle bearing registration number SMA3464R (Honda Shutter) black in colour at the traffic light junction of Bukit Timah Road turning into junction of Dunearn Road & Swiss Club Road and I stopped at the traffic light junction.

While the traffic light turned green, I drove my vehicle straight toward Swiss Club Road. Suddenly, there was a Smart taxi bearing registration number SHB451B who beat red light on the left traffic junction collided onto my vehicle left passenger side/rear. We then stopped our vehicle, the smart taxi from portion was dented and my left rear was badly damaged due to the impact. During, the incident myself & my passenger only suffer stiff neck and no one was convey to hospital. There is no government property damaged and no traffic Police was called down to scene. We only exchange particular at scene and our vehicle was towed to workshop for insurance claim.

On 16/08/2022 at 0800hrs, I went to Mount Elizabeth Hospital to seek treatment due to neck pain, I was given 7 days outpatient medical certificate from 16/08/2022 to 22/08/2022.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999



T/20220816/2012

3 of 3

Report No. T/20220816/2012

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature of Officer Recording The Report: E / SR-STAFF SGT LIM WEI MING 
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / AEIT / SR STAFF SGT FAHKRUL RAZI BIN SUHAIME Contact No.: 65470000

Signature Of Informant: 
Date/Time: 16/08/2022 11:10
Classification Of Case:

NP168