

(08/11/8) waf
ASS. REC. BY: JPM

REF:

CS3/CT122007926/Ry3


238B
1526

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: FBU 629C
at Workshop m/s UNITED CYCLES LLP
of 25, KAKI BUKIT RD #01-25 @ SYNOY
Insured: SNB 2643E CT1
Policy No. DMPCSNW00179632201
Claims No. SNM22D205706/C02
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 17K
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBU 629C Yr Regn: 2022 / July
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: YAMAHA XSR 155 MANUAL C.C 155
Colour: BLACK A/C: Insured / Std / NI / NA
Sp. Reading: - T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: M43RG4760MK026239
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / R/Rim / STD A/Rim or
Tyre Size: F: 110/70-17
R: 140/70-17
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or TRAILWINNER
Front Rear
R/Bal. 4 mm R/Bal. 4 mm
L/Bal. mm L/Bal. mm
D.O.A. 12/08/22 D.O.L. 19/08/22
Survey held at UNITED CYCLES
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 6K

30/8/22 ESTIMATE RANGE OF REPAIR (No. of days) (1K-2K) / 3 days

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

) S + RS SI

) Photos

) Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	2388
Vehicle No.:	FBU629C
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Aug 2022
Vehicle Make:	YAMAHA
Vehicle Model:	XSR155 MANUAL
Primary Colour:	Black
Manufacturing Year:	2021
Engine No.:	G3J6E0328485
Chassis No.:	MH3RG4760MKD26239
Maximum Power Output:	-
Open Market Value:	\$3,278.00
Original Registration Date:	28 Jul 2022
First Registration Date:	28 Jul 2022
Transfer Count: -	1
Actual ARF Paid:	\$492.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	27 Jul 2032
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$10,910.00
COE Rebate Amount:	\$10,807.00
Total Rebate Amount:	\$10,807.00

The information contained herein is correct as at 30 Aug 2022

OK