COMFORTDELGRO

1	305526579			
:	19.08.22			
	!_			

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

FINALIZATION FORM   To :		Fax: 6546 8156				
То	: :=	LKK	4	Fax:		
Attn	1	GUO QIANG				
Vehic	le Re	g No. : SHC1333Y	Dat	e of Accident	15.08.22	
The s	survey	and estimates of the repairs of	the above-mentioned	vehicle are as follo	ows:-	
1.	The	repair job shall bill to:	NTUC		EM8817E	
2.	The f	finalized amount shall be:				
	(a)	Spare Parts after List discount	t			
	(b)	Labour Charges (include adv	vertisement stickers et	tc,if any)		
		Total for Part-By-Part Repair	Cost			
	(c.)	Lumpsum Repair (if applicable Total for Lumpsum repair cost Final Lumpsum Repair cost	after Less: 20%	33	\$1,650.00 \$1,650.00	
3.	Estim	nated normal period for repairs:	2wo	rking days.		

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and

finalized amount

Date

Signature :	Lim	B	Signature :	
Name :	LIMTS	V	Name :	GUO QIANG

Fax 65468156

: <u>62148398</u>

## For Official Use Only

Tel

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
Rental Rate P/Day		YES		
Loss of Income Paid	23 <del>000</del>	N		
3. Survey Fees		==		
4. LTA Search Fee	\$7.49 /\$2.00	Y		
<ol><li>Medical Fees (on behalf of driver, if applicable)</li></ol>				
6 Overrun				

kemarks	:					