

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC22007938/Gce2		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	10-11-2022 INC4		
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	EM 8817E	Veh. Ir	spected	SHC 1333Y	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1184480-003	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	16/08/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS	C.C		1798	
	Engine No.	HIDDEN	Year o	f Reg.	2017	
	Chassis No.	JTDKB3FU403560567	Colou	•	BLUE	
	Odometer	542495	Steering		IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST	_AKE	6 mm	
	L/H Front Tyre	195/65 R15	WEST	_AKE	6 mm	
	R/H Rear Tyre	195/65 R15	WEST I	_AKE	6 mm	
	L/H Rear Tyre	195/65 R15	WEST	_AKE	6 mm	
4.	. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	15/08/2022	Inspec	tion Date	16/08/2022	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
	59 LOYANG DRIVE SINGAPORE 508969					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					