

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

NOTE (L/sum)

Date: 17.08.2022
Time: 16:12:44
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305526806
REGN NO : SH 9992K
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 25.10.2019
DATE/TIME IN : 17.08.2022 14:15
ACCIDENT DATE : 17.08.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0578-G COVER-FR BUMPER# 1 481.10 20.00 384.88

0002 04-01-0101-0111-G BUMPER COVER CLIP 10 L 22.00 20.00 17.60

SUB-TOTAL : 402.48

JOB NATURE

0000 PB PANEL BEATING

400.00 350

0001 SP SPRAYPAINT CHARGE

300.00 250

SUB-TOTAL : 700.00

TOTAL : 1,102.48

MVA NAME & SIGNATURE
DATE:

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE:

1 Day
Gino Qiang
4/s
17/8/22
upm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal and improper work allowed
- Supplying parts, materials, labour, etc. is subject to approval by the Insurance Company

Acknowledged by: _____
Signature: _____
Date: _____