



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



AUTOMOBILE INSPECTION REPORT

INCOME INSURANCE LTD

Ref: NS/INC22007941/Gqce2

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 21-10-2022

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBJ 3196Y	Veh. Inspected	SHA 1097P
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1193441-001	Excess (\$)	0.00
Assign From		Assign Date	18/08/2022

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40 1.7	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KMHLB41UMHU098209	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	GITI	6 mm
L/H Front Tyre	205/60 R16	GITI	6 mm
R/H Rear Tyre	205/60 R16	GITI	6 mm
L/H Rear Tyre	205/60 R16	GITI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/08/2022	Inspection Date	18/08/2022
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
--	-----------------------