

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrotauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SMH 5577Z**
Made : Audi
Model : TT Coupe 1.8
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bonnet	1	\$ 5,107.00	\$ <i>Ry</i> 5,107.00
2	Front Bonnet Emblem	1	\$ 118.00	\$ <i>ng</i> 118.00
3	Front Bonnet Lock RH	1	\$ 427.00	\$ <i>X</i> 427.00
4	Front Bonnet Lock LH	1	\$ 427.00	\$ <i>X</i> 427.00
5	Front Bumper Side Retainer RH	1	\$ 68.00	\$ <i>dig</i> 68.00
6	Front Bumper Side Retainer LH	1	\$ 68.00	\$ <i>X</i> 68.00
7	Front Bumper Tow Cover	1	\$ 58.00	\$ <i>X</i> 58.00
8	Front Bumper Headlamp Washer Cylinder Cover RH	1	\$ 68.00	\$ <i>X</i> 68.00
9	Front Bumper Headlamp Washer Cylinder Cover LH	1	\$ 68.00	\$ <i>X</i> 68.00
10	Front Bumper Reinforcement	1	\$ 1,154.00	\$ <i>X</i> 1,154.00
11	Front Headlamp Assembly RH	1	\$ 2,589.00	\$ <i>cut</i> 2,589.00
12	Front Headlamp Assembly LH	1	\$ 2,589.00	\$ <i>X</i> 2,589.00
13	Front Lock Carrier (Support Panel)	1	\$ 1,089.00	\$ <i>X</i> 1,089.00
14	Aircon Condenser	1	\$ 605.00	\$ <i>X</i> 605.00
15	Radiator	1	\$ 1,061.00	\$ <i>X</i> 1,061.00
16	Front Fender Inner Cowling RH	1	\$ 197.00	\$ <i>de</i> 197.00
17	Front Door RH	1	\$ 4,192.00	\$ <i>X</i> 4,192.00
18	Front Door Side Mirror Assembly RH	1	\$ 1,279.00	\$ <i>X</i> 1,279.00
19	Rocker Panel Garnish RH	1	\$ 748.00	\$ <i>X</i> 748.00
20	Front Shock Absorber RH	1	\$ 419.00	\$ <i>X</i> 419.00
21	Front Lower Arm RH	1	\$ 934.00	\$ <i>X</i> 934.00
22	Front Knuckle RH	1	\$ 1,070.00	\$ <i>?</i> 1,070.00
23	Front Wheel Hub & Bearing RH	1	\$ 486.00	\$ <i>?</i> 486.00

Parts Sub Total :	\$ 24,821.00
5% Discount	\$ 1,241.05
PARTS TOTAL :	\$ 23,579.95

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Bumper (Aftermarket Bodykit) <i>check price.</i>	1	\$ 5,000.00	\$ <i>ava</i> 5,000.00
2	Front Grille Assembly (Aftermarket Bodykit)	1	\$ 2,400.00	\$ <i>X</i> 2,400.00
3	Front Fender RH (Aftermarket Bodykit) <i>check price</i>	1	\$ 3,000.00	\$ <i>de</i> 3,000.00
4	Front Number Plate	1	\$ 50.00	\$ <i>X</i> 50.00

5	Front Bumper Clips - Set	1	\$	50.00	\$ 30.00 50.00	50.00
6	Front Grille Assembly Clips - Set	1	\$	50.00	\$ X	50.00
7	Front Fender Inner Cowling RH Clips - Set	1	\$	50.00	\$ 30.00 50.00	50.00
8	Front Door Inner Trimboard RH Clips - Set	1	\$	50.00	\$ X	50.00
9	Rocker Panel Garnish RH Clips - Set	1	\$	50.00	\$ X	50.00
10	Front Bonnet Sealant	1	\$	150.00	\$ X	150.00
11	Front Door RH Sealant	1	\$	150.00	\$ X	150.00
12	Front Wheel Rim RH <i>check price</i>	1	\$	3,000.00	\$ 2,000.00 3,000.00	3,000.00
13	Front Tyre RH	1	\$	650.00	\$ X	650.00
14	Radiator Coolant	1	\$	150.00	\$ X	150.00
SPECIAL NETT TOTAL :					\$	14,800.00

Nos.	LABOUR				TOTAL S\$
1	To Panel Beat, Remove & Refix Parts			\$ 500	1,600.00
2	To Spray Paint Affected Areas			\$ 660	1,400.00
3	Wiring & Bulb Check			\$ 30	100.00
4	To Transfer Front Door RH Mechanism			\$ X	150.00
5	To Remove & Refix Aircon Condenser & Top Up Gas			\$ X	150.00
6	To Remove & Refix Radiator & Pressure Test			\$ X	150.00
7	To Remove & Refix Front Undercarriage		<i>photo -</i>	\$ 150!	500.00
8	To Conduct Four Wheel Alignment			\$ 80	150.00
9	To apply anti rust on affected parts			\$ 30	150.00
10	To Conduct Water Leak Test			\$ X	100.00
11	To Send for Diagnostic and Reset Control Unit. Programming & Calibration			\$ X	480.00
LABOUR TOTAL :					\$ 4,930.00

Tafim 97495789
 - WP 19/8/22 @ 1145
 1/5 Resury after repair
 tafim@lkhants.com
 4 days
 To check consistency of accident
 To check part price.

PARTS TOTAL : \$ 23,579.95
 SPECIAL NETT TOTAL : \$ 14,800.00
 LABOUR TOTAL : \$ 4,930.00
GRAND TOTAL : \$ 43,309.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 667G

Vehicle Details

Vehicle No.: SMH5577Z
Vehicle to be Exported: Yes
Intended Deregistration Date: 18 Aug 2022
Vehicle Make: AUDI
Vehicle Model: TT COUPE 1.8 TFSI S-TRONIC
Primary Colour: White
Manufacturing Year: 2013
Engine No.: CDA384129
Chassis No.: TRUZZZ8J1D1011531
Maximum Power Output: 118.0 kW (158 bhp)
Open Market Value: \$37,481.00
Original Registration Date: 15 Mar 2013
First Registration Date: 15 Mar 2013
Transfer Count: 3
Actual ARF Paid: \$32,481.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 14 Mar 2023
PARF Rebate Amount: \$16,240.00

Intended COE Rebate Details

COE Expiry Date: 14 Mar 2023
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$92,667.00
COE Rebate Amount: \$5,257.00
Total Rebate Amount: \$21,497.00

The information contained herein is correct as at 17 Aug 2022

OK

VEHICLE NO:	SMH5577Z	MAKE & MODEL:	Audi TT	<input checked="" type="radio"/> AUTO / <input type="radio"/> MANUAL
DATE OF ACCIDENT	17 / 08 / 2022	*C.C.	1800	
TIME OF ACCIDENT	0930	<input checked="" type="radio"/> AM / <input type="radio"/> PM		
LOCATION OF ACCIDENT	Service Road of Blk 77 Bedok Reservoir View Road towards			
EXACT PURPOSE USED AT TIME OF ACCIDENT	EMPLOYMENT / PRIVATE USE / PRIVATE HIRE	Block 770		
NAME OF OWNER	Yap Rui San			
EMAIL:	esthee84@gmail.com	Office:		MOBILE: 9271 0935
NRIC	S8416667G			
CLAIM TYPE	OD / <input checked="" type="radio"/> THIRD PARTY / <input type="radio"/> REPORTING ONLY			
FLEET POLICY:	YES / <input checked="" type="radio"/> NO			
INSURANCE CO.	Sompo			
TYPE OF COVERAGE	Comprehensive / <input checked="" type="radio"/> Third Party / <input type="radio"/> Third Party Fire & Theft			
POLICY NO.				
NAME OF DRIVER	AS ABOVE / IF NO.	Yong Xiang Peng		
NRIC	S8330827C			
DATE OF BIRTH	25 / 09 / 1983			
ANY PASSENGER	<input checked="" type="radio"/> YES / <input type="radio"/> NO: 1			
NAME OF PASSENGER	Yap Rui San			
GENDER OF PASSENGER	MALE / <input checked="" type="radio"/> FEMALE			
OCCUPATION	Outdoor / <input checked="" type="radio"/> Indoor			
DATE OF DRIVING PASS	21 / 02 / 2007			
GENDER	<input checked="" type="radio"/> Male / <input type="radio"/> Female			
CONTACT NO.	Mobile: 9696 0827	Office:		
EMAIL:	Yong X.P. 83@gmail.com.			
ADDRESS	86 Jalan Setia Singapore 368504.			
DOES DRIVER OWN OTHER VEHICLES?	<input checked="" type="radio"/> NO / If yes, Reg No.	INSURER:		
RELATIONSHIP	Employee / If No: Spouse.			
WEATHER CONDITION	<input checked="" type="radio"/> Clear / <input type="radio"/> Raining / <input type="radio"/> Other:			
ROAD SURFACE	<input checked="" type="radio"/> Dry / <input type="radio"/> Wet / <input type="radio"/> Other:			
ANY INJURIES	<input checked="" type="radio"/> No / If yes: Who?			
CONVEYED BY AMBULANCE	<input checked="" type="radio"/> No / If yes: Who?			
POLICE REPORT	<input checked="" type="radio"/> No / If yes: Where?			
NOTICE OF INTENDED PROSECUTION GIVEN?	<input checked="" type="radio"/> NO / IF YES: WHO?			
VEHICLE B NO.	C13 83571	Any Passenger:	Not Sure.	
NAME				
CONTACT NO.				
VEHICLE C NO.		Any Passenger:		
VEHICLE D NO.		Any Passenger:		
VEHICLE E NO.		Any Passenger:		
VEHICLE F NO.		Any Passenger:		
ANY WITNESS				
WITNESS CONTACT NO.				
WAS THERE ANY VIDEO CAPTURE?		YES / <input checked="" type="radio"/> NO		
WAS THERE ANY AUDIO RECORDED?		YES / <input checked="" type="radio"/> NO		
SCENE ACCIDENT PHOTOS TAKEN?		YES / <input checked="" type="radio"/> NO		
Who is Reporting	<input checked="" type="radio"/> Driver / <input type="radio"/> Owner / <input type="radio"/> Both			
Original Language Used	<input checked="" type="radio"/> English / <input type="radio"/> Mandarin / <input type="radio"/> Others:			
Have you been approach by unknown person soliciting (s) / offering accident claims assistance?		YES / <input checked="" type="radio"/> NO		

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan



Describe Circumstance of the Accident

I was travelling @ the service road of Block 767
Bedok Reservoir View Road towards Block 770. Out of sudden,
vehicle (B) who was coming from the opposite lane cut into
my lane and collided onto my vehicle front right position.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel