

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/1988 GS1 Reg. No. 19-900/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAL	_ INSURANCE (S) PL	F	Ref:	CS/AGI22007960/Eny3e2	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	Γ	Date:	22/03/2023	
			C	Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMN 9942U	Veh. Inspected		PC 4921K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10017038/JT	Excess (\$)		0.00	
	Assign From	SALIZAWATI HAIZAR	Assign Date		19/08/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	NISSAN NV350	c.c		2488	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JN1TC2E26Z0001246	Colour		BROWN	
	Odometer	116505 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	FAIR				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195 R15	DUNLOP		4 mm	
	L/H Front Tyre	195 R15	DUNLOP		4 mm	
	R/H Rear Tyre	195 R15	DUNLOP		4 mm	
	L/H Rear Tyre	195 R15	DUNLOP		4 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	16/08/2022	Inspection Date		26/09/2022	
	Survey held at	MOVA AUTOMOTIVE PTE LTD				
		BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 . SINGAPORE 159722				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: