

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 19960 <i>i</i>	198R GST Reg. No. 19-	-9607198	-K	
		Affiliated to Federation Internatio	nale Des Experts En Au	tomobile)	
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef: C	S/AGI22007975/Avy3e2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate: 07	7/09/2022	
			Co	ode: A	GI	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SMN 9632P	Veh. Inspected	SI	MK 8018K	
	Policy No.		Coverage (\$)	0.	00	
	Claim No.	C10017035/JL	Excess (\$)	0.	00	
	Assign From	SALIZAWATI HAIZAR	Assign Date	19	9/08/2022	
2. Vehicle Particulars & Condition						
	Make & Model	B.M.W. 520I	c.c	19	998	
	Engine No.	HIDDEN	Year of Reg.	20)18	
	Chassis No.	WBAJA12060WE60412	Colour	W	/HITE	
	Odometer	51070 KM	Steering	IN.	ORDER	
	Brakes	IN ORDER	Modification	SI	PORTS RIM	
	General	GOOD				
3.		Conditi	ions of Tyres			
		Size	Make	В	alance	
	R/H Front Tyre	275/35 R19	MICHELIN	6	mm	
	L/H Front Tyre	275/35 R19	MICHELIN	6	mm	
	R/H Rear Tyre	275/35 R19	MICHELIN	6	mm	
	L/H Rear Tyre	275/35 R19	MICHELIN	6	mm	
4.	Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	17/08/2022	Inspection Date	22	2/08/2022	
	Survey held at	YSK AUTO WORKSHOP	•			
		1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883				
5a.	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	D)IN ACCORDANC	Estimate Days of Repair				
			,			

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: