

(08/11/08) waf
ASS. IEC. BY: Rasm

REF:

CC3/AIS 2200 7982/Rp93

S
443A

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFZ 8388X

at Workshop m/s VOLKSWAGEN

of 247, ALEXANDRA RD

Insured: AIS

Policy No. _____

Claim No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 83K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 49K

Veh No: SFZ 8388X Yr Regn: 2017 / OCT

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: VOLKSWAGEN GOLF 1.4TSI 9/Reg 1395

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 68084 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZZZAUZHW127182

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 228/402R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 18/08/22

Survey held at

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 22/08/22

Des. of Damages: Frt Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

) S + RS, SI

) Photos

) Others

Report Format : _____

Lump Sum / I.B.I. (\$ _____)

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company
ALLIANZ GLOBAL
CORPORATE & SPECIALTY SE
SINGAPORE
12 MARINA VIEW
#14-01 ASIA SQUARE TOWER 2
Singapore 018961

Customer Details:
Mr
ARISTO
MANGKULIONO
620 BUKIT BATOK CENTRAL
#30-524
Singapore 650620

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

18-08-2022
5211042669
T11FC0131K
30001
2022023997/ 1
18-08-2022
YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SFZ8388X	5G13HZ	24-10-2017	VWVZZZAUZH127782	Golf 1.4 CLBM 92 TSI D7F	60,303

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
5G6807417APGRU	Cover For Bumper Primed	1	pcs.	1,382.73	10.00%	1,244.46	1,331.57
5G6807568D 9B9	Rear Diffusor Satin Black	1	pcs.	349.21	10.00%	314.29	336.29
5G0919491	Sensor Bracket	2	pcs.	16.08	10.00%	28.94	30.97
5G0919491A	Sensor Bracket	1	pcs.	16.08	10.00%	14.47	15.48
5G0919492A	Sensor Bracket	1	pcs.	16.08	10.00%	14.47	15.48
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	85.94	10.00%	77.35	82.76
D 822150A1	Bonding Agent For Plastic	1	pcs.	68.85	10.00%	61.97	66.31
5G0807305D	Bumper REINFORCEMENT	1	pcs.	732.39	10.00%	659.15	705.29
5G6807863C	Attachment Strip BUMPER CTR BRACKET	1	pcs.	70.74	10.00%	63.67	68.13
5G6807393A	Guide Piece LHR BUMPER BRACKET (UPPER)	1	pcs.	41.89	10.00%	37.70	40.34
5G6807394A	Guide Piece RHR BUMPER BRACKET (UPPER)	1	pcs.	41.89	10.00%	37.70	40.34
5G6807393	Guide Piece LHR BUMPER BRACKET (SIDE)	1	pcs.	41.89	10.00%	37.70	40.34
5G6807394	Guide Piece RHR BUMPER BRACKET (SIDE)	1	pcs.	41.89	10.00%	37.70	40.34
WHT005263	Rivet	4	pcs.	1.32	10.00%	4.75	5.08
	LABOUR	13	pcs.	720.00	#1	2,180.00	2,311.20
	SPRAY PAINT	13	pcs.	680.00	#1	2,040.00	2,182.80
	NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60
	MSIG MOTORMAX PLUS VS ALLIANZ 3RD PARTY VEHICLE PC3446Y D.O.A: 18-08-2022 SURVEY BY:						

Quotation valid till 25-08-2022

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#1	760.00	6,914.32	292.70	7%	537.20	292.70	7,674.32	8,211.52
Total	760.00	6,914.32	292.70		537.20	292.70	7,674.32	8,211.52

OLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page.

2/2

Company
ALLIANZ GLOBAL
CORPORATE & SPECIALTY SE
SINGAPORE
12 MARINA VIEW
#14-01 ASIA SQUARE TOWER 2
Singapore 018961

Customer Details:
Mr
ARISTO
MANGKULIONO
620 BUKIT BATOK CENTRAL
#30-524
Singapore 650620

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

18-08-2022
5211042669
T11FC0131K
30001
2022023997/ 1
18-08-2022
YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SFZ8388X	5G13HZ	24-10-2017	WVWZZZAUZHW127782	Golf 1.4 CLBM 92 TSI D7F	60,303

Customer



—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
3 days
P/P
22/08/22 @ 1000
Resurvey before paint

MSIG motor max
plus vs Asian
out
and later

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 18/08/2022 12:37 (SGT)
Reported by Both
Date of Accident 18/08/2022 09:45 (SGT)
Exact Location of Accident Singapore
Additional Location Information TRAFFIC LIGHT JUNCTION @ BT BATOK EAST AVE 3
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SFZ8388X

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner ARISTO MANGKULIONO
NRIC No SXXXX443A
Email Address arisslee_singnet@yahoo.com
Mobile Phone No (Phone) +65-97317487
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Volkswagen
Model Golf
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1400

INSURANCE COMPANY

Name of Insurance Company MSIG Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number A 300360374 QMY

DRIVER

Name of Driver ARISTO MANGKULIONO
NRIC No SXXXX443A
Date Of Birth 26/09/1975
Occupation Indoor

Date Of Driving Pass	11/01/2003
Driving experience	19 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97317487
Alt. Phone Number	-
Email Address	arisslee_singnet@yahoo.com
Address	620 BUKIT BATOK CENTRAL
Address complement	#30-524
Postcode	650620
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN & VIDEO

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC3446Y
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	LEOW KIM SENG
Contact Number	(Phone) +65-81802581

Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Actual Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



Describe Circumstance of the Accident

Incident location: traffic light junction
① BT BAYOK EAST AVE 3.

Time: 9.45 am. 18. AUG. 2022.

Description: THE VEHICLE ROLLED SLOWLY FROM
THE BACK WHILE MY CAR ②
STATIONARY ① THE TRAFFIC LIGHT
ROLLED & COLLIDED FROM THE BACK.

3RD PARTY DETAILS:

NAME: LEOW KIM SENG
PH: 8180 2581
VEH. NO: PC 3445 Y


Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature (Date & Time)

Actual Driver's Signature (if driver is not the policyholder)
(Date & Time)



Witnessed by Reporting Centre Personnel
(Name as in NRIC ID card)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 443A

Vehicle Details

Vehicle No.: SFZ8388X

Vehicle to be Exported: No

Intended Deregistration Date: 23 Aug 2022

Vehicle Make: VOLKSWAGEN

Vehicle Model: GOLF 1.4 TSI AT 5G13HZ HID SR

Primary Colour: Silver

Manufacturing Year: 2016

Engine No.: CZC165388

Chassis No.: WVVZZZAUZHW127782

Maximum Power Output: 92.0 kW (123 bhp)

Open Market Value: \$23,833.00

Original Registration Date: 24 Oct 2017

First Registration Date: 24 Oct 2017

Transfer Count: 0

Actual ARF Paid: \$15,367.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 23 Oct 2027

PARF Rebate Amount: \$11,525.00

Intended COE Rebate Details

COE Expiry Date: 23 Oct 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$41,617.00

COE Rebate Amount: \$21,502.00

Total Rebate Amount: \$33,027.00

The information contained herein is correct as at 23 Aug 2022

OK

Volkswagen Golf 1.4A TSI Sunroof

Overview

Financial

Accessories

Similar






Research

Photos

Map



SERVING DRIVERS
FIRST!

Price	\$80,000		
Depreciation 	\$14,770 /yr View models with similar depre	Reg Date	18-Jul-2017 (4yrs 10mths 24days COE left)
Mileage	42,000 km (8.2k /yr)	Manufactured 	2016
Road Tax 	\$624 /yr	Transmission	Auto
Dereg Value	\$31,597 as of today (change)	OMV 	\$23,692
COE	\$42,801	ARF	\$15,169
Engine Cap	1,395 cc	Power	92.0 kW (123 bhp)
Curb Weight 	1,249 kg	No. of Owners	1