

ASS. REC. BY:

REF:

162 22007985/kv

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SLN 1129R

Policy No.

Claims No. C10016973/JM

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

09 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GRG 4529E

Yr Regn:

08, 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Dyna

c.c.

2982

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

132582

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFAT 35YXOK 208488

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195R 13 x P

R:

155R 12 x P (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

3

mm

L/Bal.

3

mm

D.O.A.

15/8/22

Rear

R/Bal.

55

mm

L/Bal.

55

mm

D.O.I.

22/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/8/22

Kenneth informed LS \$2250 (Red 4144, 64%)

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

1)

Date/Time, File Return to?

31/8/22-typist

Report Format: TP

ump Sum / I.B.t. (\$ 2250)