Our Job Ref No : 305518546					COMFORIDELGRO		
	Date : 10.06.2022				ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969		
		TION FORM				Singapore 508966	
То	To : LKK				Fax :		
Att	n ;		THEVAN				
Vel	Vehicle Reg No. : SHC8999E					03.06.2022	
The	survey	and estimates	s of the repairs of the above-	mentioned veh	icle are as folk	ows:-	
Z		repair job shal		NTU		SLZ3813Y	
2.	The finalized amount shall be:						
	(a)	Spare Parts	after List discount				
	(b)	Labour Char	ges				
		Total for Pa	rt-By-Part Repair Cost				
	(c.)	Total for Lum	epair (If applicable) apsum repair cost after Less:	ı			
		Final Lumps	um Repair cost	-	Marie de	\$700.00	
5.	Signature : CHIANG				We confirm the estimates and finalized amount  Signature:		
	Tel	: <u>621483</u>		Da	ate :		
	Fax	: 6546818	56	_			
For Of	ficial U	se Only					
	Ite	m	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks	
1. Ren	tal Rate	P/Day		YES			
		me Paid	-	N			
3. Surv			-	-7			
	cal Fee ver, if a	Fee s (on behalf pplicable)	\$7.49/\$2.00	YES			
Remarks							