

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCC	INCOME INSURANCE LTD			NS/INC22008000/Vqcm4		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	07-09-2022 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SMQ 5119R	Veh. Ir	nspected	SHA 8047M	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1176314-004	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	10/06/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS	c.c		1798	
	Engine No.	HIDDEN	Year o	f Reg.	2017	
	Chassis No.	JTDKB3FU403556986	Colou	r	YELLOW	
	Odometer	761638	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/55 R15	WEST		5 mm	
	L/H Front Tyre	195/55 R15	WEST		5 mm	
	R/H Rear Tyre	195/55 R15	WEST		5 mm	
	L/H Rear Tyre	195/55 R15	WEST	LAKE	5 mm	
4.	, ,					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	. General Information					
	Accident Date	10/06/2022		tion Date	10/06/2022	
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	b. Estimate Days of Repair					
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				