

ASS. REC. BY:

REF:

C12/22008037/KC

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STV 294 J

Yr Regn:

07, 13

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes

A1 2200

c.c

1991

Colour:

M. Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

136329

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 212 034 2A 815315

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/458 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

8 A 122

D.O.I.

24/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/8/21 Rpt @ 1750h. Canhu

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

\$ + RS. \$

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

JIN HUAT & CO

176 Sin Ming Drive, #05-01
Sin Ming Autocare
Singapore 575721

Tel : 6453 2151; Fax : 6456 3060
email: jinhuat1951@gmail.com
Co. Reg. No: 020403/00C

Quotation

To: Wong Peng Hoon/Michelle Toh Li Sze
29 Nim Terrace
Singapore 804374

Date : 13 July 2022

Contact: 9695 3339

Pages : 1 of 1

Vehicle No: SJV 294 J
Model: Mercedes Benz E200
Insurer: AIG Insurance (Singapore) Pte Ltd

NOT Notified
11 hr @ 1750/hr
Running After Paint
2 days

We are pleased to quote you as follows:

Items	Description	Qty	Unit	Unit Price	Total Price
Accident Details:					
	Date of Accident : 08 July 2022				
	T/P claim against Vehicle No. SNF 9637 G				
	insured with China Taiping Insurance Pte Ltd				
Parts:					
1)	Rear bumper <i>R</i>	1	pc	\$ 1,405.00	\$ 1,405.00 ✓
2)	Rear bumper lower spoiler/lip <i>nd</i>	1	pc	\$ 252.00	\$ 252.00 ✓
3)	Rear bumper reinforcement <i>R</i>	1	pc	\$ 828.00	\$ 828.00 X
4)	LH T/lamp <i>SL</i>	1	pc	\$ 612.00	\$ 612.00 X
5)	LH bumper sensor <i>nd</i>	1	pc	\$ 210.00	\$ 210.00 ✓
Labour: <i>108</i>					
6)	Repair T/lamp panel, inner support and replace parts	1	lot	\$ 850.00	\$ 850.00 <i>250</i>
7)	Spray painting	1	lot	\$ 750.00	\$ 750.00 <i>280</i>
TOTAL PRICE				\$	4,907.00

JIN HUAT & CO

Alice Tan

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	09/07/2022 11:56 (SGT)
Reported by	Driver
Date of Accident	08/07/2022 17:17 (SGT)
Exact Location of Accident	Nim Terrace, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV294J
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	Wong Peng Hoong
NRIC No	S6906715H
Email Address	michtoh@gmail.com
Mobile Phone No	(Phone) +65-96207733
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	E200
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1991

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	2100474710-06

DRIVER

Name of Driver	Michelle Toh Li Sze (Tu Lishi)
NRIC No	S7912937B
Date Of Birth	29/04/1979
Occupation	Indoor