

ASS. REC. BY:

REF:

C12 / 22 00 8037/KC

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

24/8/22 Rpt @ 1750h. Carbur (Red. 3157; 64%)

Veh No:

STV 294J

Yr Regn:

07, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes

A1

c.c

1991

Colour:

M. Brown

A/C: Insured / Std / NI / NA

Sp. Reading

136329

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD 212 034 2A 815315

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

245/458 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

2

mm

Rear

R/Bal.

2

mm

L/Bal.

2

mm

L/Bal.

2

mm

D.O.A.

8/7/22

D.O.I.

24/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



Prell. Report



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fines

Others

TOTAL

Report Format:

TP

Lump Sum / I.B.I. (\$

1750

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	09/07/2022 11:56 (SGT)
Reported by	Driver
Date of Accident	08/07/2022 17:17 (SGT)
Exact Location of Accident	Nim Terrace, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV294J
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	Wong Peng Hoong
NRIC No	S6906715H
Email Address	michtoh@gmail.com
Mobile Phone No	(Phone) +65-96207733
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	E200
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1991

### INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	2100474710-06

### DRIVER

Name of Driver	Michelle Toh Li Sze (Tu Lishi)
NRIC No	S7912937B
Date Of Birth	29/04/1979
Occupation	Indoor

Date Of Driving Pass	12/09/1998
Driving experience	23 YEARS AND 10 MONTHS
Gender	Female
Mobile Number	(Phone) +65-96953339
Alt. Phone Number	-
Email Address	michtoh@gmail.com
Address	29 Nim Terrace
Address complement	-
Postcode	804374
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

Please refer to the sketch plan.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SNF9634G
Vehicle Manufacturer	Toyota
Vehicle Model	Noah
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private hire
Name of Driver	-
Contact Number	-

China Taiping Insurance  
claimsdept@sg.entaiping.com

## JIN HUAT & CO

176 Sin Ming Drive, #05-01  
Sin Ming Autocare  
Singapore 575721  
Tel : 6453 2151; Fax : 6456 3060  
email: jinhuat1951@gmail.com  
Co. Reg. No: 020403/00C

## Quotation

To: Wong Peng Hoon/Michelle Toh Li Size  
29 Nim Terrace  
Singapore 804374

Date : 13 July 2022

Contact: 9695 3339

Pages : 1 of 1

Vehicle No: SJV 294 J  
Model: Mercedes Benz E200  
Insurer: AIG Insurance (Singapore) Pte Ltd

NOT NOTIFIED  
11 hr @ 1750/hr  
Recovery After Paint  
2 days

We are pleased to quote you as follows:

Items	Description	Qty	Unit	Unit Price	Total Price
<b>Accident Details:</b>					
	Date of Accident : 08 July 2022				
	T/P claim against Vehicle No. SNF 9637 G				
	insured with China Taiping Insurance Pte Ltd				
<b>Parts:</b>					
1)	Rear bumper <i>R1</i>	1	pc	\$ 1,405.00	\$ 1,405.00 ✓
2)	Rear bumper lower spoiler/lip <i>nd</i>	1	pc	\$ 252.00	\$ 252.00 ✓
3)	Rear bumper reinforcement <i>R</i>	1	pc	\$ 828.00	\$ 828.00 X
4)	LH T/lamp <i>SL</i>	1	pc	\$ 612.00	\$ 612.00 X
5)	LH bumper sensor <i>nd</i>	1	pc	\$ 210.00	\$ 210.00 ✓
<b>Labour:</b>					
6)	Repair T/lamp panel, inner support and replace parts <i>108</i>	1	lot	\$ 850.00	\$ 850.00 2501
7)	Spray painting	1	lot	\$ 750.00	\$ 750.00 2801
<b>TOTAL PRICE</b>					<b>\$ 4,907.00</b>

JIN HUAT & CO

Alice Tan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: