

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190R GS1 Reg. No. 19-900/190-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERAL	_ INSURANCE (S) PL	Re	ef: CS/AGI22008043/Kny3e2	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate: 10/10/2022	
			Co	ode: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMQ 4295X	Veh. Inspected	SLL 5127E	
	Policy No.	P10473032R01	Coverage (\$)	0.00	
	Claim No.	C10017031/JY	Excess (\$)	0.00	
	Assign From	SALIZAWATI HAIZAR	Assign Date	22/08/2022	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA VEZEL (A)	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	RU11117852	Colour	METALLIC BLUE	
	Odometer	63490 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/55 R17	YOKOHAMA	7 mm	
	L/H Front Tyre	215/55 R17	YOKOHAMA	7 mm	
	R/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
	L/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	18/08/2022	Inspection Date	23/08/2022	
	Survey held at 160 SIN MING DRIVE #01-13 SIN MING AUTOCITY				
	Repairer	epairer LIM TAN MOTOR PTE LTD			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

12 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: