

CONVERGENCE AUTOMOTIVE
 39 Woodlands Close, Mega @ Woodlands
 #01-24 Singapore 737856
 Tel: (65) 6993 2080 / (65) 9888 8119
 ☒ operations@convergenceauto.com.sg

*not Authorized
 new
 survey
 19/8/22
 2/543100
 6 days*



**CONVERGENCE
 AUTOMOTIVE**

ESTIMATE

DATE: 15-Aug-22
DOA: 12-Aug-22
VEHICLE NO: SLV 9610 Y
MAKE & MODEL: Toyota Wish

DESCRIPTION	QUANTITY	AMOUNT	TOTAL
-------------	----------	--------	-------

LIST ITEMS

Rear bumper	1	\$1,016.40	DIS \$1,016.40
Rear bumper side retainer <i>o/s</i>	1	\$98.60	3ent \$98.60
Rear bumper damper	1	\$87.10	11 \$87.10 X
Rear bumper reflector	1	\$151.50	11 \$151.50 X
Rear reinforcement	1	\$550.80	NS \$550.80 X
Rear end panel	1	\$519.80	11 \$519.80 X
Rear end panel top garnish	1	\$369.00	11 \$369.00 X
Taillamp (RH)	1	\$592.00	SCR \$592.00
Taillamp lower bracket (RH)	1	\$93.80	11 \$93.80 X
Rear fender (RH)	1	1121.35	Body \$1121.35
Rear fender <i>glass RH</i>	1	408.10	RM 408.10
Rear door (RH) repair	1	\$0.00	R \$0.00 X
Total			5008.45
Less 25%			3756.33

SPECIAL NETT ITEMS

Sundries	1	\$60.00	11 \$60.00 X
Rear bumper clips (set)	1	\$60.00	RM \$60.00 50
Rear end panel top garnish clips (set)	1	\$30.00	11 \$30.00 X
Rear <i>fender glass sealant RH</i>	1	\$100.00	RM \$100.00 40
Taillamp clips (set)	1	\$60.00	11 \$60.00 X
Taillamp seal	1	\$100.00	11 \$100.00 X
Rear alloy rim (RH)	1	\$800.00	11 \$800.00 X
Rear tire (RH)	1	\$300.00	11 \$300.00 X
Total			\$1,510.00

Parts Total

LABOUR CHARGES

Check wiring system after disconnect and connect	\$100.00	20
To apply undercoating & rust roofing	\$200.00	40
Panel Beating	\$1,500.00	800
Spray Painting	\$1,200.00	850
Labour Total	\$3,000.00	

Total Parts and Labour Cost of Repair

LKR Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*2-2780.36
 250
 2088.27
 90
 1710
 3888.27
 2108*