

Immediate Advice

To: AXA Insurance Pte Ltd 16/9/2022

Survey Details:

Date of loss	20-Aug-22	
Date of appointment	23-Aug-22	
Date of survey	29-Aug-22	
Location of survey	AH LUCK MOTOR & TRADING	

Vehicle Details:

Claim Type:	Third Part	ty Claim	
Vehicle number	SMZ 6177	SMZ 6177T	
Make and Model	HONDA S	HONDA SHUTTLE 1.5G CVT SENSIN	
Date of registration	6/5/2021		
Excess	-		
Market Value	\$	102,000.00	
Parf Rebate	\$	46,851.00	
Nett Loss	\$	55,149.00	

Repair details:

Initial Estimate	\$ -	

Proposed/Revised repair cost:

Parts	
Check items (estimate)	
Labour	
Total	\$ -
Lump Sum(if applicable)	

Number of days for repair	<u>5</u>



Remarks:

The estimate repair cost of the damaged vehicle is in the
region of \$3,000.00 - \$4,000.00.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	