

**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

*SMH626Z*

Yr Regn:

*10/01/19*Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

*(A)*

Make:

*KIA cerato 1.6 SX c.c 1591*

Colour

*Red*

A/C: Insured / Std / NI / NA

Sp. Reading

*36086*

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

*KN AF 3416MK\*5023986*Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

*225/55-R16*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

*20/08/22*

D.O.I.

*24/08/22*

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*5/9/22 P/P & 4554.00 informed Ren (Red, 4539, 5070)*

Date/Time, File Pass to?

☐

: Preli. Report

1) *7/9/22*☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

*4*

Resurvey No. of Trip:

*2*

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

)    S + RS,    SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) *4554*

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	521Z
<b>Vehicle Details</b>	
Vehicle No.:	SMH626Z
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Aug 2022
Vehicle Make:	KIA
Vehicle Model:	CERATO 1.6(A) EX
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	G4FGJH713013
Chassis No.:	KNAF3416MK5023986
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$13,854.00
Original Registration Date:	10 Jan 2019
First Registration Date:	10 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$13,854.00 6927
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jan 2029
PARF Rebate Amount:	\$10,390.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	09 Jan 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,556.00
COE Rebate Amount:	\$16,295.00
<b>Total Rebate Amount:</b>	<b>\$26,685.00</b>

The information contained herein is correct as at 24 Aug 2022

OK



Low Mileage Selection! The Stylish Kia Cerato Wasn't Always As Good-Looking As Is Today, And All The Convenience Features For Your Daily Drive, This Unit Is Presented In Elegant Pearl White With Black Leather Interior, Vehicle Is Fully Maintained By Agent Since Day 1,...

Car World Automobile Pte Ltd

Posted: 21-Aug-2022

PREMIUM AD



**Kia Cerato 1.6A LX**

\$78,800

\$11,430 /yr

18-Jan-2019

1,591 cc

46,986 km

Sedan

Available

100% loan available! Fully serviced & maintained by agent C&C with free servicing in pristine condition yet comes with a 5 years comprehensive warranty & 10 years on engine for a peace of mind! Guaranteed accident-free unit with low mileage done! We provides v...

Creative Auto

Posted: 20-Aug-2022



**Kia Cerato 1.6A LX**

\$86,800

\$11,130 /yr

29-Nov-2019

1,591 cc

29,200 km

Sedan

Available

Low Mileage Selection! The Stylish Kia Cerato Wasn't Always As Good-Looking As Is Today, And All The Convenience Features! For Your Daily Drive, Vehicle Is Fully Maintained And Service With Full Service Records History Available In Agent (C&C Service Centre!) Since Day...

Car World Automobile Pte Ltd

Posted: 20-Aug-2022

PREMIUM AD



**Kia Cerato 1.6A LX**

\$73,888

\$10,670 /yr

15-Jan-2019

1,591 cc

115,000 km

Sedan

Available

1 Owner Only In Elegant Pearl White. Full Maintained At Agent (C&C) W 5/10 Years Warranty. Fuel Efficient, Spacious & Durable Model In The Market. Very Well Maintained Interior And Exterior. Flexible Finance Package Is Available. Trade In Is Welcomed. Call Our Friendly S...

Posted: 20-Aug-2022

PREMIUM AD

ADVERTISING



Replay



**Kia Cerato 1.6A GT Line Sunroof**

\$98,800

\$12,520 /yr

09-Oct-2019

1,591 cc

37,000 km

Sedan

Available

Highest Specs GT Line! 1 Owner, Very Low Mileage, Fully Agent Maintained With 5 Years C&C Warranty, 10 Years Engine Warranty, Road Tax Till Oct, Spacious Cabin/Boot, Excellent Fuel Efficiency, Don't Miss! Genuine And Transparent Dealing Backed By Positive Reviews, Bu...

Posted: 19-Aug-2022



**Kia Cerato 1.6A LX**

\$75,800

\$10,960 /yr

17-Jan-2019

1,591 cc

50,000 km

Sedan

Available

1 owner, original paint, no repairs needed, very neat and clean interior, car in 100% stock condition, immediate transfer of ownership upon collection. Bank loan/flexible in house loan available, view to appreciate, don't miss this great deal, call us now.

Posted: 19-Aug-2022



**Kia Cerato 1.6A EX**

\$84,800

\$11,900 /yr

12-Mar-2019

1,591 cc

61,200 km

Sedan

Available

Signature Grey Paintwork Kept Till Date! Fully Maintained By C&C Since First Register In 2019! Under C&C Warranty Till March 2024! Hurry Up! Give Us A Call To Secure This Unit Before It's Gone!

Ka-Hup Vehicles Trading

Posted: 19-Aug-2022

PREMIUM AD



**Kia Cerato 1.6A LX**

\$78,800

\$10,700 /yr

13-Jun-2019

1,591 cc

79,000 km

Sedan

Available

One Owner Unit With Full Service History with C&C, Still Under Agent Warranty. High trade in price, 100% loan available! Attractive low interest rates to cater all your financial needs! Quick delivery with ready stocks. Book a test drive to believe it! Kindly reach out to our fri...

Pacific Cars SG Pte Ltd

Posted: 18-Aug-2022



**Kia Cerato 1.6A SX Sunroof**

\$91,800

\$12,370 /yr

24-Apr-2019

1,591 cc

43,000 km

Sedan

Available

Superb Condition. SX Specs With Electric Seats And Sunroof. Well Taken Care Of. C&C Unit. 10 Years Engine Warranty. 2.48% Loan Interest. Full Loan Available. Trade In Welcome. Contact us Now To View!

Posted: 17-Aug-2022

Compare

**Kia Cerato 1.6A EX**

\$83,000

\$11,490 /yr

08-Apr-2019

1,591 cc

98,000 km

Sedan

Available

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	22/08/2022 11:11 (SGT)
Reported by	Driver
Date of Accident	20/08/2022 16:45 (SGT)
Exact Location of Accident	Yio Chu Kang Rd, Singapore
Additional Location Information	YIO CHU KANG ROAD BETWEEN BUS STOP 67019 & TAMARIND ROAD
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH626Z
-----------------------------	---------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN TONG LING
NRIC No	SXXXX521Z
Email Address	TONGLING.TAN@GMAIL.COM
Mobile Phone No	(Phone) +65-98572018
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1591

#### INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	1900002912-02

#### DRIVER

Name of Driver	LOW SOON HENG (LIU SHUNXING)
----------------	------------------------------

Occupation	Indoor
Date Of Driving Pass	27/04/2018
Driving experience	4 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-90614632
Alt. Phone Number	-
Email Address	SH.LOW87@GMAIL.COM
Address	BLK 418B FERNVALE LINK #17-140
Address complement	-
Postcode	792418
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	4
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### PASSENGER 1

Name	TAN TENG LING
Gender	Female

#### PASSENGER 2

Name	ADEN LOW
Gender	Male

#### PASSENGER 3

Name	ADAM LOW
Gender	Male

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

#### ATTACHMENT(S)

Are accident photos available for attachment? .....	Yes
Was there any video captured by Car Camera? .....	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number .....	SJT732Y
Vehicle Manufacturer .....	Toyota
Vehicle Model .....	ALTIS
Vehicle Variant .....	-
Vehicle Colour .....	Gray
Vehicle Category .....	Private car
Name of Driver .....	MUHAMMAD FARHAN BIN MOHD FADIL
Contact Number .....	(Phone) +65-94476060
Address .....	-
Address complement .....	-
Postcode .....	-
Insurance Company Name .....	China Taiping Insurance (Singapore) Pte. Ltd.
Nature Of Damage .....	-
Details of property damaged in accident .....	-
No. Of Passenger (Including Driver) .....	-


**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

**Sketch Plan**



Describe Circumstances of the Accident

The accident happened along Yio Chu Keng Road (in direction towards Ang Mo Kio). It took place between bus stop 6709 and Tamarind Road.

My car was stationary behind other cars on the leftmost lane. The third party car # SJT132Y could not brake in time and hit my car on the rear.

The accident took place on 20 Aug 2012, 4.45pm.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel





CYCLE &amp; CARRIAGE

CYCLE &amp; CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 67461000 Fax: (65) 64875857



Movement that inspires

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN TONG LING	Cust No/Name /TAN TONG LING
BLK 418B FERNVALE LINK	Reg No/Reg Date SMH626Z / 10/01/201
#17-140	Date In/Mileage 22/08/2022/ 0
SINGAPORE 792418	Chassis No KNAF3416MK5023986
Contact No Mobile: 98572018	Engine No G4FGJH713013
	Make/Model KIA/CERATO 1.6 A EX G333
	Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	22/08/2022/ 16:36	REN	979 / Renemer Ramirez Bag	11403
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
Z TEXT ACCIDENT ON 20/08/2022 ALONG YCK RD, BUS STOP 67019 & TAMARIND RD OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT VEHICLE TP#: SJT732Y TP INS: CHINA TAIPING					
A 10028901					280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM					
A 90000001					80.00
TO CHECK WIRING AND ELECTRICAL SYSTEM					
E PNT88000					640.00
TO REMOVE & RE-INSTALL REAR FLOOR BOARDS, TRIM AND CARPETS TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS					
E PNT88000					3200.00
TO REPLACE UPR & LWR REAR BUMPER, BRACKETS, CLIPS, LH & RH T/SIGNAL LAMP & COVER, REINFORCEMENT, STAY, ETC -TO CUT & WELD REAR END PANEL STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS					
E PNT98000					1650.00
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS (UPPER REAR BUMPER & REAR END PANEL)					
E PNT88000					100.00
TO CHECK & TEST REVERSE SENSORS					
E PNT88000					220.00
TO SUPPLY ONE SET REVERSE SENSOR					
M SUNDRY					200.00
TO APPLY SEALANT KIT ON CUT & WELD AREAS					
M SUNDRY					100.00
TO APPLY ANTI-CORROSION ON AFFECTED AREAS					
M SUNDRY					50.00
TO SUPPLY C & C BADGE					
M SUNDRY					50.00
SUNDRIES					
M UPR COVER-RR BUMPER					651.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## CYCLE &amp; CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

CYCLE &amp; CARRIAGE

330 Ubi Road 3, Singapore 408650 Tel: (65) 67461000 Fax: (65) 64875857



Movement that inspires

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN TONG LING	Cust No/Name /TAN TONG LING
BLK 418B FERNVALE LINK #17-140 SINGAPORE 792418	Reg No/Reg Date SMH626Z / 10/01/201
Contact No Mobile: 98572018	Date In/Mileage 22/08/2022/ 0
	Chassis No KNAF3416MK5023986
	Engine No G4FGJH713013
	Make/Model KIA/CERATO 1.6 A EX G333
	Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	22/08/2022/ 16:36	REN	979 / Renemer Ramirez Bag	11403

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LWR COVER-RR BUMPER	1.00	241.00	00.00	241.00
M LH SIDE UPR BRACKET ASSY-RR BPR	1.00	25.00	00.00	25.00
M RH SIDE UPR BRACKET-ASSY RR BPR	1.00	31.00	00.00	31.00
M LH COVER-RR BUMPER FOG LAMP	1.00	19.00	00.00	19.00
M LH LAMP ASSY-SIDE T/SIGNAL	1.00	201.00	00.00	201.00
M RH COVER-RR BUMPER FOG LAMP	1.00	19.00	00.00	19.00
M RH LAMP ASSY-SIDE T/SIGNAL	1.00	201.00	00.00	201.00
M LH UNDER COVER-RR BUMPER	1.00	33.00	00.00	33.00
M EXTN WIRING ASSY-BWS	1.00	207.00	00.00	207.00
M LH UPR BRACKET-RR BEAM MTG	1.00	9.00	00.00	9.00
M RH UPR BRACKET-RR BEAM MTG	1.00	9.00	00.00	9.00
M CTR LWR BRACKET-RR BEAM	1.00	6.00	00.00	6.00
M LWR BRACKET-RR BEAM MTG	2.00	6.00	00.00	12.00
M ANTENNA ASSY-SMARTKEY	1.00	46.00	00.00	46.00
M BEAM-RR BUMPER	1.00	318.00	00.00	318.00
M LH STAY-RR BUMPER	1.00	65.00	00.00	65.00
M RH STAY-RR BUMPER	1.00	65.00	00.00	65.00
M PANEL ASSY-BACK	1.00	324.00	00.00	324.00
M TRIM ASSY-RR TRANSVERSE	1.00	41.00	00.00	41.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


Date:

Confirm &amp; accepted by

Nett 9,093.00  
7% GST on 9093.00 636.51  
Total Payable 9,729.51

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE &amp; CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 67461000 Fax: (65) 64875857



Movement that inspires

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN TONG LING	Cust No/Name /TAN TONG LING
BLK 418B FERVALE LINK	Reg No/Reg Date SMH626Z / 10/01/201
#17-140	Date In/Mileage 29/08/2022/ 36172
SINGAPORE 792418	Chassis No KNAF3416MK5023986
Contact No Mobile: 98572018	Engine No G4FGJH713013
01/09/	Make/Model KIA/CERATO 1.6 A EX G333
	Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	01/09/2022/ 11:27	REN	979 / Renemer Ramirez Bag	11403
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
Z TEXT					
ACCIDENT ON 20/08/2022 ALONG YCK RD, BUS STOP 67019 & TAMARIND RD					
OWNER CLAIMING THIRD PARTY					
LOSS OF RENTAL					
TP#: SJT732Y TP INS: CHINA TAIPING					
A 10028901					280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM					
A 90000001					80.00
TO CHECK WIRING AND ELECTRICAL SYSTEM					
E PNT88000					1280.00
TO REPLACE UPR & LWR REAR BUMPER, LH & RH BRACKETS,					
LH & RH T/SIGNAL LAMP COVER, REINFORCEMENT, LH & RH STAY.					
-TO REPAIR REAR END PANEL					
STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS					
E PNT98000					1100.00
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS					
(UPPER REAR BUMPER & REAR END PANEL)					
E PNT88000					80.00
TO CHECK & TEST REVERSE SENSORS					
E PNT88000					220.00
TO SUPPLY ONE SET REVERSE SENSOR					
M SUNDRY					60.00
TO APPLY ANTI-CORROSION ON AFFECTED AREAS					
M SUNDRY					20.00
SUNDRIES					
Z TEXT					
FINALIZATION					
NO. OF TOTAL REPAIR DAYS - 4 DAYS					
ATTENTION TO: MR. MARCUS CHUA					
X UPR COVER-RR BUMPER	1.00	651.00	00.00		651.00
X LWR COVER-RR BUMPER	1.00	241.00	00.00		241.00
X LH SIDE UPR BRACKET ASSY-RR BPR	1.00	25.00	00.00		25.00
X RH SIDE UPR BRACKET-ASSY RR BPR	1.00	31.00	00.00		31.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE &amp; CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 67461000 Fax: (65) 64875857



Movement that inspires

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN TONG LING	Cust No/Name /TAN TONG LING
BLK 418B FERNVALE LINK	Reg No/Reg Date SMH626Z / 10/01/201
#17-140	Date In/Mileage 29/08/2022/ 36172
SINGAPORE 792418	Chassis No KNAF3416MK5023986
Contact No Mobile: 98572018	Engine No G4FGJH713013
01/09/	Make/Model KIA/CERATO 1.6 A EX G333
	Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	01/09/2022/ 11:27	REN	979 / Renemer Ramirez Bag	11403

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X LH COVER-RR BUMPER FOG LAMP	1.00	19.00	00.00	19.00
X RH COVER-RR BUMPER FOG LAMP	1.00	19.00	00.00	19.00
X BEAM-RR BUMPER	1.00	318.00	00.00	318.00
X LH STAY-RR BUMPER	1.00	65.00	00.00	65.00
X RH STAY-RR BUMPER	1.00	65.00	00.00	65.00

Estimate

Confirm &amp; accepted by

	Nett	4,554.00
7% GST on	4554.00	318.78
Total Payable		4,872.78

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.