

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22008084/Kny3q2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924		Date:	18/10/2022	
			Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SDT 8989S	Veh. Inspected	SKZ 9471Y	
	Policy No.	P10106958R03	Coverage (\$)	0.00	
	Claim No.	C10017046/JM	Excess (\$)	0.00	
	Assign From	SALIZAWATI HAIZAR	Assign Date	23/08/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS (A)	c.c	1598	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	MR053REH104538165	Colour	METALLIC SILVER	
	Odometer	187099 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/45 R17	FALKEN	7 mm	
	L/H Front Tyre	225/45 R17	FALKEN	7 mm	
	R/H Rear Tyre	225/45 R17	FALKEN	7 mm	
	L/H Rear Tyre	225/45 R17	FALKEN	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	19/08/2022	Inspection Date	23/08/2022	
	Survey held at	BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569541.			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

7 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: