

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	HSBC LIFE (SING)	APORE) PTE LTD	Ref:	CC4/ASM22008104/Upa3q2	
	10 MARINA BOULI #48-01 MARINA BA 2SINGAPORE 018	AY FINANCIAL CENTRE TOWER	Date:	14/04/2023	
	ATTN:WINNIE		Code	: HSB	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBK 7955S	Veh. Inspected	SMM 3515P	
	Policy No.	GA559105	Coverage (\$)	0.00	
	Claim No.	S2M049FP	Excess (\$)	0.00	
	Assign From		Assign Date	23/08/2022	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA FIT G (A)	c.c	1317	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	GK31347454	Colour	WHITE	
	Odometer	65873 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	175/70 R14	BRIDGESTONE	7 mm	
	L/H Front Tyre	175/70 R14	BRIDGESTONE	7 mm	
	R/H Rear Tyre	175/70 R14	BRIDGESTONE	7 mm	
	L/H Rear Tyre	175/70 R14	BRIDGESTONE	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	20/08/2022	Inspection Date	23/08/2022	
	Survey held at	QUAN DE MOTOR TRADING			
		BLK 1 KAKI BUKIT AVENUE 6 #01-67 AUTOBAY SINGAPORE 417883			
5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days			