

ASS. FEO. BY:

REF:

CS/INC 22008116/ACY3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / T / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNB5184T Yr Regn: 2019, August

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Attrage c.c. 1193

Colour: Grey A/C: Insured / Std / NI / NA

Sp.Reading: 42353 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MMBSTA13AKH002807

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55R15

R: 185/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Roadstone

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 23/08/22

*Survey held at 8m.

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP INC</u>
<u>28/9</u>	<u>Adrian finalised LS & 3400/-; 5 days with repainer. (Red. 6172.89, 64%)</u>
	<u>MV:</u>
	<u>PV:</u>
	<u>Nett:</u>

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

____ S + RS. ____ SI

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

Report Format:

TP

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	19/08/2022 09:51 (SGT)
Reported by	Both
Date of Accident	18/08/2022 07:45 (SGT)
Exact Location of Accident	Yio Chu Kang Rd, Singapore
Additional Location Information	SLIP ROAD TOWARDS CTE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNB5184T
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	WILLIAM WIBISONO
NRIC No	S8373216D
Email Address	GBIWILLIAM@GMAIL.COM
Mobile Phone No	(Phone) +65-92707094
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Attrage
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1200

INSURANCE COMPANY

Name of Insurance Company	Etika Insurance Pte Ltd
Policy Number / Cover Note Number	M0018078

DRIVER

Name of Driver	WILLIAM WIBISONO
NRIC No	S8373216D
Date Of Birth	12/11/1983
Occupation	Indoor

Date Of Driving Pass	26/05/2009
Driving experience	13 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-92707094
Alt. Phone Number	-
Email Address	GBIWILLIAM@GMAIL.COM
Address	132 PUNGGOL WALK #02-20
Address complement	-
Postcode	828777
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	JAMES WIBISONO
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS DRIVING STRAIGHT ALONG THE SLIP ROAD OF YIO CHU KANG ROAD TOWARDS CTE AT THE EXTREME LEFT LANE OF 2 LANES. THE TRAFFIC AT THAT POINT OF TIME WAS HEAVY. ALL VEHICLES IN FRONT OF ME WERE MOVING SLOWLY AND STOPPING INTERMITTENTLY. SUDDNELY, I FELT A HUGE IMPACT FROM BEHIND. VEHICLE B COLLIDED ONTO THE REAR PORTION OF MY VEHICLE AND CAUSED DAMAGE. I ALIGHTED AND REALISED THERE WERE A TOTAL OF 3 VEHICLES INVOLVED.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ3294Y
-----------------------------	----------

Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	VEHICLE B
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJS8531M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	VEHICLE C
No. Of Passenger (Including Driver)	2

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	WILLIAM WIBISONO
Gender	Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SNB5184T
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

INJURED 2

Name of injured person	JAMES WIBISONO
Gender	Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SNB5184T
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

<input checked="" type="checkbox"/>	A
<input checked="" type="checkbox"/>	B
<input checked="" type="checkbox"/>	C
<input checked="" type="checkbox"/>	D
<input checked="" type="checkbox"/>	E
<input checked="" type="checkbox"/>	F
<input checked="" type="checkbox"/>	G
<input checked="" type="checkbox"/>	H
<input checked="" type="checkbox"/>	I
<input checked="" type="checkbox"/>	J
<input checked="" type="checkbox"/>	K
<input checked="" type="checkbox"/>	L
<input checked="" type="checkbox"/>	M
<input checked="" type="checkbox"/>	N
<input checked="" type="checkbox"/>	O
<input checked="" type="checkbox"/>	P
<input checked="" type="checkbox"/>	Q
<input checked="" type="checkbox"/>	R
<input checked="" type="checkbox"/>	S
<input checked="" type="checkbox"/>	T
<input checked="" type="checkbox"/>	U
<input checked="" type="checkbox"/>	V
<input checked="" type="checkbox"/>	W
<input checked="" type="checkbox"/>	X
<input checked="" type="checkbox"/>	Y
<input checked="" type="checkbox"/>	Z

Slip id at Yio Chu Kang Rd Towards CTE

A: SNB51847

B: GBJ32944

C: DJS0531M



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving straight along the slip road of Yio Chu Kang Rd towards CTE at the extreme left lane of 2 lanes.

The traffic at that point of time was heavy, all vehicles in front of me were moving slowly and stopping intermittently.

Suddenly, I felt a huge impact from behind. Veh "b" collided into the rear portion of my vehicle and caused damage.


I alighted and realized there were a total of 3 vehicles involved.



DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SM AUTOMOTIVE

Ntuc

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 18/08/2022

Estimated repair cost for vehicle no: SNB5184T MITSUBISHI ATTRAGE 1.2 CVT

CHASSIS: MMBSTA13AKH002807 (2019)

19/08/2022

TP INC

Calire

S/N	Qty	Items	U/price	Amount
1	1	REAR BOOTLID <i>Regis</i>	\$828.30	\$828.30 +
2	1	REAR BOOTLID LOCK <i>Neu</i>	\$206.30	\$206.30 +
3	1	REAR BOOTLID INNER TRIM <i>Neu</i>	\$158.60	\$158.60 +
4	1	REAR BOOTLID OUTER CHROME MOULDING <i>Neu</i>	\$298.60	\$298.60 +
5	2	REAR BOOTLID NUMBER PLATE LAMP <i>Neu</i>	\$65.10	\$130.20 +
6	1	REAR BOOTLID EMBLEM ATTRAGE <i>Neu</i>	\$38.60	\$38.60 ✓
7	1	REAR BOOTLID EMBLEM LOGO <i>Neu</i>	\$48.60	\$48.60 ✓
8	1	REAR WEATHER STRIPE <i>Neu</i>	\$148.60	\$148.60 +
9	1	REAR BUMPER <i>Deformed</i>	706	706 ✓
10	2	REAR BUMPER BRACKET <i>Neu</i>	\$98.70	\$197.40 +
11	2	REAR BUMPER SIDE RETAINER <i>Neu</i>	\$128.60	90 \$257.20 ✓
12	1	REAR END PANEL <i>Deformed</i>	\$402.30	\$402.30 ✓
13	1	REAR END PANEL TOP GARNISH <i>Deformed</i>	\$82.30	\$82.30 ✓
14	1	REAR END PANEL AIR VENT <i>Deformed</i>	\$95.10	\$95.10 ✓
15	1	REAR END PANEL AIR DUCT <i>Neu</i>	\$112.20	\$112.20 +
16	1	REAR END PANEL KEYLESS SENSOR <i>Neu</i>	\$248.60	\$248.60 +
17	2	REAR TAILLAMP <i>Neu</i>	\$276.30	\$552.60 +
18	2	REAR TAILLAMP INNER PANEL <i>Neu</i>	\$318.40	\$636.80 +

1462.90

11316.61

TOTAL :	\$4,992.10
LESS 10 %	\$499.21
SUB-TOTAL :	\$4,492.89

SNB5184T MITSUBISHI ATTRAGE

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>New</i>	\$80.00	\$80.00 <i>30</i>
2	1	REAR BUMPER LOWER SPOILER <i>Delux</i>	\$850.00	\$850.00 <i>800</i>
3	1	REAR EXHUAUST TAIL PIPE <i>New</i>	\$260.00	\$260.00 <i>x</i>
4	1	REAR BUMPER REVERSE SENSOR <i>Delux</i>	\$280.00	\$280.00 <i>200</i>
5	1	REAR CAMERA <i>New</i>	\$480.00	\$480.00 <i>x</i>
6	1	REAR NUMBER PLATE WITH CASING <i>New</i>	\$60.00	\$60.00 <i>x</i>
7	1	REAR BUMPER LOWER SPOILER SEAL <i>New</i>	\$120.00	\$120.00 <i>50</i>
8	1	REAR END PANEL SEALANT <i>New</i>	\$120.00	\$120.00 <i>60</i>

1140

TOTAL: \$2,250.00

TOTAL PARTS: \$6,742.89

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS
- 5 To remove Reverse sensor. *50*
- 6 To remove upholstery *150. 60.*

700
\$1,200.00
1800 *no* \$1,000.00
\$80.00 *3*
\$300.00
60.
Subtotal :- \$2,580.00
Total:- \$9,322.89
9,572.89

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Admin
h/s 050 days.
total: 4256.61
h/s 3.41k

341k