

ASS. REC. BY:

REF:

EQ / 22008120/KV

Kenneth

## ASSIGNMENT

9

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 866k

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 24 days Res.: Yes or NoLum Sum: 26 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMH5148B Yr Regn: 01.19Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MIT Attrage c.c. 1193Colour: M. Silver A/C: Insured / Std / Nil / NASp. Reading: 00165 T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: MM B STA 13A JM 004409Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 20/8/22

Survey held at

Rear

R/Bal. 9 mmL/Bal. 9 mmD.O.I. 24/8/2022Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 / Bonnet jammed unable to take chassis number.

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

) \$ + RS. \$

) Fines

) Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06643

Vehicle Insured : GBC8843S  
Accident Date : 20-Aug-2022

Date : 22-Aug-2022

Our Ref : 022135 (EQ) / CHAN

PAGE : 1

LEONG SIYUN  
BLK 19 JALAN TENTERAM  
#26-138  
Singapore 321019

*Not Withheld*  
*11 Pym &*  
*Recovery After Pym*  
*24 days*

## ESTIMATED COST OF REPAIR FOR MIT ATTRAGE SMH5149B

1 pc Boot lid		828.00	—
1 pc Boot lid top spoiler		572.00	—
2 pcs Boot lid hinge	@ S\$192.00	384.00	—
1 pc Boot lid inner lock		206.00	—
1 pc Boot lid lock catch		25.00	X
1 pc Boot lid rubber		148.00	—
1 pc Boot lid cable		65.00	?
1 pc Boot lid outer chrome		378.00	—
2 pcs Boot lid license plate lamp	@ S\$ 48.00	96.00	X
1 pc Boot lid "ATTRAGE" emblem		35.00	—
1 pc Boot lid logo		41.00	—
1 pc Boot lid "MIVEC" plate		58.00	—
1 pc Rear windscreen glass		584.00	—
2 pcs Rear w/s glass side moulding	@ S\$ 85.00	170.00	—
1 pc Rear w/s glass top moulding		50.00	—
2 pcs Rear fender	@ S\$733.00	1,466.00	—
2 pcs Rear fender side extension	@ S\$135.00	270.00	—
2 pcs Rear fender inner trim cover	@ S\$158.00	316.00	—
1 pc Rear n/s fender inner shield		38.00	?
2 pcs Taillamp	@ S\$326.00	652.00	—
2 pcs Taillamp corner panel	@ S\$115.00	230.00	—
2 pcs Taillamp gasket	@ S\$ 28.00	56.00	—
2 pcs Taillamp side clip	@ S\$ 7.00	14.00	—
1 pc Rear end panel		512.00	—
1 pc End panel top garnish		95.00	—
2 pcs End panel side guide	N/S 0.7 @ S\$ 65.30	130.60	—
1 pc End panel centre guide		52.10	—
1 pc Rear bumper fascia		708.00	—

### LKK Auto Consultants hence notify

#### the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Con't Page 2 ...



# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBC8843S

Page : 2

1 pc	Rear bumper lower spoiler			CM 1,643.00	✓
2 pcs	Rear chassis extension member	@ S\$718.00	1,436.00	?	
1 pc	Rear spare tyre panel		906.00	?	
1 pc	Rear spare tyre board		CM 205.00	✓	
1 pc	Rear spare tyre screw & nut		195.00	?	
1 pc	Rear exhaust pipe		571.00	?	
1 pc	Bonnet		691.00	✓	
2 pcs	Bonnet hinge	@ S\$ 58.00	116.00	?	
1 pc	Bonnet insulator		CM 160.00	✓	
1 pc	Bonnet inner lock		Im 65.00	✓	
1 pc	Bonnet rubber		48.00	?	
1 pc	Bonnet cable		38.00	?	
2 pcs	Front fender	o/s Bu @ S\$438.00	876.00	✓	
2 pcs	Front fender "ECO" emblem	@ S\$ 45.00	90.00	✓	
2 pcs	Eco emblem lower chrome	@ S\$ 59.00	118.00	✓	
1 pc	Front o/s fender inner shield		93.00	?	
1 pc	Front o/s fender outer garnish		27.00	?	
2 pcs	Headlamp	o/s CM n/s ? @ S\$544.00	1,088.00	✓	
1 pc	Front grille		CM 525.00	✓	
1 pc	Front grille logo		CM 47.00	✓	
1 pc	Front grille top cover		59.00	?	
8 pcs	Front grille clip	@ S\$ 3.50	28.00	✓	
1 pc	Front bumper fascia		666.00	✓	
1 pc	Front bumper reinforcement		132.00	✓	
2 pcs	Front bumper side retainer	@ S\$ 15.00	30.00	✓	
1 pc	Front bumper lower grille		CM 156.00	✓	
1 pc	Front bumper centre lower cover		89.00	?	
1 pc	Front bumper lower spoiler		CM 1,643.00	✓	
1 pc	Front bumper tow cover		25.00	✓	
2 pcs	Front wiper garnish side	@ S\$ 25.00	50.00	?	
2 pcs	Horn	@ S\$ 75.00	150.00	?	
1 pc	Radiator assy		872.00	?	
1 pc	Radiator top guide		126.00	?	
1 pc	Radiator fan cowling		117.00	?	
1 pc	Radiator fan blade		70.00	?	
1 pc	Radiator fan motor		374.00	?	
1 pc	Radiator spare tank		38.00	?	
1 pc	Radiator top hose		18.00	?	

Con't Page 3 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBC8843S

Page : 3

1 pc	Radiator lower hose	26.00	7
1 pc	Air con condenser	683.00	7
2 pcs	Air con condenser side guide @ S\$ 18.00	36.00	7
1 pc	Air con suction hose	208.00	7
1 pc	Air con discharge hose	230.00	7
1 pc	Front top panel	168.00	7
1 pc	Front lower support panel	999.00	7
1 pc	Air intake air duct	120.00	7
1 pc	Air cleaner housing assy	185.00	7
1 pc	Engine manifold	1,723.00	7

-----  
26,138.70

Less 10% : 2,613.87

	23,524.83	200sn
1 pc	350.00	sn
1 pc	60.00	sn
1 pc	300.00	sn
1 pc	40.00	sn
1 pc	50.00	sn
1 pc	50.00	sn
1 pc	40.00	sn
1 pc	30.00	sn

To towing

(Bill) 100.00 ✓

To rewire damaged parts and refocus  
headlamp beam.

20.00 ✓

To remove & renew rear windscreen  
glass and conduct water leak test.

150.00 120

To remove roof lining, front and  
rear seats, trim board and carpet

200.00 120

To apply undersealing

300.00 210

Con't Page 4 ...

# ALAN'S UNITED

10101 10101 10101  
10101 10101 10101  
10101 10101 10101  
10101 10101 10101

10101 10101 10101

10101 10101 10101  
10101 10101 10101

10101 10101

10101 10101  
10101 10101  
10101 10101

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBC8843S

Page : 4

To remove and renew exhaust  
silencer box

*601*  
80.00

To putty and spray replaced parts

2,400.00 *22nd*

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

*230d*  
2,500.00

Total :

-----  
S\$30,194.83  
=====

Singapore Dollars Thirty Thousand One Hundred  
and Ninety Four and Cents Eighty Three Only



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	22/08/2022 11:18 (SGT)
Reported by	Both
Date of Accident	20/08/2022 13:40 (SGT)
Exact Location of Accident	CTE, Singapore
Additional Location Information	CTE TOWARDS SLE BEFORE MOULMEIN
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SMH5149B

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LEONG SIYUN
NRIC No	SXXXX474F
Email Address	CHARLTON.NG@GMAIL.COM
Mobile Phone No	(Phone) +65-98651576
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Attrage
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
	1193

#### INSURANCE COMPANY

Name of Insurance Company	EQ Insurance Company Ltd
Policy Number / Cover Note Number	DMPPHQ22-000486

Name of Driver	NG ZHEWEI, CHARLTON (HUANG ZHEWEI)
ID No	SXXXX035E
Date of Birth	13/04/1986
Location	Indoor

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

Sketch Plan

(TE towards SLE (Tunnel))



A - SMH5149B

B - GBC8843S

C - SMC 1704D