

ASS. REC. BY:

REF: SMR/2200814011k9Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Accord

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 847k

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 7-10 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKU 2877H Yr Regn: 07, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A) WagonMake: Nazda 5 c.c. 1998Colour: M. Gray A/C: Insured / Std / NI / NASp. Reading: 152081 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JM6CW1071F0121905Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / RIm or

Tyre Size: F: Kapen 205/60R16R: Yoko

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 3 mmL/Bal. 3 mmD.O.A. 23/8/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or15

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Wlscp said unable to locate find parts, likely part by part.

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation

S + RS. SI

Fines

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech Invs (\$ )☐ : Weekend (\$ )

Report Format :

Lump Sum / I.B.I: (\$ )

# ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

*Not Authorized  
Library &  
Heavy After Paint  
7-10 days*

## ESTIMATE

### FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01, CITY HOUSE

SINGAPORE 068877

ATTN: ACCIDENT CLAIMS DEPARTMENT

DATE : 23.08.2022  
VEHICLE NO : SKU2877H  
VEH MAKE/MODEL : MAZDA 5  
YOM : 2015  
CHASSIS NO : JN6CW1071F0121905  
DATE OF ACCIDENT : 23.08.2022

NO	QTY	DESCRIPTION	AMOUNT \$
		<b>LIST PRICE:-</b>	
1	1	REAR TAIL GATE	\$ 1,637.00 ✓
2	2	REAR TAIL GATE HINGE	\$ 77.20 X
3	2	REAR TAIL GATE ABSORBER LH & RH	\$ 354.20 X
4	1	REAR TAIL GATE LOCK	\$ 256.20 ✓
5	1	REAR TAILGATE STRICK	\$ 57.90 X
6	1	REAR TAILGATE LOGO	\$ 44.10 ✓
7	1	REAR TAILGATE EMBLEM PANEL	\$ 482.40 X
8	1	REAR TAILGATE "MAZDA 5"	\$ 81.60 ✓
9	1	REAR BUMPER	\$ 961.20 ✓
10	2	REAR BUMPER SDE RETAINER LH & RH	\$ 95.20 ✓
11	1	REAR TAILGATE LAMP LH	\$ 409.40 X
12	1	REAR TAILGATE LAMP RH	\$ 409.40 X
13	1	REAR BUMPER REFLECTOR LH	\$ 53.00 ✓
14	1	REAR BUMPER REFLECTOR RH	\$ 53.00 X
15	1	REAR LAMP LH	\$ 601.70 X
16	1	REAR LAMP RH	\$ 601.70 X
17	1	REAR END PANEL OUTER	\$ 515.70 7
18	1	REAR END PANEL INNER	\$ 177.50 7
19	1	REAR TAILGATE RUBBER	\$ 80.40 7
20	1	REAR END PANEL TOP GARNISH	\$ 2,426.90 X
21	1	REAR WINDSCREEN MOULDING	\$ 39.60 X
22	1	REAR FENDER LH	\$ 2,426.90 X
23	1	REAR FENDER INNER SHILED	\$ 39.60 X
24	1	REAR FENDER RH	\$ 1,085.60 X
25	1	REAR FENDER INNER SHIELF RH	\$ 108.60 X
26	1	FRONT BONNET	\$ 207.00 X
27	2	FRONT BONNET HINGE	\$ 135.80 X
28	1	FRONT BONNET LOCK	\$ 702.30 7
29	1	FRONT BONNET INSULATOR	
30	1	FRONT GRILLE BASE	
31	1	FRONT GRILLE OUTER	
TOTAL - LIST ITEM			\$ 14,121.10
LIST 20%			\$ 2,824.22
TOTAL			\$ 11,296.88

# ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

## ESTIMATE

### FIRST CAPTIAL INSURANCE LTD

36 ROBINSON ROAD

#16-01, CITY HOUSE

SINGAPORE 068877

ATTN: ACCIDENT CLAIMS DEPARTMENT

DATE : 23.08.2022  
VEHICLE NO : SKU2877H  
VEH MAKE/MODEL : MAZDA 5  
YOM : 2015  
CHASSIS NO : JN6CW1071F0121905  
DATE OF ACCIDENT : 23.08.2022

NO	QTY	DESCRIPTION	AMOUNT \$
32	1	FRONT EMBLEM	
33	1	FRONT HEADLAMP LH	
34	1	FRONT HEADLAMP LOWER BRACKET LH	
35	1	FRONT HEADLAMP RH	
36	1	FRONT HEADLAMP LOWER BRACKET RH	
37	1	FRONT BUMPER	
38	2	FRONT BUMPER SIDE RETAINER LH & RH	
39	1	FRONT FOGLAMP LH	
40	1	FRONT FOGLAMP GARNISH LH	
41	1	FRONT FOGLAMP RH	
42	1	FRONT FOGLAMP GARNISH RH	
43	1	FRONT REINFORCEMENT BAR	
44	1	FRONT SUPPORT PANEL	
45	1	REAR EXHAUST	
46	1	REAR EXHAUST MOUNTING	
47	1	REAR EXHAUST BOX	
48	1	REAR EXHAUST HEAT SHEID	
49			
50			
51			
52			
53			
54			
55			
56			
57			
58			
59			
60			
TOTAL - LIST ITEM			\$ -
LIST 20%			\$ -
TOTAL			\$ -

**10 Ang Mo Kio Industrial Park 2A**  
**#03-11 AMK Autopoint Singapore 568047**  
**Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: [claims@mycarworkshop.com.sg](mailto:claims@mycarworkshop.com.sg)**

10 Ang Mo Kio Industrial Park 2A  
#03-11 AMK Autopoint Singapore 568047  
Tel: 6481 9518 / 6481 9519

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: [claims@mycarworkshop.com.sg](mailto:claims@mycarworkshop.com.sg)

36 ROBINSON ROAD

#16-01, CITY HOUSE

SINGAPORE 068877

ATTN: ACCIDENT CLAIMS DEPARTMENT

DATE :	23.08.2022
VEHICLE NO :	SKU2877H
VEH MAKE/MODEL :	MAZDA 5
YOM :	2015
CHASSIS NO :	JN6CW1071F0121905
DATE OF ACCIDENT :	23.08.2022

DATE : 23.08.2022

VEHICLE NO : SKU2877H

VEH MAKE/MODEL: MAZDA 5

YOM : 2015

CHASSIS NO : JN6CW1071F0121905

DATE OF ACCIDENT: 23.08.2022

90ln  
✓  
7  
80ln  
x  
200ln  
x  
1  
x  
  
120cl  
7  
4cl  
8cl  
12cl  
5cl  
6cl  
7

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

**Signature:**

Date:

<b>Total - L/C</b>	<b>\$</b>	<b>4,550.00</b>
--------------------	-----------	-----------------

<b>Sub-Total</b>	<b>\$</b>	<b>17,086.88</b>
------------------	-----------	------------------

7% GST	\$	1,196.08
--------	----	----------

<b>Total</b>	<b>\$</b>	<b>18,282.96</b>
--------------	-----------	------------------

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	23/08/2022 17:37 (SGT)
Reported by	Driver
Date of Accident	23/08/2022 13:32 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	PIE (CHANGI) BEFORE TOA PAYOH EXIT 16A
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU2877H
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	TAN CHEW TIAM
NRIC No	SXXXX814G
Email Address	CHEW.TIAM@GMAIL.COM
Mobile Phone No	(Phone) +65-90272108
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Mazda
Model	5
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2000

### INSURANCE COMPANY

Name of Insurance Company	Sompo Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	D22MTPV010011186

### DRIVER

Name of Driver	CHAN LEE CHING
NRIC No	SXXXX614F
Date Of Birth	25/11/1967
Occupation	Outdoor

**SKETCH PLAN**

VEH A: SKU 2877H  
VEH B: SHF 333M  
VEH C: SNL 543Y

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

**Sketch Plan**

Before Tou Payoh Exit 16A  
PIE (Changi)