

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



INCOME INSURANCE LTD Ref: NS/INC22008191/Gvce2						
1100.111.1100.101.1100.1101						
73 BRAS BASAH ROAD						
	905-01 NTUC TRADE UNION HOUSESINGAPORE 89556			20-10-2022		
1895	00		Code:	INC4		
4						
1.	Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SKF 6888D Veh. Inspected SHC 9000E					
	Insured Veh.	SKF 6888D		•	SHC 9000E	
	Policy No.	MT/4405440 000	Covera		0.00	
	Claim No.	MT/1185110-002	Exces		0.00	
	Assign From		Assign		22/08/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI I40	c.c		1685	
	Engine No.	HIDDEN	Year o		2016	
	Chassis No.	KMHLB41UMGU089838	Coloui	<u> </u>	BLUE	
	Odometer	-	Steeri		IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST	LAKE	6 mm	
	L/H Front Tyre	195/65 R15	WEST	LAKE	6 mm	
	R/H Rear Tyre	195/65 R15	WEST	LAKE	6 mm	
	L/H Rear Tyre	195/65 R15	WEST	LAKE	6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	19/08/2022	Inspec	tion Date	22/08/2022	
	Survey held at	Survey held at COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969				
5a.	ia. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					