

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 QD ☒ TP ☐ N/S ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: _____
 at Workshop m/s COMFORTDELGRO

of _____
 Insured: FBG 8419M

Policy No. _____
 Claims No. MT/1185320-002

Sum Insured: _____ Excess: _____
 (Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHC8339K Yr Regn: 30 Sep 2020

Type: M.Car / M.Cycle / Bus / Van / Lorry ☒ Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS c.c. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: — T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU303091455 *

Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ Burnt

Steering: ☒ ☐ Jammed / Leaked / Burnt or

Brake: ☒ ☐ Jammed / Leaked / Burnt or

Modi: ☒ Nil ☐ Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTLAKE

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 20/8/2022 D.O.I. 22-08-2022

Survey held at W/S 3PM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

14/10/22 Guo Qiang informed LS \$2550 (Red 1914.65, 42%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 19/10/22-typist

Report Filed: TP

Lump Sum/MPB: LS \$2550

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : W/Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Other:

TOTAL