

ASS. REC BY: Tuffin

REF: CS/TM/22008/194/Tqy 3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / IS / TP RES / OD RES / EVA / INV / MV
 To Inspect/Vehicle No: _____
 at Works/tp m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: S4D 3897T Yr Regn: 2018 Dec
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Prius C.C. 1798
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 381756 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: STD KB3FY203077725
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/65R15
 R: na
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Winstake
 Front 6 mm R/Bal. 6 mm
 L/Bal. 6 mm R/Bal. 6 mm
 D.O.A. _____ D.O.I. 23/8/22
 Survey held at Confort Loggy
 Des. of Damages: F/R / Rear / O/S / N/S / U/C / Rooftop or
O/S Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS

WP
 Vehicle: IN / OUT
 Date: _____ Person Contacted: Aray

Date / Time	Action / Instruction

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Date/Time, File Return to?
 1) _____
 2) _____
 Rep. Format: _____
 Lump Sum / I.B.R. (P) _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S + RS. \$ _____
 Photos _____
 Others _____
 TOTAL _____

To Kio

LK

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Aug 2022)
Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: **ComfortDelGro Engineering Pte Ltd/SHD3897T/25/08/2022 09:03**
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER	25.00	0.00	<i>Ry</i> *503.04 FL
2	1		*REAR WHEEL RIM COVER RH	25.00	0.00	<i>inf</i> *177.70 FL
3	1		*REAR DOOR COMFORT APP RH	0	0.00	<i>inf</i> *80.00 FS
				Sub Total (S\$)		760.74
				- List Item Discount on L Items (S\$)		170.19
				Total Parts (S\$)		590.55

F=Franchise part. S=SpcNett. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHD3897T/25/08/2022 09:03. Not valid without Reference section.
 Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	350 550.00
2	SPRAY PAINTING	New	750 800.00
Gross Labour Cost (\$\$)			1,350.00

ComfortDelGro Engineering Pte Ltd/SHD3897T/25/08/2022 09:03. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Handwritten notes:
 Tanjong 97495749
 wp' 25/8/22 @ 4pm
 c/s Resing after repair
 Tanjong @ lkhants.com
 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be asurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4657408

JC No: 305527670

Customer: COMFORT TRANSPORTATION PTE LTD
VMS No: 7010045
Customer No: 383 SIN MING DRIVE
Address: Singapore SINGAPORE 575717
Phone: (R) 65508755 (O)
(P)
Account Card No.


REGN NO: SHD3897T	MILEAGE
MAKE: TOYOTA	FUEL E.....1/2.....F
MODEL: PRIUS HYBRID(G4)	DATE/TIME IN 24.08.2022 15:40
YR OF MANU: 13.12.2018	TARGET DATE
CHASSIS CODE: JTDKB3FU203077725	COMPLETION DATE/TIME:

Accident Date: 23.08.2022
Nature: 3P 23.08.2022

JOB DESCRIPTION

/NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: **SHD3897T** CHIANG

Vehicle No.: **SHD3897T**

Signature/Date

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard