

AIR DETAILS

Reference

Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Aug 2022)
 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)
 Repairer's (Price-denominated Standard List)
Code: ComfortDelGro Engineering Pte Ltd/SHD3897T/25/08/2022 09:03
 These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

Qty	Part No.	Particulars	%Disc	%Depr	Amount
		*REAR BUMPER COVER	25.00	0.00	<i>Ry</i> *503.04 FL
		*REAR WHEEL RIM COVER RH	25.00	0.00	<i>ent</i> *177.70 FL
		*REAR DOOR COMFORT APP RH	0	0.00	<i>ent</i> *80.00 FS
Sub Total (\$)					760.74
- List Item Discount on L Items (\$)					170.19
Total Parts (\$)					590.55

Sp=Special part. S=SpcNett. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHD3897T/25/08/2022 09:03. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

177.70
25% 133.27
80

213.27

Estimates on Miscellaneous Items

Qty Particulars

Amount

Miscellaneous Items

1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	PANEL BEATING	New	350	550.00
2	SPRAY PAINTING	New	750	800.00
Gross Labour Cost (S\$)			1100	1,350.00

ComfortDelGro Engineering Pte Ltd/SHD3897T/25/08/2022 09:03. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1100
 Tanjil 97495749 213.77
 'wp' 25/8/22 @ 4pm 11
 1100
 CBS Resurvey after repair ✓ 1324.77
 Tanjil @ lkhant.com 4591050
 2 days ✗

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: