


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 UD ☒ TP WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: **FBK 2401G**
 At Workshop n/a: **S1 MOTORING**
 (d) _____
 Insured: **SJP 7064S**
 Policy No: _____
 Claims No: **S1M03C6E**
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: **10k**
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: **5** ~~4~~ days Res.: Yes or No
 Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **FBK 2401G** Yr Regn: **21/5/2015**
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **Honda cb600X m** cc **399**
 Colour: **black** A/C: _____ Insured / Std / NI / NA
 Sp. Reading: **not avail** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **NC471005762**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or
 Brake: **In order** / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: **120/60R17**
 R: **120/60R17**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / **PIR** / SUMI /
 TOYO / YOKO or _____

Front	Rear
R/Bal. 5 mm	R/Bal. 5 mm
L/Bal. _____ mm	L/Bal. _____ mm
D.O.A. 18/6/21	D.O.I. 22/6/21 1700
Survey held at S1 motoring w/s	
Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooltop or	

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	inv: 10k
	NV: 71161
	rebate: 2539
	rr: 7.5k - 3k
	body injury
24/6/2021	Revise to Cynthia via Smart Claim.
24/6/2021	Submit PRS.
	11/10/22 Submit lump sum: \$5350 and 5 days

Date/Time, File Pass to? ☐ : Prel. Report
 1) 24/6 TYPIST ☐ : Final Report
 Date/Time, File Return to? _____

Days Of Repair: **5**
 Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)
☐ : Wash and (\$)

Survey Fee:	
Transportation:	
S + AS: \$	
Fuel:	
Other:	
Total:	

Report Formed: _____
 Lump Sum / PRS: **5350**