



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/GRB21007566/Eny3e2-1	
			Date: 17/11/2022	
			Code: GRB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMY 4631S	Veh. Inspected	FBQ 6474M
	Policy No.	D21MFL0000447	Coverage (\$)	0.00
	Claim No.	MFL2021D0002605	Excess (\$)	0.00
	Assign From	CARINE KEK	Assign Date	25/08/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	YAMAHA N-MAX	c.c	155
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	MH3SG431000013037	Colour	BLUE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	100/80-14	MAXXIS	5 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	100/80-14	MAXXIS	5 mm
	L/H Rear Tyre			mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	18/06/2021	Inspection Date	13/07/2021
	Survey held at	3POINTS ENTERPRISE 50 BUKIT BATOK STREET 23, #02-22, MIDVIW BUILDING, SINGAPORE 659578		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	