



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC22005489/Kvy3m4-1 Date: 29/08/2022 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBH 8076M	Veh. Inspected	SDH 3338S
	Policy No.		Coverage (\$)	0.00
	Claim No.	22/22/22/VC05/025909	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	22/08/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MERCEDES C200 (A)	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	WDD2050772R509148	Colour	METALLIC DARK BLUE
	Odometer	36699 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/45 R18	BRIDGESTONE	7 mm
	L/H Front Tyre	225/45 R18	BRIDGESTONE	7 mm
	R/H Rear Tyre	225/45 R18	BRIDGESTONE	7 mm
	L/H Rear Tyre	225/45 R18	BRIDGESTONE	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S DOOR. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	07/06/2022	Inspection Date	13/06/2022
	Survey held at	HIAP LEK AUTOMOBILE TRADING 160 SIN MING DRIVE #05-17 SIN MING AUTOCITY SINGAPORE 575722		
<b>5a. Remarks</b>				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	