

Date : 27.08.2022

Fax :

Vehicle Reg No. : **SHD6752H**

18.08.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

2. The finalized amount shall be:

(b)	Labour Charges	\$650.00
-----	----------------	----------

Total for Part-By-Part Repair Cost	\$650.00
---	-----------------

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Total for European repair cost after 2000:		
Final Lumpsum Repair cost		

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : _____

Signature: *taufikh*

Name : CHIANG

Name : Taufikh

Tel : 62148314

Date : 12/10/22

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 27.08.2022

Time: 09:22:50

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305527675
REGN NO : SHD6752H
MILEAGE : 0000000000
MAKE : MERCEDES BENZ
MODEL : E220CDI(E6)
DATE OF REGN : 08.04.2016
DATE/TIME IN : 25.08.2022 09:45
ACCIDENT DATE : 18.08.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

SUB-TOTAL : 0.00

JOB NATURE

0000 PB PANEL BEATING SHD6752H TP

400.00

0001 SP SPRAYPAINT CHARGE

250.00

SUB-TOTAL : 650.00

TOTAL : 650.00

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO