

(08/11/11) wef

ASS. IEC. BY:

REF:

CC4/LPC22008274/Rpa3

4834

ASSIGNMENT

From:

Date:

Estimated Cost:

Veh No:

SMT 2308R

Yr Regn: 2020 / APR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMT 2308R

Make: Hyundai AD Nante 1.6 LSA cc 1591

at Workshop m/s Hin Lunn

Colour: Green

A/C: Insured / Std / NI / NA

of 1058, Bukit Merah LN 3 #0120

Sp. Reading: 48002

T/Radio: Insured / Std / NI / NA

Insured:

LPC

Eng/No:

Policy No.

C/No:

KMHD841 CMLU035107

Claim No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F:

195/65R15

R:

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

89K

Front

Rear

IDAC Accident Report:

Consistent? : Yes or No

R/Bal.

6

mm

R/Bal.

6

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6

mm

L/Bal.

6

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

17/08/22

D.O.I.

23/08/22

Lum Sum:

%

3 Val.: Yes or No

Survey held at

Hin Lunn

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 85K

Change to OD CLAIM

Date/Time, File Pass to?

☐

Prel. Report

Days Of Repair:

1)

☐

Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

Survey Fee:

Transportation:

☐

Interview (\$

Photos

☐

Tech. Invs (\$

Others

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$