

AXA Insurance Pte Ltd

Assessments

General Details

Involving
Date of Loss
Time of Loss
Loss Description
Comment

2019 SUZUKI JIMNY SIERRA 1.5 (SMN5506Y)

09/07/2022

11:55 AM

SMN5506Y (INSD) HIT BY QX531G
5 W/DAYS

Vehicle Details

Vehicle Registration#
Registration Province
Mileage
Manufacturing Year
Purchase date
Registration date
Age of vehicle

SMN5506Y

36263.00

2019

14/08/2019
2

	Policy Information	Assessment Information
Make	SUZUKI	SUZUKI
Model	JIMNY SIERRA 1.5	JIMNY SIERRA 1.5
Type		
Type of paint		
Chassis No	JB74W108595	
Engine No	K15B1026077	
Engine Capacity		
Sum Insured	0.00	0
Market Value	0.00	0

Workshop Details

Total Rebate Amount	0.00
Net Loss Amount	0.00
Assigned Workshop	
Days of work completion	5

Assessment Summary

Category	Revised Amount
Excess	-1,000.00
Spare Parts	3,537.50
Labour	592.14
Settlement %	100.0
Amount Non-standard Deduction	0.00
Final Claim Amount	3,129.64

Detailed Assessment

Inspection Date	20220714
Assessment Details	
Total Loss	false
Towing Charges	0.00
Voluntary Excess	0.00
Compulsory Excess	1000.00
Young/ Inexperienced/ Unnamed Driver Excess	0.00
Other Excess	0.00

Condition of vehicle at time of survey

General condition	Good
Steering (Serviceable)	true

Footbrake (Serviceable)
 Handbrake (Serviceable)
 Engine Modification
 Pre-accident condition

true
 true
 false
 Good

Tyre condition

Age of tyres
 Front Tyre Size
 Rear Tyre Size
 Front left side
 Rear left side
 Front right side
 Rear right side
 Spare wheel

205/70-R15
 205/70-R15
 YOKOHAMA -7MM
 YOKOHAMA -7MM
 YOKOHAMA -7MM
 YOKOHAMA -7MM

Parts

No.	Quantity	Part Name	Condition	Dep / Batt%	Discount %	Salvage %	Adjusted Amount	Supplementary Parts	Action	Comment
1	1.00	TOTAL PARTS AMOUNT		0	0	0	3537.5	No	Approve	

Labour

No.	Description	Adjusted Labour Amount	Adjusted Paint Amount	Action	Comment
1	TOTAL LABOUR AMOUNT	592.14	0	Approve	
	5 W/DAYS				

Miscellaneous

No.	Name	Adjusted Amount	Action	Comment

Paint Labour/Material Ratio

Paint Labour Ratio
 Paint Material Ratio
 Cash Loss

20.0
 80.0
 false