

ASS. REC. BY:

REF:

A15/22008313/ke

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

26

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

30/8 @ 780.00 CASH

Veh No:

S14D 5271K

Yr Regn:

01, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

406400

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB31-4003079117

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: Fin 79

195/65R15

R:

Pailon

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

P

mm

L/Bal.

7

mm

L/Bal.

P

mm

D.O.A.

11/3/22

D.O.I.

29/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rec

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

NOT AUTHORIZED

\$780/1

AAD2205-064

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5271K

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

26 AUG 2022

SHD5271K

JTDKB3FU003079117

200303878K

TOYOTA

PRIUS

11/05/2022

SNE6012J/ Allianz

25/01/2019

PART

- 1 PANEL SUB-ASSY, REAR DOOR, LH
- 1 FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, LH
- 1 COVER, REAR DOOR OUTSIDE HANDLE, LH
- 1 HINGE ASSY, REAR DOOR, LOWER LH
- 1 HINGE ASSY, REAR DOOR, UPPER LH
- 1 TAPE, BLACK OUT, NO.1 REAR LH
- 1 TAPE, BLACK OUT, NO.2 REAR LH
- 1 TAPE, BLACK OUT, NO.3 REAR LH
- 1 MOTOR ASSY, POWER WINDOW REGULATOR, REAR LH
- 1 REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH
- 1 COVER, REAR BUMPER
- 1 FILLER, REAR BUMPER EXTENSION, LH
- 1 MOULDING ASSY, BODY ROCKER PANEL, LH
- 1 RIM
- 1 PANEL SUB-ASSY, QUARTER, LH
- 1 LINER, REAR WHEEL HOUSE, LH

LIST

\$	R	1,294.90
\$	R	193.50
\$	R	17.90
\$	R	87.10
\$	R	98.90
\$	nn	21.90
\$	nn	34.90
\$	nn	15.40
\$	Sn	926.00
\$	Sn	206.70
\$	R	442.60
\$	Sn	123.70
\$	Sn	594.80
\$	R	1,900.10
\$	R	871.50
\$	R	139.80

TOTAL \$ 6,527.10

25% \$ 1,631.78

\$ 4,895.33

Special Nett

- 1 FENDER CLIP
- 1 FENDER LINER CLIP
- 1 REAR BUMPER CLIP
- 1 TYRE
- 1SET DOOR WEATHERSTRIP CLIP
- 1 REAR DOOR STICKER TEL. NO
- 1SET CLIP, ROCKER PANEL MOULDING

\$	nn	65.00	X
\$	nn	65.00	X
\$	nn	65.00	X
\$	Sn	350.00	X
\$	Sn	65.00	X
\$	nn	100.00	born ✓
\$	Sn	65.00	X

TOTAL

\$ 710.00

TOTAL PARTS

\$ 5,605.33

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,400.00 *601*

Putty And Spray Painting Of The Affected Portion.

\$ *6601* 1,400.00 *6601*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *nn* 240.00 *X*

To Check Electrical Lighting Concerned.

\$ *nn* 170.00 *X*

TOTAL \$ 3,590.00

Over All Total \$ 9,195.33

(PART-BY-PART) Repair Days

20 days

14 day
2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: