

Enquire Vehicle's Insurance Particulars (As At 29 Jun 2022 / 16:00:00)

Vehicle No.:

XD9087K

Make Description/Model:

MITSUBISHI / FUSO FV51SJD2DEA

Insurance Company Name:

AXA INSURANCE PTE LTD

Business Transaction Reference No.:

20220630155222382245

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	30/06/2022 17:08 (SGT)
Reported by	Driver
Date of Accident	29/06/2022 16:00 (SGT)
Exact Location of Accident	Fort Rd, Singapore
Additional Location Information	TO MARINA DRIVE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE5150S
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	MEGA GAS ENTERPRISE PTE LTD
Company Reg No	200205814Z
Email Address	SALES@MEGAGAS.COM.SG
Mobile Phone No	(Phone) +65-65674000
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Dyna
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2982

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Policy Number / Cover Note Number	P2347750

DRIVER

Name of Driver	PENG ZHIQIANG
Passport No/FIN	G2988729U
Date Of Birth	29/01/1989
Occupation	Outdoor



Date Of Driving Pass	08/07/2020
Driving experience	1 YEAR AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98322769
Alt. Phone Number	-
Email Address	SALES@MEGAGAS.COM.SG
Address	161 BUKIT MERAH CENTRAL #04-3747
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD9087K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	RAMACHANDRAN GANAPATHY
Passport No/FIN	G7412723T



Contact Number	(Phone) +65-91247024
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

I AM AWARED THAT MY INSURER MAY HAVE A **14 DAYS TIMEFRAME** FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29/6/2022 at about 16.00pm. I drove my lorry no GRE 5150S along Fort Rd toward Marina Dr, when I reach the place of Fort Rd so I go straight at the traffic light junction Green light. The car and the motorcycle vehicle in front me slow down. I also slow down my lorry no GRE 5150S. Suddenly the Big lorry behind me with vehicle no XD 9087K and hit onto my lorry no GRE 5150S Rear Body and front portion Rear End panel and Diesel tank damaged.

(my lorry no GRE 5150S very damaged.)

- ☐ Claim own policy
- ☒ Claim third party
- ☐ Claim OD / TP at other works hop
- ☐ For record purpose

LYS

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Policy No. _____
Insurer _____ Veh. No. _____

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

30-6-22

213 Pon

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

INVOICE

To: Mega Gas Enterprise Pte Ltd
28D Pioneer Sector 2
Singapore 628407

Date : 08/08/2022

Invoice No : IV22-08006/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle GBE 5150S (Inclusive Of Photographs And Transport Charges) Our reference : CAS/22-08/006	\$1,882.00
Total	\$1,882.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Mega Gas Enterprise Pte Ltd
28D Pioneer Sector 2
Singapore 628407

Date : 08/08/2022

Reference No : CAS/22-08/006

General Information

Registration No. : GBE 5150S
Accident Date : 29/06/2022

Particulars of Damaged Vehicle

Colour	: Multi	Make & Model	: Toyota Dyna 150 Manual
Engine Capacity	: 2982 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 273049	Engine No.	: 1KD2507261
Chassis No.	: JTFAT35Y90K204688	Steering	: In Order
Registration Date	: 22/12/2015	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	195R15	FALKEN	90%
L/H Front Tyre	195R15	FALKEN	90%
R/H Rear Tyre	155R12 (D)	FALKEN	90% / 90%
L/H Rear Tyre	155R12 (D)	FALKEN	90% / 90%

Inspection

Repairer : LYS Engineering
65 Chestnut Avenue, #18-15, Singapore 679524

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$46,846.48
Revised Amount : \$34,350.00
Less Excess : -
Nett Total : \$34,350.00

Remarks

- (A) Survey was done on 30/06/2022
- (B) Re-survey was done on 05/07/2022 & 08/07/2022
- (C) Re-survey after repair was done on 02/08/2022
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Constant Appraiser Services

Vehicle No : GBE 5150S

Our ref : CAS/22-08/006

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT – LIST ITEMS</u>			
1	1pc	Diesel EGR control valve	Dented	174.85	174.85
2	2pcs	Engine mounting L/R @ \$172.50	Serviceable	345.00	-
3	1pc	Front cabin end panel	Repair	1,461.80	-
4	1pc	Front cabin end panel glass	Cracked	220.60	220.60
5	1pc	Front cabin end panel glass rubber	Necessary	116.20	116.20
6	1pc	Front cabin opener handle	Bent/Twisted	311.20	311.20
7	2pcs	Front cabin safety lock bracket @ \$195.60	Bent	391.20	391.20
8	2pcs	Front cabin safety lock L/R @ \$265.50	Bent	531.00	531.00
9	1pc	Fuel exhaust injector	Dented/Bent	1,217.10	1,217.10
10	1pc	Fuel exhaust injector pipe	Bent	372.25	372.25
11	1pc	Fuel injector bracket	Bent	381.90	381.90
12	1pc	Value assy vacuum	Dented	173.82	173.82
13	1pc	Gear box mounting	Torn	182.10	182.10
14	1pc	Water pump	Dented/Jammed	272.50	272.50
15	1pc	Radiator assy	Mounting Broken	1,217.45	1,217.45
16	1pc	Radiator fan blade	Serviceable	281.90	-
17	1pc	Radiator fan clutch	Bent/Jammed	371.25	371.25
18	1pc	Radiator fan cowling	Broken	274.45	274.45
19	1pc	Rear exhaust silencer gasket	Necessary	43.75	43.75
20	1pc	Rear exhaust silencer pipe	Dented/Bent	781.90	781.90
21	2pcs	Rear exhaust silencer rubber mounting @ \$61.10	Distorted	122.20	122.20
22	1pc	Rear floor carrier	Dented/Warped	6,914.00	6,914.00
23	1pc	Rear number plate bracket	Bent	291.40	291.40
24	2pcs	Rear number plate lamp @ \$69.60	Cracked	139.20	139.20
25	1pc	Rear spare tyre carrier bracket	Repair	174.45	-
26	1pc	Tailgate	Dented	1,137.00	1,137.00
27	4pcs	Tailgate hinge @ \$64.40	Bent/Jammed	257.60	257.60
28	2pcs	Tailgate opener handle @ \$213.10	Dented/Bent	426.20	426.20
29	2pcs	Tailgate rubber stopper bracket @ \$135.00	Bent	270.00	270.00
30	2pcs	Tailgate rubber stopper @ \$43.10	Cut/Deformed	86.20	86.20
31	2pcs	Taillamp bracket @ \$93.00	Bent/Twisted	186.00	186.00
32	2pcs	Taillamp @ \$251.30	Cracked/Broken	502.60	502.60

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT – LIST ITEMS (CONT'D)</u>			
33	2pcs	Side gate flip lock handle @ \$213.10	Dented/Jammed	426.20	426.20
34	2pcs	Side gate flip lock handle pin holder @ \$26.00	Bent	52.00	52.00
35	2pcs	Side gate flip lock handle pin @ \$22.00	Necessary	44.00	44.00
36	10pcs	Side gate hinge @ \$64.40	Bent	644.00	644.00
37	2pcs	Side gate L/R @ \$1,812.55	Dented/Twisted	3,625.10	3,625.10
38	1pc	Swirl control valve	Damaged	1,538.70	1,538.70
39	1pc	Air cleaning box	Broken	598.90	598.90
				26,557.97	24,294.82
		Less 25%		(6,639.49)	(6,073.70)
			Sub total	19,918.48	18,221.12
		<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>			
1	1pc	Gearbox	Jammed/Oil Leaked	3,500.00	3,500.00
2	1pc	Propeller shaft	Bent	800.00	800.00
3	1bot	Gearbox oil	Necessary (50%)	100.00	50.00
4	4ltrs	Rear axle oil @ \$20.00	Necessary (50%)	80.00	40.00
5	1bot	Coolant	Necessary (50%)	60.00	30.00
6	1pc	Fan belt	Cut (50%)	96.00	48.00
7	1bot	Radiator coolant	Necessary (50%)	50.00	25.00
8	1set	Reverse sensor	Damaged	250.00	220.00
9	1pc	Rear carrier front inner board	Broken	600.00	600.00
10	12pcs	Rear carrier floor wooden board @ \$250.00	Broken	3,000.00	3,000.00
11	9pcs	Rear carrier floor wooden beam @ \$80.00	Broken	720.00	720.00
12	1pc	Tailgate inner wooden board	Broken	600.00	600.00
13	2pcs	Side gate inner wooden board @ \$800.00	Broken	1,600.00	1,600.00
14	3pcs	Rear carrier front wooden guard @ \$250.00	Broken	750.00	750.00
15	4sets	Side gate top wooden guard @ \$650.00	Broken	2,600.00	2,600.00
16	16pcs	Side gate wooden guard holder @ \$12.00	Bent/Twisted	180.00	180.00
17	1pc	Rear number plate	Dented	40.00	40.00
18	1pc	Tailgate '70km/h' sticker	Necessary	12.00	12.00
19	1pc	Tailgate 'flammable gas' sticker	Necessary	25.00	25.00
20	1pc	Tailgate outer aluminium board	Dented	500.00	500.00
21	2pcs	Side gate outer aluminium board @ \$900.00	Broken/Twisted	1,600.00	1,600.00

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS (CONT'D)</u>			
22	4pcs	Silicon for aluminium board @ \$40.00	Necessary	160.00	160.00
23	50pcs	Bolt & nut set @ \$1.50	Necessary	75.00	75.00
24	1pc	Company advertisement	Necessary	1,000.00	800.00
			Part total	38,316.48	36,196.12
		<u>LABOUR & MISC. CHARGES</u>			
1		To remove, reinstall electrical wiring harness, check lighting, resetting & rewire for parking sensor		100.00	60.00
2		To remove, reinstall transmission gearbox & propeller shaft		480.00	300.00
3		To remove, reinstall rear carriage		450.00	350.00
4		To respray painting on the change bodyparts, repair portion & where consistent to the accident		2,500.00	2,000.00
5		To remove & change exhaust silencer box with pipe, realign where necessary consistent to the accident		100.00	70.00
6		To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct & re-align body structure, body alignment & damaged consistent to the accident		2,500.00	2,200.00
7		To apply anti-rust chemical on repaired & replaced panel		200.00	150.00
8		To repair & straighten chassis member & realign back position		1,200.00	800.00
9		To remove & replace rear wooden board & beam		1,000.00	800.00
			Grand total	46,846.48	42,926.12
Recommended cost of lump sum repair (To its pre-accident condition)					34,350.00

Constant Appraiser Services

Vehicle No : GBE 5150S

Our ref : CAS/22-08/006

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$34,350.00** on a contractual basis. Under normal circumstances, the repair period would be about **32 (Thirty Two)** working days.

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA

INVOICE

65 Chestnut Ave #18-15, Singapore 679524
Tel: 6674 8965 Fax: 6674 8965 Hp: 9730 8695
Email: lys88@yahoo.com.sg

Specialise in Motor Repairing, Welding, Panel Beating, Spray Painting, Side Guide, Accident Claims, General Insurance Agents, ROV Inspection, Insurance Claim.

For **LYS ENGINEERING**

INVOICE

65 Chestnut Ave #18-15, Singapore 679524
Tel: 6674 8965 Fax: 6674 8965 Hp: 9730 8695
Email: lys88@yahoo.com.sg

Specialise in Motor Repairing, Welding, Panel Beating, Spray Painting, Side Guide, Accident Claims, General Insurance Agents, ROV Inspection, Insurance Claim.

[illegible]

Invoices not paid within 30 days of date, interest at the rate of 1.5% interest per month will be carry out until settled.
All cheques should be crossed & made payable to "LYS ENGINEERING".

TOTAL \$	120.	00
----------	------	----

LYS ENGINEERING

Customer's Signature & Official Stamp

E. & O. E.

For **LYS ENGINEERING**

CASH SALES/INVOICE**No: 0004092****James Towing Services**Blk 288 Yishun Ave 6 #07-50 Singapore 760288
James Low HP: 9015 7488 • 9811 9966**24 Hrs**
Towing Services
拖车服务日期
Date:

29/6/2022

寶號
Messre:

Cash

車號

Vehicle No:

GBE 51505

型號

Model No:

LORRY 10

由

From:

Fort Rel

到

To:

3 Pioneer 2004th

時間 (日夜)

Time (day/night)

600p

to 1800p

其他

Other:

3 Pioneer 2004th to 7 Soon Le Est

現金

CASH\$

12000

CHEQUE:

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTES: Vehicle is towed at owner's risk. The company accepts no responsibility for damage or other misdemeanor to your vehicle whilst being towed.

收貨人

Received by

經手人

Issued by

AXA INSURANCE PTE LTD

Original

8 Shenton Way, #24-01
 AXA Tower, Singapore 068811
 Customer Centre #01-21
 Tel 1800 8804988
 E-mail: www.axa.com.sg
 GST Registration Number: 199903512M
 Customer Care Centre



Agent Code: 05254

Policy No. / or / P2347750

Extension for Road Tax (For Fleet)

SmartDrive Quote Ref

MOTOR COVER NOTE

No. CN169489

- The Motor Vehicle (Third Party Risks and Compensation) Act (Cap 189) - Republic of Singapore, or
- The Road Transport Act 1987 of Malaysia, or
- The Agreement between the Minister of Finance (Singapore) and the Motor Insurers' Bureau of Singapore dated 22 February 1975, or
- The Agreement between the Minister for Transport (Malaysia) and the Motor Insurers' Bureau of West Malaysia dated 30 March 1992,
- And any subsequent revisions to the above Acts and Agreements

The Insured mentioned in the Schedule, having proposed for insurance in respect of the Motor Vehicle described in the Schedule, is hereby **HELD COVERED** under the terms of the Company's usual form of Motor Policy applicable thereto for the period mentioned in the Schedule unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

SCHEDULE

THE COMPANY	AXA INSURANCE PTE LTD
INSURED	MEGA GAS ENTERPRISE PTE LTD
INSURED BUSINESS REGISTRATION NO	200205814Z
MAKE AND DESCRIPTION OF VEHICLE	TOYOTA DYNA 150 MANUAL
VEHICLE REGISTRATION NO	0PE51505
YEAR OF MANUFACTURE	2015
ENGINE NO.	1KD2507261
CHASSIS NO	JTFAT35Y90K204688
ENGINE CAPACITY TONNAGE	1.79 TONS
COVER TYPE	COMPREHENSIVE
WEE PURCHASE	NIL
VALUE - \$	AS PER MARKET VALUE
PERIOD OF INSURANCE	FROM: 22/06/2022 TO: 21/06/2023
EXCESS - \$	700.00
AXA PREMIUM WORKSHOP?	YES

THIS CERTIFICATE RELATES TO THE INSURANCE POLICY WHICH IS ISSUED IN ACCORDANCE WITH THE PROVISIONS OF THE MOTOR VEHICLE (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) AND PART IV OF THE ROAD TRANSPORT ACT 1987 (MALAYSIA).

AXA INSURANCE PTE LTD

Authorized Signatory

AXA Insurance Agency on 18/04/2022 11:24 pm

Note: This Cover Note is only valid for 60 days from the date of issue unless replaced by the Certificate of Insurance issued by the Company.

- Premium for time on risk will be charged subject to minimum of \$553.50 (inclusive of GST) if the policy is cancelled after the inception date.
- An administrative fee of \$526.75 (inclusive of GST) will be charged:
 - Cover note issued and cancelled before inception.
 - Retaining the old registration number for a new vehicle insuring with AXA.

PREMIUM WARRANTY

For Individual Customers:

Please note that the premium in full should be paid before inception date shown above in order for the insurance cover to be valid.

For Non-Individual Customers:

Please note that where the period of cover is for more than 60 days, the premium in full should be paid within 60 days of inception (initial) endorsement. For all other cases, the premium in full should be paid before inception.

0% 25% 50% 75% 100%

71022Jt

Register New Vehicle (Acknowledgement)

Vehicle Particulars

Vehicle No.:	GBES1505		
Vehicle Type:	B31 - Goods (Open) Lorry (Metal Body)/Pickup	Vehicle Scheme:	Normal
Vehicle Attachment 1:	No Attachment		
Vehicle Attachment 2:	-	Vehicle Attachment 3:	-
Vehicle Make:	TOYOTA	Vehicle Model:	TOYOTA DYNA 150 MANUAL
Chassis No.:	JTFAT35Y90K204688	Engine No.:	1KD2507261
Motor No.:	-	Trailer Chassis No.:	-
Propellant:	Diesel	Passenger Capacity:	2
Engine Capacity:	2982 cc	Power Rating:	-
Maximum Power Output:	-		
Unladen Weight:	1880 kg	Maximum Laden Weight:	3500 kg
Primary Colour:	White	Secondary Colour:	-
First Registration Date:	22 Dec 2015	Original Registration Date:	22 Dec 2015
Manufacturing Year:	2015	Open Market Value:	\$27,855.00
PARF Eligibility:	No	Minimum PARF Benefit:	\$0.00
No. of Transfers:	0	Additional Registration Fee Rate:	5.00%

Owner Particulars

Owner Name: MEGA GAS ENTERPRISE PTE. LTD.

Owner ID Type: Company

Owner ID: 200205814Z

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 28D

Registered Street Name: PIONEER SECTOR 2

Registered Unit No.: -

Registered Building Name: -

Registered Postal Code: 628407

COE No. / Expiry Date: 20151222050013230 / 21 Dec 2025

COE Bid Category: C - Goods Vehicle & Bus

POP Paid: \$27,677.00

62685115
FAX

Transaction Details

Business Transaction Ref. No.: 20151222114537559461

Business Transaction Date: 22 Dec 2015

Business Transaction Time: 11:45:37

Message

The above vehicle has been successfully registered.

Please note that \$6,230.00 will be deducted from your GIRO account.

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner/Partnership

Owner ID Type:	Company
Owner ID:	0142

Vehicle Details

Vehicle No:	ORE151505
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Jun 2022
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	White
Manufacturing Year:	2015
Engine No:	1KDZ507261
Chassis No:	JTFAT35Y90K204685
Maximum Power Output:	
Open Market Value:	\$27,856.00
Original Registration Date:	22 Dec 2015
First Registration Date:	22 Dec 2015
Transfer Count:	0
Actual APF Paid:	\$1,283.00

Import and PARF Details (if applicable)

PARF Eligible:	No
PARF Eligibility Expiry Date:	
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	21 Dec 2025
COE Category:	C - Vehicle Vehicle & Bus
COE Period (years):	10
POF Paid:	\$27,672.00
COE Rebate Amount:	\$9,612.00
Total Rebate Amount:	\$9,612.00

COE Period/Year(s):

10

PQP Paid:

\$27,677.00

COE Rebate Amount:

\$9,612.00

Total Rebate Amount:

\$9,612.00

✓

The information contained herein is correct as at 29 Jun 2022