

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 29-Aug-22

INSURANCE: Erigo

MODEL: TOYOTA PRIUS G5

VEHICLE NO.: SH 8575 M

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
PANEL SUB-ASSY, FRONT DOOR, RH <i>ryu</i>	1	\$ 1,769.60	\$1,769.60	X
FRONT DOOR HINGE UPPER <i>HH</i>	1	\$ 115.22	\$115.22	X
FRONT DOOR HINGE LOWER <i>HH</i>	1	\$ 127.68	\$127.68	X
FRONT DOOR CHECK <i>HH</i>	1	\$ 214.93	\$214.93	X
FRONT DOOR OUTER MOULDING <i>HH</i>	1	\$ 264.04	\$264.04	X
FRONT DOOR WHETHER STRIP <i>HH</i>	1	\$ 641.06	\$641.06	X
FRONT DOOR COMFORT LOGO <i>hec</i>	1	\$ 105.00	\$105.00	✓
BONNET <i>torn / broken</i>	1	\$ 1,330.70	\$1,330.70	✓
INSULATOR, HOOD <i>torn</i>	1	\$ 557.34	\$557.34	✓
INSULATOR CLIPS <i>hec</i>	10	\$ 5.04	\$50.40	✓
BONNET RUBBER <i>hec</i>	1	\$ 49.70	\$49.70	✓
BONNET CABLE <i>HH</i>	1	\$ 74.48	\$74.48	X
BONNET HINGE (RH) <i>st</i>	1	\$ 80.78	\$80.78	✓
BONNET HINGE (LH) <i>st</i>	1	\$ 80.78	\$80.78	✓
BONNET LOCK <i>st</i>	1	\$ 185.64	\$185.64	✓
CATCH, HOOD AUXILIARY HOOK <i>HH</i>	1	\$ 12.04	\$12.04	X
RADIATOR GRILLE <i>broken</i>	1	\$ 813.20	\$813.20	✓ 316.87
RADIATOR GRILLE EMBLEM <i>dislodged / mostly cracked</i>	1	\$ 123.20	\$123.20	✓ 79.35
RADIATOR GRILLE EMBLEM LOWER GARNISH <i>cut</i>	1	\$ 268.30	\$268.30	✓ 120.37
FRONT BUMPER COVER G5 <i>torn</i>	1	\$ 1,322.48	\$1,322.48	✓ 586.18
FRONT BUMPER REINFORCEMENT <i>Dental</i>	1	\$ 974.96	\$974.96	✓ 716.60
FRONT BUMPER REINFORCEMENT ABSORBER LH/RH <i>HH</i>	2	\$ 161.98	\$323.96	X
FRONT BUMPER LOWER REINFORCEMENT BRACKET LH/RH <i>HH</i>	2	\$ 462.00	\$924.00	X
ABSORBER, FRONT BUMPER, LOWER REINFORCEMENT <i>HH</i>	1	\$ 178.78	\$178.78	X
FRONT BUMPER SPONGE <i>torn</i>	1	\$ 110.32	\$110.32	✓
FRONT BUMPER LOWER GRILLE <i>broken</i>	1	\$ 208.04	\$208.04	✓
LAMP ASSY, FOG, RH <i>H mostly broken</i>	1	\$ 1,288.00	\$1,288.00	✓ 961.70
FRONT NO. PLATE GARNISH <i>broken</i>	1	\$ 138.60	\$138.60	✓ 89.60
FRONT BUMPER CLIPS <i>hec</i>	1	\$ 30.80	\$30.80	✓
FRONT BUMPER SIDE RETAINER LH/RH <i>h/s HH o/s broken</i>	2	\$ 107.80	\$215.60	✓ 77.00
FRONT BUMPER TOP GARNISH <i>broken</i>	1	\$ 315.56	\$315.56	✓ 225.40
FRONT BUMPER SIDE GARNISH LH/RH <i>src</i>	2	\$ 216.90	\$433.80	X
COVER, FRONT BUMPER HOLE, LH/RH <i>o/s dislodged h/s HH</i>	2	\$ 39.73	\$79.46	✓
REINFORCEMENT, FRONT BUMPER LOWER <i>broken</i>	1	\$ 330.54	\$330.54	✓
BRACKET, FRONT BUMPER EXTENSION MOUNTING <i>HH</i>	1	\$ 154.56	\$154.56	X
SUPPORT FR BUMPER, LH/RH <i>HH</i>	2	\$ 114.38	\$228.76	X
FRONT BUMPER CENTRE FRAME <i>HH</i>	1	\$ 331.66	\$331.66	X
BRACKET, FRONT BUMPER SIDE, LH/RH <i>HH</i>	2	\$ 115.22	\$230.44	X
FRONT CHASSIS MEMBER SIDE COVER (RH) <i>HH</i>	1	\$ 196.50	\$196.50	X
UNIT ASSY, HEADLAMP, LH/RH (LED) <i>o/s broken h/s mostly broken</i>	2	\$ 4,837.00	\$9,674.00	✓ 5470.56
HEADLAMP ECU <i>mostly broken o/s</i>	1	\$ 2,176.20	\$2,176.20	✓ 682.60
HEAD LAMP PANEL (LH/RH) <i>Dental 240.10 x 2</i>	2	\$ 336.14	\$672.28	✓ 480.20
TOP PANEL CENTRE <i>Dental</i>	1	\$ 510.97	\$510.97	✓ 364.98

2735.28 x 2

13331.18

TOP PANEL SIDE LH/RH <i>O/S Dent</i> <i>H/S reg</i>	2	\$ 204.26	\$408.52	✓
BRACE PANEL <i>vt</i>	1	\$ 105.28	\$105.28	✓
BRACKET, HEADLAMP MOUNTING, LH/RH <i>HH</i>	2	\$ 35.70	\$71.40	X
HEADLAMP BULB <i>HH</i>	1	\$ 48.02	\$48.02	X
RADIATOR ASSY <i>vt</i>	1	\$ 2,578.52	\$2,578.52	✓ 1841.80
COOLANT <i>HH</i>	1	\$ 45.00	\$45.00	X
RADIATOR FAN MOTOR ASSY <i>broken</i>	1	\$ 1,093.90	\$1,093.90	✓ 925.82
*RADIATOR TOP HOSE <i>broken</i>	1	\$ 60.24	\$60.24	✓
RADIATOR SPARE TANK <i>broken mounting</i>	1	\$ 176.12	\$176.12	✓
RADIATOR BOTTOM MOUNTING <i>HH</i>	2	\$ 38.50	\$77.00	X
STAY, RADIATOR SUPPORT, LH/RH <i>HH</i>	2	\$ 91.98	\$183.96	X
DEFLECTOR, RADIATOR SIDE, LH/RH <i>HH</i>	2	\$ 116.90	\$233.80	X
COVER, RADIATOR SUPPORT OPENING <i>HH</i>	1	\$ 315.56	\$315.56	X
RESERVE TANK ASSY, RADIATOR W/O CAP <i>HH</i>	1	\$ 553.42	\$553.42	X
HORN (1 PC) <i>socket broken</i>	1	\$ 157.79	\$157.79	✓
AIR CLEANER HOUSING ASSY <i>crack/broken</i>	1	\$ 836.70	\$836.70	✓
AIR CLEANER HOSE <i>HH</i>	1	\$ 86.97	\$86.97	X
AIR DUCT <i>broken</i>	1	\$ 181.16	\$181.16	✓
INLET ASSY, AIR CLEANER <i>HH</i>	1	\$ 278.88	\$278.88	X
AIR DUCT CENTRE <i>svz</i>	1	\$ 131.64	\$131.64	X
CONDENSER ASSY, W/RECEIVER <i>vt</i>	1	\$ 1,871.24	\$1,871.24	✓ 1336.60
AIRCON DISCHARGE HOSE <i>vt broken</i>	1	\$ 541.66	\$541.66	✓ 386.90
AIRCON LIQUID HOSE & PIPE <i>vt</i>	1	\$ 812.63	\$812.63	✓ 580.45
AIRCON HOSE SUCTION <i>vt</i>	1	\$ 758.62	\$758.62	✓ 541.87
FENDER SUB-ASSY, FRONT RH <i>Dent</i>	1	\$ 1,323.42	\$1,323.42	✓ 1111.93
FRONT HOUSING ASSY RH <i>reg</i>	1	\$ 1,323.36	\$1,323.36	X
FRONT FENDER SHIELD RH <i>torn</i>	1	\$ 277.90	\$277.90	✓
FRONT FENDER SHIELD CLIP <i>HH</i>	1	\$ 20.86	\$20.86	✓
FRONT FENDER HYBRID EMBLEM, RH <i>HH</i>	1	\$ 121.10	\$121.10	✓ 86.50
BRACKET, FRONT SIDE PANEL, RH <i>HH</i>	1	\$ 62.30	\$62.30	X
EXTENSION, FRONT FENDER, RH <i>HH</i>	1	\$ 66.08	\$66.08	X
SEAL, FRONT FENDER TO COWL SIDE, RH <i>HH</i>	1	\$ 21.28	\$21.28	X
GUSSET, FRONT FENDER APRON, LOWER RH <i>HH</i>	1	\$ 48.86	\$48.86	X
EXTENSION, FRONT FENDER APRON, FRONT RH <i>HH</i>	1	\$ 32.48	\$32.48	X
MEMBER, FRONT APRON TO COWL SIDE, UPPER RH <i>HH</i>	1	\$ 193.76	\$193.76	X
FRONT APRON TO COWL SIDE, LOWER FRT RH <i>HH</i>	1	\$ 115.22	\$115.22	X
FRONT WINDSCREEN GLASS <i>crack</i>	1	\$ 2,278.22	\$2,278.22	✓ 1627.30
FRONT WINDSCREEN GLASS MOULDING <i>HH</i>	1	\$ 292.04	\$292.04	✓ 208.60
ARM, FRONT WIPER, RH <i>vt / distorted</i>	1	\$ 252.14	\$252.14	✓
BLADE, FRONT WIPER, RH <i>HH</i>	1	\$ 207.06	\$207.06	X
WIPER TOP GARNISH <i>broken</i>	1	\$ 935.65	\$935.65	✓ 686.90
WIPER SPARE TANK <i>many broken</i>	1	\$ 257.25	\$257.25	✓
WIPER SPARE TANK MOTOR <i>Den</i>	1	\$ 339.78	\$339.78	✓
WIPER SPARE TANK FLOAT (NECK) <i>torn / distorted</i>	1	\$ 77.70	\$77.70	✓
FRONT WHEEL RIM <i>HH</i>	1	\$ 2,198.77	\$2,198.77	X
FRONT WHEEL CAP <i>HH</i>	1	\$ 246.12	\$246.12	X
FRONT WHEEL HUB BEARING <i>HH</i>	1	\$ 783.92	\$783.92	X
FRONT SUSPENSION LOWER ARM (RH) <i>HH</i>	1	\$ 884.66	\$884.66	X
FRONT SHOCK ABSORBER (RH) <i>HH</i>	1	\$ 557.48	\$557.48	X
ABSORBER TOP MOUNTING RH <i>HH</i>	1	\$ 274.68	\$274.68	X
FRONT DRIVE SHAFT (RH) <i>HH</i>	1	\$ 2,469.60	\$2,469.60	X
RACK & PINION ASSY <i>HH</i>	1	\$ 2,269.82	\$2,269.82	X
BAR, STABILIZER <i>HH</i>	1	\$ 493.36	\$493.36	X
LINK ASSY, FRONT STABILIZER, RH <i>HH</i>	1	\$ 275.52	\$275.52	X
KNUCKLE, STEERING, RH <i>HH</i>	1	\$ 813.12	\$813.12	X

JOINT ASSY, LOWER BALL, FRONT RH	HH	1	\$ 279.97	\$279.97
ENGINE MOUNTING (RH)	Denki	1	\$ 535.78	\$535.78
ENGINE MTG (FRONT)	HH	1	\$ 244.48	\$244.48
ENGINE MTG (REAR)	HH	1	\$ 242.06	\$242.06
ENGINE TOP COVER	broken	1	\$ 364.00	\$364.00
BRAKE MASTER PUMP	Wack / Dom	1	\$ 8,930.18	\$8,930.18
SUB TOTAL				\$69,632.38
LESS 20% 25%				\$13,926.48
DISCOUNTED TOTAL				\$55,705.90
FRONT NO. PLATE	1st	SN 1	\$ 35.00	\$35.00
FRONT NO. PLATE TRIM COVER	broken	SN 1	\$ 42.00	\$42.00
FRONT TYRE (RH)	HH	SN 1	\$ 302.40	\$302.40
BRAKE FLUID	HH	SN 1	\$ 80.00	\$ 80.00
FRONT WINDSCREEN SEALANT	HH	SN 1	\$ 120.00	\$ 120.00
SUB TOTAL				\$579.40
Labour Charge				
Panel Beating		1	\$ 2,000.00	\$2,000.00
Spray Painting Charge		1	\$ 1,600.00	\$1,600.00
Wiring Charge		1	\$ 100.00	\$100.00
Tuff Kote		1	\$ 100.00	\$100.00
Towing Charge		1	\$ 80.00	\$80.00
Transfer of Door Mechanism FRONT		1	\$ 80.00	\$80.00
Re-set Frt Power Window System		1	\$ 200.00	\$200.00
Four Wheel Alignment		1	\$ 120.00	\$120.00
Remove/Refix Undercarriage (Frt)		1	\$ 400.00	\$400.00
Remove/Refix Radiator		1	\$ 90.00	\$90.00
Remove/Refix Aircon & Refill Gas		1	\$ 130.00	\$130.00
Remove/Refix Front Windscreen Glass		1	\$ 120.00	\$120.00
Remove/Refix Steering Rack/Wheel/Dr Shaft		1	\$ 150.00	\$150.00
Remove/Refix Brake Master & Booster Pump		1	\$ 120.00	\$120.00
Diagnostic & Resetting To Erase Fault Code		1	\$ 550.00	\$550.00
TOTAL LABOUR				\$5,840.00
ESTIMATE TOTAL				\$62,125.30

after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

30/08/2022 @ 0945h

NA Andri

26,297.69

Supp 3,055.88

P/P 29,353.57

11 8 days.

2kk Andri

Check all prices

Provide EV before
Tuesday.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

BIFROST AUTO PTE LTD

SUPPLEMENTARY

DATE: 31-Aug-22

INSURANCE: Ergo

MODEL: TOYOTA PRIUS G5

VEHICLE NO.: SH 8575 M (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
BONNET STAND <i>st</i>	1	\$ 285.72	\$285.72
FRONT LOWER CROSSMEMBER <i>mt</i>	1	\$ 500.78	\$500.78
*RADIATOR RETUEN HOSE INLET <i>brn</i>	1	\$ 160.24	\$160.24
*RADIATOR RETURN HOSE OUTLET <i>brn</i>	1	\$ 159.64	\$159.64
FRONT WINDSCREEN LOWER MOULDING <i>hec</i>	1	\$ 185.45	\$185.45
WIPER TOP GARNISH PANEL <i>Double</i>	1	\$ 1,125.38	\$1,125.38
ENGINE VALVE COVER <i>brn/hec</i>	1	\$ 1,568.58	\$1,568.58
ENGINE VALVE COVER RUBBER <i>hec</i>	1	\$ 268.85	\$268.85
SUB TOTAL			\$4,254.64
LESS 20% <i>25%</i>			\$850.93
DISCOUNTED TOTAL			\$3,403.71
ESTIMATE TOTAL			\$3,403.71

after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

1
yn

2Kk Auto

8

4,074.51

25%

3,055.88

63529.01

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SH8575M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	31 Aug 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Blue
Manufacturing Year:	2020
Engine No.:	2ZR2G75252
Chassis No.:	JTDKB3FU003091171
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	19 Feb 2020
First Registration Date:	19 Feb 2020
Transfer Count:	0
Actual ARF Paid:	\$14,530.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Feb 2028
PARF Rebate Amount:	\$10,897.00
Intended COE Rebate Details	
COE Expiry Date:	18 Feb 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$26,431.00
COE Rebate Amount:	\$18,066.00
Total Rebate Amount:	\$28,963.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 29 Aug 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	29/08/2022 12:29 (SGT)
Reported by	Driver
Date of Accident	28/08/2022 05:40 (SGT)
Exact Location of Accident	Orchard Rd, Singapore
Additional Location Information	TOWARDS ENTRANCE TO VOCO ORCHARD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH8575M
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-81814331
Alternative Phone No	(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1798

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Policy Number / Cover Note Number	VFX/P2419138

DRIVER

Name of Driver	YEO POON CHUAN
NRIC No	SXXXX495D
Date Of Birth	27/10/1954
Occupation	Outdoor

Date Of Driving Pass	01/07/1975
Driving experience	47 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-81814331
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 840 TAMPINES STREET 82 #11-107
Address complement	-
Postcode	520840
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	RELIEF DRIVER
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	UNKNOWN
Gender	Male

PASSENGER 2

Name	UNKNOWN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 28.08.2022 AT ABOUT 0540HRS I WAS DRIVING MY VEHICLE A SH8575M FETCHING MY PASSENGERS TO EMERALD HILL. NEAR VOCO HOTEL, MY VEHICLE A WAS ON THE 3RD LANE OF ORCHARD ROAD WHEN VEHICLE B GBH2021K ON MY LEFT CUT INTO MY LANE SUDDENLY. HENCE MY VEHICLE A FRONT COLLIDED ONTO VEHICLE B RIGHT REAR. UPON IMPACT MY PASSENGERS AND MYSELF HURT OUR NECK, SHOULDER AND BACK. AMBULANCE CAME AND ATTENDED TO US BUT WE ARE NOT CONVEYED. PASSENGERS THEN TOOK ANOTHER TAXI.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes



DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH2021K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	UNKNOWN
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	YEO POON CHUAN
Gender	Male
Phone No	(Phone) +65-81814331
Address	BLK 840 TAMPINES STREET 82 #11-107
Address Complement	-
Post Code	520840
Approximate Age Years Old	-
Injuries Sustained	HURT OUR NECK ,SHOULDER AND BACK.
Injured person in which vehicle?	SH8575M
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

A - SH8575M

B - GBH 2021K

VOCO HOTEL

ORCHARD ROAD



Describe Circumstances of the Accident

ON 28.08.2022 AT ABOUT 0540HRS I WAS DRIVING MY VEHICLE A SH8575M FETCHING MY PASSENGERS TO EMERALD HILL. NEAR VOCO HOTEL, MY VEHICLE A WAS ON THE 3RD LANE OF ORCHARD ROAD WHEN VEHICLE B GBH2021K ON MY LEFT CUT INTO MY LANE SUDDENLY. HENCE MY VEHICLE A FRONT COLLIDED ONTO VEHICLE B RIGHT REAR. UPON IMPACT MY PASSENGERS AND MYSELF HURT OUR NECK, SHOULDER AND BACK. AMBULANCE CAME AND ATTENDED TO US BUT WE ARE NOT CONVEYED. PASSENGERS THEN TOOK ANOTHER TAXI


Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel


29.08.2022 1055HRS

