(06/11/15)	REF:		
ASS. REC. BY:			
	ASS	SIGNMENT	~
From:	Date:	Veh No: 5L34487	Yr Regn: 28 11, 2016
Estimated Cost:		Type: MC / M.Cycle / Bus / Van / Lor	ry / Taxi / Prime Mover /
OD / TP / WS / TP RES / O	D RES / EVA / INV / MV	Truck / Trailer or	
To Inspect Vehicle No:		Make: tyota	A4,5 cc 1598
	Trumwork harage	Colour One 4	A/C: Insured / Std / NI / NA
of	icon in the interest of the in	Sp.Reading 52676 9	T/Radio: Insured / Std / NI / NA
Insured:	+XA	Eng/No:	
-		C/No: MR 053RET	1104560223
Claima No.		Gen. Cond: Good / Fir / Poor / Burnt	
Sum Insured:	Excess:	Steering: In reer / Jammed / Leaked / I	Burnt or
(Client's Record)		Brake: Inforder / Jammed / Leaked / Burnt or	
Make of Veh:		Modi: Nii / S/Rim / STI A/Rim or	
		Tyre Size: F: 205/55 R 6	
(Policy Condition)		r: 205/55K16	
Remark: The veh had commenced its		BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /	
repair at the time of inspection.		TOYO/YOKO or GITI	
Bal. or Market Value:	62 V	Front	Rear
-	Consistent? : Yes or No	R/Bal. 6 mm	R/Bal5mm
IDAC Accident Rport:	Consistent? : Yes or No	L/Bal. 6 mm	L/Bal. 5 mm
GIA / PR Seen:	days Res.: Yes or No	D.O.A15/08/22	D.O.I. 29/8/2022
Est. Repairs:	% 3 Val.: Yes or No		ork harage
LUIII SUUI.		Des. of Damages : Frt / Rear / O/S / (U/S / U/C / Rooftop or	
CA / REV / REP. / 24	HRS Vehicle: IN / OUT		
Date: Person		The U/C / Chassis frame / Body S	Structure affected due to collision.
Date / Time Action / Ins			
Date / Time Action / Inc			MV: 63K
			NY: 2016
Date/Time, File Pass to?	: Preli. Report	Days Of Repair:	
	: Final Report	Resurvey No. of Trip:	Survey Fee:
) Date/Time, File Return to?			Transportation:
	Add Fee:)S + RS,SI
		: Interview (\$) Photos
		: Tech. Invs (\$) Others
CDOIL CO.)	:Weekend (\$)
ump Sum / I.B.I: (\$	/		TOTAL