

08/11/13) wef

ASS. REC. BY: Marcus

REF:

CCG/CT/22008389/4ea3

### ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBC 6549E  
1st's mo

at Workshop m/s

of

Insured:

GBC 4550X

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value:

8k.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

196N

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBC 6549E

Yr Regn:

25/06/13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Car /

Make:

Toyota hiace

C.C

2982

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

259500

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFH 202500117343

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

23/08/22

D.O.I.

30/08/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 10k.

Core used 24-06-2023 MP 4433

7/8/22 1/s & 1600 informed Susan.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS. SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

)

ESTIMATE  
29-08-2022  
GBC6549E220823  
GBC6549E  
Toyota Hiace  
Manual

$$\begin{array}{r} p-1987.5 \\ 252 \\ \hline 1490.62 \\ 170 \\ 410 \\ \hline 2070.62 \\ 208 \\ \hline 1656. \end{array}$$