

ASS. REC. BY:

REF:

MSG / 220084001K9

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Smm 9407D

Yr Regn:

07.19

Type: M.Capt / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Vial E

c.c

1496

Colour

m Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

106814

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR 2B 23F 3901182859

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD / Rlm or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

27/8/22

D.O.I.

30/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

& 177

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Policy No.

msig.

KANG

AUTO ENGINEERING PTE LTD

Sin Ming Auto City

160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015

Email: kangauto@singnet.com.sg



Not Authored

Returning After Repair

M/S CHEN SONG WAH
BLK 722 WOODLANDS AVENUE 6
#09-540
SINGAPORE 730722

POLICY NO : THIRD PARTY CLAIM
OUR REF : TP22/08/1170
VEHICLE NO : SMM9407D
MAKE/MODEL : TOYOTA VIOS
DATE OF ACCIDENT : 27.8.22

1	PC	BONNET			S\$	R	965.20	✓
1	PC	BONNET LOCK				R	310.00	X
1	PC	BONNET HINGE				R	165.00	X
1	PC	FRONT BUMPER				R	780.00	✓
1	PC	FRONT BUMPER BRACKETS				R	85.00	X
2	PCS	FRONT BUMPER SIDE RETAINER	25.00	EA		R	50.00	X
1	PC	FRONT BUMPER REINFORCEMENT				R	225.00	?
1	PC	FRONT BUMPER CLIPS				R	38.00	✓
1	PC	FRONT BRACE PANEL					195.00	?
1	PC	FRONT GRILLE				CM	380.20	✓
1	PC	FRONT BADGE				R	60.00	✓
1	PC	BOOTLID				R	992.20	✓
1	PC	BOOTLID EMBLEM				R	54.20	✓
1	PC	BOOTLID 'VIOS' BADGE				R	45.17	✓
1	PC	BOOTLID 'E' BADGE				R	49.73	✓
1	PC	BOOTLID RUBBER				Nil/Nil	186.50	✓
1	SET	BOOTLID HINGES				R	65.70	X
1	PC	BOOTLID LOCK				R	122.01	✓
1	PC	REAR END PANEL				R	888.10	✓
1	PC	REAR END PANEL TOP GARNISH				Nil	298.60	✓
1	PC	REAR BUMPER				R	799.50	✓
1	SET	REAR BUMPER CLIPS				R	35.00	✓
2	PCS	REAR BUMPER SIDE RETAINER	dis/ir	89.07	EA		178.14	✓
2	PCS	REAR BUMPER LOWER LID BRACKETS		58.00	EA		116.00	?
2	PCS	TAILLAMP ASSY	MSI X	dis ?	328.50	EA	657.00	
2	PCS	TAILLAMP PANELS		dis ?	121.60	EA	243.20	
2	PCS	REAR REFLECTORS	dis/ir	128.70	EA		257.40	✓
1	PC	REAR UNDER COVER					180.00	?
1	PC	EXHAUST SILENCER					558.10	?
					LESS 25%		8,979.95	
					S\$		2,244.99	
							6,734.96	

Specialised in :

Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

KANG

AUTO ENGINEERING PTE LTD

Sin Ming Auto City



160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015
Email: kangauto@singnet.com.sg

M/S CHEN SONG WAH
BLK 722 WOODLANDS AVENUE 6
#09-540
SINGAPORE 730722

POLICY NO : THIRD PARTY CLAIM
OUR REF : TP22/08/1170
VEHICLE NO : SMM9407D
MAKE/MODEL : TOYOTA VIOS
DATE OF ACCIDENT : 27.8.22

1 PC REAR NUMBER PLATE
1 SET REVERSE SENSOR
1 SET CAMERA

S\$ *Sm* 40.00 S'NETT X
od 300.00 *2000*
Sm 300.00 X

TO CHECK WIRING
TO REMOVE & REFIT EXHAUST SILENCER
TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL
TO PUTTY AND SPRAY PAINT CHARGES
LABOUR CHARGES

S\$ 30.00 ✓
80.00 *600*
120.00 *900*
2,400.00 *1200*
1,800.00 *1000*
S\$ 11,804.96

SGD ELEVEN THOUSAND EIGHT HUNDRED FOUR AND CENTS NINETY-SIXTY
ONLY.

YOURS FAITHFULLY,


KANG AUTO ENGINEERING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

BASIC INFORMATION

Date of Accident:	27/8/22	Time of Accident:	21:30 PM
Exact Location:	BUKIT TIMAH ROAD		

DETAILS OF OWN VEHICLE

Vehicle Registration No.	SMM 9407D	NRIC / FIN / Passport no:	S746995JI
Name of Registered Owner:	CHEN SONG NAM		
Owner's Email:			
Owner's Address:	BKT 722 NOODLANDS AVE 6 #09-540 S730722		
Vehicle Make:	TOY	Vehicle Model:	VIOS 1.5E
Engine Capacity (cc):		Transmission:	Auto / Manual
Type of Claim:	Own Damage / Third Party / Reporting Only		
Vehicle Category:	Private / Commercial / Motorcycle / Private Hire		
Name of Insurance Co:	AIG		
Type of Policy:	Comprehensive / Third Party / Third Party, Fire & Theft		
Policy Number:	1900129681-03		

DRIVER

Name of Driver:	<input checked="" type="checkbox"/> same as		
NRIC / FIN / Passport no:		Date of Birth:	01.08.1974
Occupation:	Indoor / Outdoor	Driving Pass Date:	25.07.1997
Contact Number:		Gender:	Male / Female
Address:			
Relationship with Owner:	Owner / Employee / Spouse / Child / Hirer / Other:		

GENERAL INFORMATION OF THE ACCIDENT

Type of Collision:	Chain collision / Side Swipe / Front to Rear / Others:		
Weather Condition:	Clear / Raining / Others:		
Road Surface:	Dry / Wet / Others:		
Was anybody injured?	Yes / No	Police Report Made?	Yes / No
No. of passenger onboard (including driver):	1		

DETAILS OF OTHER VEHICLE

	Vehicle 1	Vehicle 2	Vehicle 3
Vehicle Registration No:	SLT2566Z	SMM 4328G	
Vehicle Make / Model:			
Name of Driver:			
NRIC / FIN / Passport no:			
Contact Number:			
Name of Insurance Co:			

DETAILS OF WITNESS

Name:		Contact Info:	
-------	--	---------------	--

DETAILS OF INJURED PERSON

	Person 1	Person 2	Person 3
Name / in which vehicle?:	CHEN SONG NAM SMM 9407D		

Driver's Declaration: I declare that the information given in this report are true and accurate to the best of my collection and I bear full responsibility for any consequences arising from incomplete or inaccurate information that are submitted.



Signature of Driver

Date and time



**SINGAPORE
POLICE FORCE**



T/20220829/2133

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

2 of 3

Report No. T/20220829/2133

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMM9407D	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1900129681-03	19/07/2022	18/07/2023

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHEN SONG WAH	ID No.	S7469952I
Related Vehicle	SMM9407D (Car)	Contact No.	81861121
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	28/08/2022	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On 27/08/2022 at 2130hrs, I was traveling (SMM9407D) along Bukit Timah Road towards Beauty World near First Ave. I was traveling on the second lane.

While I was traveling, I noticed the front vehicle slowed down and came to a stop. As such, I also follow and stopped. Suddenly, I felt an impact from the rear. Due to the impact, my vehicle moved forward and hit onto the front vehicle (SMM4328G). I alighted to make a check and I realized that one vehicle (SLT2566Z) hit onto my vehicle's rear. Total there are 3 vehicles involved in the accident. My vehicle is the second vehicle. The first vehicle is SMM4328G, and the last vehicle is SLT2566Z. No one was injured at the point of time. No police or ambulance was activated. My vehicle has an in-car camera. I exchange particulars with the drivers and took some photos of the accident.

On 28/08/2022, I felt pain on my back and neck area. As such, I went to see a doctor and gotten 5 days of medical certificate.

Particulars of the drivers

SMM4328G - Kumaresan S/O K Adaikkappan, S1487780J, HP: 90773544
SLT2566Z - Frederick Hong Shi Hao, S9218823Z, HP: 81863951

**SINGAPORE
POLICE FORCE**

T/20220829/2133

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

1 of 3

Report No. T/20220829/2133

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/08/2022 14:04		Vide Report No.:		Station Diary No.: 23	
Informant's Particulars					
Name of Informant: CHEN SONG WAH			Address: APT BLK 722 WOODLANDS AVENUE 6 #09-540 SINGAPORE 730722		
ID Type / ID No.: NRIC NO / S7469952I			Contact No.: Home/Office: Mobile: 81861121		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 48	Date of Birth: 01/08/1974	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: AIR CON MECHANIC			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 27/08/2022 21:30	Type of Location: Straight Road
Location: BUKIT TIMAH ROAD				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLT2566Z	Car					1
SMM4328G	Car					1
SMM9407D	Car	TOYOTA	VIOS 1.5 E (AUTO)	Silver		0

Details of Vehicle Insurance						
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date		