

ASS. REC. BY:

REF: SMOI 22008421Kc

K Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: _____

at Workshop n/s Chen Loan Optima

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Ham
(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 811k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 10/23 Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJK 2602 8 Yr Regn: 10, 08

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Vios c.c. 1497

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 295835 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053149 305081312

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Turador

Front _____ Rear _____

R/Bal. 4 mm R/Bal. 5 mm

L/Bal. 6 mm L/Bal. 3 mm

D.O.A. 27/8/22 D.O.I. 31/8/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>Car BZ</u>

Date/Time, File Pass to? : Prell. Report : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

- Add Fee: : Site Insp (\$ _____)
- : Interview (\$ _____)
- : Tech Invs (\$ _____)
- : Weekend (\$ _____)

Transportation	_____
S - RS	_____
Fixings	_____
Others	_____
TOTAL	_____

Report Format : _____
Lump Sum / I.B.I: (\$ _____)

趙源摩哆 Chew Goon Motor

Bik 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

*Not Authorized
 11 Aug @
 Return After Paint
 7 days*

To: Sompo Insurance Singapore Pte Ltd

Policy No: _____
 Third Party

Date: 30.08.2022

Accident Date : 27.08.2022

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Toyota Vios" Reg. No. SJK2602Z Claiming Against Your Insured Veh. No. SLN4847G			
1pc	Boot		Ry 871.00 ✓
2pcs	Boot Hinges	65.00	R 130.00 X
1pc	Boot Emblem		na 65.00
1pc	Boot Badge VIOS		na 63.00
1pc	Boot Badge E		na 54.00
1pc	Boot Outer Moulding		na 245.00
1pc	Boot Lock		na 123.00
1pc	Boot Lock Catch		R 38.50 X
1pc	Boot Stopper RH		na 13.20
1pc	Boot Weatherstrip		Ref ID 226.00 50% na
1pc	Rear Bumper		Ry 522.00
12pcs	Rear Bumper Clips	5.00	na 60.00
1pc	Rear Bumper Bracket RH		121.00
2pcs	Rear Bumper Top Retainers	97.00	dis 194.00 L
2pcs	Rear Bumper Reflectors	150.00	dis 300.00 L
2pcs	Rear Bumper Corner Retainers	90.00	dis 180.00 L
2pcs	Taillamps	372.00	CM 744.00
2pcs	Taillamp Gaskets	25.00	na 50.00
2pcs	Taillamp Panels	159.00	dis 318.00 L
1pc	End Panel		Ry 764.00
1pc	End Panel Garnish		CM 242.00
1pc	Spare Tyre Top Board		dis 164.00
2pcs	Boot Compartment Storage Styrofoam Boards	283.00	CM 566.00
1pc	Rear Fender RH	1,070.00	R 900.00 X
1pc	Rear Joint Panel (Taillamp-Fender)		R 198.00
2pcs	Rear Fender Trim Boards	285.00 <i>dis</i>	570.00 L
1pc	Rear Windscreen Moulding		na 155.00
1pc	Rear Exhaust Silencer		820.00 7
1pc	Rear Exhaust Silencer Gasket		42.00 7
Less 25%			8,738.70
			2,184.68
			6,554.03
	Rear Number Plate		Ry 45.00 SN ✓
	Rear Bumper Reverse Sensor		na 280.00 SN
	Rear Windscreen Sealant		na 50.00 SN X
	Rear Windscreen Sealer		na 40.00 SN X
	Rear Windscreen Fastener		na 50.00 SN X
	Roadside Assist Signage		CM 45.00 SN ✓
	Portable Vacuum Cleaner		na 110.00 SN X
			C/F 7,174.03

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Sompo Insurance Singapore Pte Ltd

Policy No: Third Party

Date: 30.08.2022

Accident Date : 27.08.2022

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Toyota Vios" Reg. No. SJK2602Z Claiming Against Your Insured Veh. No. SLN4847G		
		B/F	7,174.03
	To Conduct Electrical Check, Replace Reverse Sensors, Module, Rewiring etc.		120.00 <i>5d</i>
	To Dismantle / Refit Rear Windscreen Glass		<i>na</i> 160.00 <i>X</i>
	To Dismantle / Refit Trunk Compartment Boards & Trims		80.00 <i>✓</i>
	To Dismantle / Transfer Boot Fittings / Ancillary Accessories		100.00 <i>5d</i>
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 <i>6d</i>
	To Repair / Replace & Align Muffler / Exhaust System		120.00 <i>6d</i>
	To Supply End Panel / Rear Fender Body Joint Sealant		<i>na</i> 80.00 <i>X</i>
	Labour Charge - Panel Beating, Repairing Of Rear Chassis, Inner Panel, Floor Panel, Spare tyre Panel, Rear N/S Fender etc. Cnt, Weld End Panel, Rear Fender & Part Replacement		1,800.00 <i>100d</i>
	To Spray Painting Affected Areas (Rr Fender, Taillamp Panels *2, End Panel, Spare Tyre Panel Boot, Boot Garnish, Bumper, Bumper Sensors. Joint Panels *2 Etc...)		<i>100d</i> 1,800.00
		Total :	11,534.03

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be completed by the **Policyholder and/or the Actual Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 29/08/2022 10:48 (SGT)
Reported by Both
Date of Accident 27/08/2022 22:45 (SGT)
Exact Location of Accident Singapore
Additional Location Information BUKIT TIMAH
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJK2602Z

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner HO MUN KAY
NRIC No SXXXX505D
Email Address HOMUNKAYSTANLEY@GMAIL.COM
Mobile Phone No (Phone) +65-96157903
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Toyota
Model Vios
Variant TOYOTA / VIOS E AUTO
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private hire
Transmission Auto
CC 1497

INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Policy Number / Cover Note Number 5095700267-04

DRIVER

Name of Driver HO MUN KAY
NRIC No SXXXX505D
Date Of Birth 04/12/1966
Occupation Outdoor

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A: 95KJ6027

B: SLN48476



**SINGAPORE
POLICE FORCE**



T/20220828/2032

1 of 3

Report No. T/20220828/2032

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/08/2022 13:20	Vide Report No.:	Station Diary No.: 46
--	------------------	--------------------------

Informant's Particulars

Name of Informant: HO MUN KAY		Address: APT BLK 153 LORONG 2 TOA PAYOH #15-606 SINGAPORE 310153	
ID Type / ID No.: NRIC NO / S1771505D		Contact No.:	Mobile: 96157903
Nationality: SINGAPORE CITIZEN		Home/Office:	
Email:			
Sex: Male	Age: 55	Date of Birth: 04/12/1966	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: SENIOR ENGINEERING SPECIALIST		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 27/08/2022 22:45	Type of Location: Straight Road
Location: BUKIT TIMAH ROAD				
Weather: Raining		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJK2602Z	Car	TOYOTA	VIOS E AUTO	Silver	Seriously Damaged	1
SLN4847G	Car	HONDA	VEZEL 1.5X CVT	Blue	Seriously Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJK2602Z	NTUC Income Insurance Co-Operative Limited	5095700267-04	14/10/2021	13/10/2022



**SINGAPORE
POLICE FORCE**



T/20220828/2032

2 of 3

Report No. T/20220828/2032

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	HO MUN KAY	ID No.	S1771505D
Related Vehicle	SJK2602Z (Car)	Contact No.	96157903
Hospital/Clinic	RAFFLESMEDICAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	28/08/2022	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	NIL
Driver			
Name	MANDINO TAN CHUN TZE	ID No.	S9439935A
Related Vehicle	SLN4847G (Car)	Contact No.	87426769
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 27/08/2022 at around 2245hrs, I was driving along Bukit Timah Road in my vehicle (SJK2602Z). I then applied my brake as the vehicle in front of me slowed down. As my car was about to come to a stop I then felt a impact from the rear of my vehicle. As my leg were still on the brakes I managed to avoid a collision with the vehicle in front of me.

After I stop my vehicle, both me and the driver (SLN4847G) behind me came out of our car and took photos and exchanged particulars. We then left shortly after. No traffic police or ambulance was dispatched.

On 28/08/2022 after waking up, I felt sore on my neck area and went to consult a doctor at RafflesMedical and was given 5 days of MC.