

ASS. REC. BY:

REF: SM01 22008421Kc

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Chen Guan ~~Optima~~

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____


(Client's Record)

Make of Veh: _____

Ham

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$11k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 10/23 Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJK 2602 8 Yr Regn: 10, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toy Vios c.c. 1497

Colour: M. Grey A/C: Insured / Std / Nil / NA

Sp. Reading: 295855 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: NR05314Y9305081312

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Turador

Front

R/Bal. 4 mm

L/Bal. 4 mm

D.O.A. 27/8/22

Rear

R/Bal. 5 mm

L/Bal. 5 mm

D.O.I. 31/8/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Car BZ

2/9 11Pm 8535d Rmmit.

2/12 Kelly said will check and come back to us.

13/1/23 Kelly confirmed LS \$5,350.00; 7 days. (Red. 6184.03, 53%)

Date/Time, File Pass to?

: Prell. Report

: Final Report

1) Date/Time, File Return to?

Days Of Repair: 7

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS. SI

Fuel

Others

TOTAL

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format: TP

Lump Sum / I.B.I. (\$) \$5,350

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	505D
Vehicle Details	
Vehicle No.:	SJK2602Z
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Aug 2022
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1NZX802445
Chassis No.:	MR053HY9305081312
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$11,834.00
Original Registration Date:	14 Oct 2008
First Registration Date:	14 Oct 2008
Transfer Count:	0
Actual ARF Paid:	\$10,674.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Oct 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$15,142.00
COE Rebate Amount:	\$3,395.00
Total Rebate Amount:	\$3,395.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 29 Aug 2022

OK



SC1J228T0001 / Chew Goon Motor
 ENTRY DATE & TIME: 29/08/2022 10:48 (SGT)
 SUBMITTED BY: CG Pei Kee
 VERSION: 1 (29/08/2022 10:48 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	29/08/2022 10:48 (SGT)
Reported by	Both
Date of Accident	27/08/2022 22:45 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	BUKIT TIMAH
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJK2602Z

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	HO MUN KAY
NRIC No	SXXXX505D
Email Address	HOMUNKAYSTANLEY@GMAIL.COM
Mobile Phone No	(Phone) +65-96157903
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Vios
Variant	TOYOTA / VIOS E AUTO
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1497

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Policy Number / Cover Note Number	5095700267-04

DRIVER

Name of Driver	HO MUN KAY
NRIC No	SXXXX505D
Date Of Birth	04/12/1966
Occupation	Outdoor

Date Of Driving Pass	22/02/1991
Driving experience	31 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96157903
Alt. Phone Number	-
Email Address	HOMUNKAYSTANLEY@GMAIL.COM
Address	APT BLK 153 LORONG 2 TOA PAYOH #15-606
Address complement	-
Postcode	310153
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	UNKNOWN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Toa Payoh Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18002519999
Alt. Police Station Phone No	(Fax) +65-63548749
Police Station Address	93 Toa Payoh Central Toa Payoh Community Building #01-02 Singapore 319194
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT NO.T/20220828/2032.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLN4847G
Vehicle Manufacturer	Honda
Vehicle Model	Vezei
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	NA / Unknown
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	HO MUN KAY
Gender	Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SJK2602Z
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A: SJK 6027
B: SLN 48476


**SINGAPORE
POLICE FORCE**


T/20220828/2032

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

1 of 3
Report No. T/20220828/2032

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/08/2022 13:20	Vide Report No.:	Station Diary No.: 46
--	------------------	--------------------------

Informant's Particulars

Name of Informant: HO MUN KAY		Address: APT BLK 153 LORONG 2 TOA PAYOH #15-606 SINGAPORE 310153	
ID Type / ID No.: NRIC NO / S1771505D		Contact No.:	Mobile: 96157903
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 55	Date of Birth: 04/12/1966	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: SENIOR ENGINEERING SPECIALIST		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 27/08/2022 22:45	Type of Location: Straight Road
Location: BUKIT TIMAH ROAD				
Weather: Raining		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJK2602Z	Car	TOYOTA	VIOS E AUTO	Silver	Seriously Damaged	1
SLN4847G	Car	HONDA	VEZEL 1.5X CVT	Blue	Seriously Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJK2602Z	NTUC Income Insurance Co-Operative Limited	5095700267-04	14/10/2021	13/10/2022



**SINGAPORE
POLICE FORCE**



T/20220828/2032

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

2 of 3
Report No. T/20220828/2032

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	HO MUN KAY	ID No.	S1771505D
Related Vehicle	SJK2602Z (Car)	Contact No.	96157903
Hospital/Clinic	RAFFLESMEDICAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	28/08/2022	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	NIL
Driver			
Name	MANDINO TAN CHUN TZE	ID No.	S9439935A
Related Vehicle	SLN4847G (Car)	Contact No.	87426769
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 27/08/2022 at around 2245hrs, I was driving along Bukit Timah Road in my vehicle (SJK2602Z). I then applied my brake as the vehicle in front of me slowed down. As my car was about to come to a stop I then felt a impact from the rear of my vehicle. As my leg were still on the brakes I managed to avoid a collision with the vehicle in front of me.

After I stop my vehicle, both me and the driver (SLN4847G) behind me came out of our car and took photos and exchanged particulars. We then left shortly after. No traffic police or ambulance was dispatched.

On 28/08/2022 after waking up, I felt sore on my neck area and went to consult a doctor at RafflesMedical and was given 5 days of MC.



**SINGAPORE
POLICE FORCE**



T/20220828/2032

3 of 3

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

Report No. T/20220828/2032

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report: E / SGT 1 LER RONG XUN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 28/08/2022 13:20
Officer In Charge Of Case: TP / GIA / SR STAFF SGT MUHAMMAD NOOR BIN ABDUL RAHMAN Contact No.: 65476219	Classification Of Case:

NP168

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

*Not Authorized
 U Sing @ 5350/2
 Return After Paint
 Delay*

To: Sompo Insurance Singapore Pte Ltd

Policy No: _____
 Third Party

Date: 30.08.2022

Accident Date : 27.08.2022

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Toyota Vios" Reg. No. SJK2602Z Claiming Against Your Insured Veh. No. SLN4847G			
1pc	Boot <i>681.20</i>	65.00	<i>RH</i> 871.00 ✓
2pcs	Boot Hinges		<i>R</i> 130.00 X
1pc	Boot Emblem		<i>na</i> 65.00
1pc	Boot Badge VIOS		<i>na</i> 63.00
1pc	Boot Badge E		<i>na</i> 54.00
1pc	Boot Outer Moulding		<i>na</i> 245.00
1pc	Boot Lock		<i>na</i> 123.00
1pc	Boot Lock Catch		<i>R</i> 38.50 X
1pc	Boot Stopper RH	<i>113.20</i>	<i>na</i> 13.20
1pc	Boot Weatherstrip		<i>na</i> 226.00 <i>502.10</i>
1pc	Rear Bumper <i>488.10</i>		<i>RH</i> 522.00
12pcs	Rear Bumper Clips	5.00	<i>na</i> 60.00
1pc	Rear Bumper Bracket RH		<i>diy</i> 121.00
2pcs	Rear Bumper Top Retainers	97.00	<i>diy</i> 194.00
2pcs	Rear Bumper Reflectors <i>0105.40</i>	150.00	<i>diy</i> 300.00
2pcs	Rear Bumper Corner Retainers	90.00	<i>diy</i> 180.00
2pcs	Taillamps <i>0355.40</i>	372.00	<i>CM</i> 744.00 <i>110.20</i>
2pcs	Taillamp Gaskets	25.00	<i>na</i> 50.00
2pcs	Taillamp Panels	159.00	<i>diy</i> 318.00
1pc	End Panel <i>055.10</i>		<i>RH</i> 764.00
1pc	End Panel Garnish <i>165.80</i>		<i>CM</i> 242.00
1pc	Spare Tyre Top Board		<i>diy</i> 164.00
2pcs	Boot Compartment Storage Styrofoam Boards <i>0142.10</i>	283.00	<i>CM</i> 566.00 <i>284.20</i>
1pc	Rear Fender RH	1,070.00	<i>R</i> 900.00 X
1pc	Rear Joint Panel (Taillamp-Fender)		<i>RH</i> 198.00
2pcs	Rear Fender Trim Boards <i>0150.00</i>	285.00	<i>na</i> 570.00
1pc	Rear Windscreen Moulding		<i>na</i> 155.00
1pc	Rear Exhaust Silencer <i>585</i>		<i>RH</i> 820.00
1pc	Rear Exhaust Silencer Gasket		<i>na</i> 42.00
	Less 25%		8,738.70
			2,184.68
			6,554.03
	Rear Number Plate		<i>RH</i> 45.00 SN ✓
	Rear Bumper Reverse Sensor		<i>na</i> 280.00 SN
	Rear Windscreen Sealant		<i>na</i> 50.00 SN X
	Rear Windscreen Sealer		<i>na</i> 40.00 SN X
	Rear Windscreen Fastener		<i>na</i> 50.00 SN X
	Roadside Assist Signage		<i>CM</i> 45.00 SN ✓
	Portable Vacuum Cleaner		<i>na</i> 110.00 SN X
		C/F	7,174.03

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: Sompo Insurance Singapore Pte Ltd

Policy No: Third Party

Date: 30.08.2022

Accident Date : 27.08.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Toyota Vios" Reg. No. SJK2602Z Claiming Against Your Insured Veh. No. SLN4847G		
		B/F	7,174.03
	To Conduct Electrical Check, Replace Reverse Sensors, Module, Rewiring etc.		120.00 <i>50d</i>
	To Dismantle / Refit Rear Windscreen Glass		<i>na</i> 160.00 <i>X</i>
	To Dismantle / Refit Trunk Compartment Boards & Trims		80.00 <i>✓</i>
	To Dismantle / Transfer Boot Fittings / Ancillary Accessories		100.00 <i>50d</i>
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 <i>60d</i>
	To Repair / Replace & Align Muffler / Exhaust System		120.00 <i>60d</i>
	To Supply End Panel / Rear Fender Body Joint Sealant		<i>na</i> 80.00 <i>X</i>
	Labour Charge - Panel Beating, Repairing Of Rear Chassis, Inner Panel, Floor Panel, Spare tyre Panel, Rear N/S Fender etc. Cnt, Weld End Panel, Rear Fender & Part Replacement		1,800.00 <i>1000d</i>
	To Spray Painting Affected Areas (Rr Fender, Taillamp Panels *2, End Panel, Spare Tyre Panel Boot, Boot Garnish, Bumper, Bumper Sensors. Joint Panels *2 Etc...)		<i>1000d</i> 1,800.00
	Total :		<u>11,534.03</u>

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: