(05/11/18) wef

ASS. REC. BY:

REF:

2920

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMB 8032R

at Workshop m/s SMRT

of 60 Woodlands Ind PK E4

Insured: NTUC

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMB 8032R Yr Regn: 2015 / OCT

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: MAN / NG363F CA24) c.c 10518

Colour MULTI A/C: Insured / Std / NI / NA

Sp.Reading 291128 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WMAA24228F7002735

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/70R22.5

R: " " D/O

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	8 mm	R/Bal.	8/8 mm
L/Bal.	8 mm	L/Bal.	8/8 mm
D.O.A.	06/07/22	D.O.I.	18/07/22

Survey held at SMRT

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or FRT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

05/09/2022 Finalise L/S $4,300.00 and 3 days (Red $1,472.43/ 26%)

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($) ___S + RS, ___SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)