

ASSIGNMENT

Front: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lrn Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJT 88552 Yr Regn: 7/12/17
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Honda Civic Type R c.c. 1996
Colour: White A/C: Insured / Std / Nil / NA
Sp. Reading: 16175 T/Radio: Insured / Std / Nil / NA
Eng/No: _____
C/No: SHHEK8790H4001512
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modl: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 225/45R17
R: _____

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
TOYO/YOKO or.

Front Rear

R/Bal. 5 mm	R/Bal. 5 mm
L/Bal. 5 mm	L/Bal. 5 mm
D.O.A. 11/8/22	D.O.I. 11/9/22

Survey held at Kok Wang

Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

Date/Time, File Pass to?

☐: Prel. Report

17/01 Typist

Final Report

Date/Time, File Return to?

2)

Report Format : SMART CLAIMS - TP

Lump Sum ~~(1.0): 00~~ 7450 .)

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$)

☐ : Interview (\$

	: Tech, Invs (\$
--	------------------

☐ : Weekend (\$)

Survey Fee:

Transportation:

$$) \quad \underline{\hspace{1cm}} S + RS \cdot \underline{\hspace{1cm}} SI$$

1 Photos

Others

TOTAL

Kok Wang Car Grooming
1 Soon Lee Street #06-40 Pioneer Centre
Singapore 627605
Hp: 91839633 E-mail: vianong@gmail.com

ESTIMATE REPORT

Vehicle Number : SJT8855Z
 Make And Model : Honda Civic Type R
 Date of Accident : 22 August 2022

S/No	Parts	QTY	Unit Price	List Price
1	Rear bumper	1		\$ 2,150.00
2	Rear bumper center garnish	1		\$ 360.00
3	Rear bumper lower garnish	1		\$ 1,320.00
4	Rear bumper side garnish LH & RH	1-2	\$ 380.00	\$ 760.00
5	Rear bumper side reflector assy LH & RH	1-2	\$ 90.00	\$ 180.00
6	Rear bumper retainer LH & RH	2	\$ 40.00	\$ 80.00
7	Rear bumper cover finisher	1		\$ 60.00
8	Rear bumper towing cover	1		\$ 390.00
9	Rear bumper absorber	1		\$ 310.00
10	Rear bumper beam	1		\$ 670.00
11	Rear end panel	1		\$ 780.00
12	Rear end panel top garnish	1		\$ 120.00
				\$ 7,180.00
Less 20%				\$ 1,436.00
Total				\$ 5,744.00

Special Nett Item

1	Rear bumper clips	1 set	\$ 30	60.00
2	Reverse sensor	1 set		\$ 350.00
3	Rear end panel top garnish clips	1 set		\$ 40.00
4	Rear diffuser (Varis)	1 pc		\$ 3,300.00
Total				\$ 3,750.00

Labour & Misc Charges

To dismantle, replace & panel beating affected parts for rear portion.
 To spray paint on affected areas for rear portion.
 To remove/replace/reinstall rear panel upholstery & trim.
 To apply anti-rust on affected areas.
 To remove/refit reverse sensors.
 To check wiring for rear portion.

	\$ 1,000.00	250
	\$ 700.00	250
	\$ 200.00	50
	\$ 100.00	30
	\$ 100.00	30
	\$ 60.00	30
Total	\$ 2,160.00	

Grand Total : \$ 11,654.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Steve (LKK)
 2/9/22, 11.00

m n
 L/S
 M AL by
 4 days

Scanned with CamScanner