

Your Ref: 209/2021

Date: 21st Dec 2022

Our Ref: CS1/LAW22008440/Uqy3m4

M/s Jusequity Law Corporation

133 New Bridge Road
#10-03 Chinatown Point
Singapore 059413

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBK 3707T
INSURED VEHICLE: SLU 9731L
ACCIDENT DATE: 02/03/2020**

We thank you for your instruction on 29/08/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBK 3707T from M/s C L Appraiser Pte Ltd.
- b) Survey report by Ajax Inspection Services Pte Ltd with colour photographs.
- c) Singapore Accident Statement of Vehicles FBK 3707T and SLU 9731L.
- d) Police Report of Vehicle FBK 3707T.
- e) Colour damaged vehicle photographs of FBK 3707T.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FBK 3707T
Make & Model	: Kawasaki ZX1000N
Chassis Number	: JKAZXT00NNA002080
Year of Registration	: 2015
Engine Capacity	: 998 cc

- 2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.