PRELIMINARY INVESTIGATION REPORT FOR A GRAZING INCIDENT INVOLVING A 5TON (MID21522) AND A CIVILIAN VEHICLE (BLUE TOYOTA ALTIS) ALONG UPPER CHANGI FLYOVER ON 29 AUG 2022 AT ABOUT 1550HRS




Figure 1: Schematic Diagram part 1




Figure 1: Schematic Diagram part 2




Figure 1: Schematic Diagram part 3




Figure 1: Schematic Diagram part 4



Figure 2A: Front View of MID21522



Figure 2B: Rear View of MID21522



Figure 2C: Side View of MID21522



Figure 2D: Side View of MID21522



Figure 2E: Side View of MID21522



Figure 2F: Side View of MID21522

$OFFICIAL\ (CLOSED) \setminus SENSITIVE\ NORMAL$



Figure 2G: Damages to front Left Bumper of MID21522



Figure 2H: MID21522 Left Passenger Step (Zoomed in Damages)

SINGAPORE ARMED FORCES STATEMENT OF DRIVER-WITNESS

STATEMENT (OF LCF MULLIAMA	LCF Muhamad Frick & in Muhamad Diszum			
NRIC NO	3266	AGE	19	MALE/FEMALE	Male
EMPLOYMEN	TO	DRIVING LICENCE NO	00644/22	NATIONALITY	Singularian
DIALECT	LANGUAGE		English /major	TEL NO	
ADDRESS					
NTEAPRETE	O BY	PANK	TIME	DATE	SIGN
RECORDED I	BY .	RANK	TIME	DATE	SIGN
Change bush to SO I St Civition to Chack From the White St With My Wit	Flyover, I Start Sind be Safe and not write inching left au venile was on my on my left mirror towner, I thought towner, I thought towner thro my left towner. I further towner is a nice of a Nevil. So I was a Nevil.	sametze with feer I double blind spot, I , Shin I can't a Civilian we lest mirrors, mirrors, But have the forme out Scratches laited for 5 m errotz the line my PC, he S	the noment the other vehicles due theck may mirror convinue to inche spot any vehicle with he so that's who I had so the sold move forwards as he seet place on the left from the thinking the left to go to he and to go to he	to the load he to the load he founds the on my left is slow down into a civilian and three rim. I civilian which is seen that the confidence of the confiden	left while continuing until 1 feet a jerk and on the hazard light a vehicle come in contact hereign, where when I know I

SAF 1201/91

All statements and further statements are to be timed and dated. Witness will be re-warned immediately prior to the recording of further statements. Statements and further statements will be signed by the Recording Officer and interpreter.

Statements of witness must be signed by the witness.

Figure 3A: Statement of Driver





Figure 3B: Statement of Witness



Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
MID21522	5 TON			1	Slightly Damaged	0
SGJ895-J	Car				Slightly	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured; NIL	Use of Pedestrian Crossing: NA

Figure 4: Police Report #1 – Part 1



T/20220830/2127

Police Station Of Origin: Woodlands West N.P.C. 1 Woodlands Street 12 SINGAPORE 738622 Tel No: 1800-363 9999

Report No. 1720220830/2127

CONTINUATION OF REPORT

Driver		7	100	N. T. Tarret	15. 10.	
Name	MUHAMMAD FAIZAL BIN MUHAMMAD RIDZUAN			ID No	k.	326E
Related Vahide	MID21522 (5 TON)			Conte	act No.	
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL	
Date Treatment	NIL	The second	Date Disc	chame	NIL	
No. of Days granted Medical Leave NIL			Degree o		NIL	

Brief Details

I was at the Changi flyover and was on the 3rd lane and had signaled left and wanted to switch to the lane on my left. I had looked at my rear mirror and did not see any incoming vehicles and had proceeded to switch lanes. I then slowly switched lanes and suddenly I felt the jerk on my left rear and saw a vehicle going up the kerb. I then proceeded to stop infront when it was safe as the car was still moving. I came down to make a check on my vehicle and did not saw the other driver as well and I had left subsequently. We then viewed our in-cer camera and got the registration plate of the other vehicle as well. I would like to state that there was no traffic police nor ambulance at scene.

Figure 4: Police Report #1 – Part 2





Police Station Of Origin:
Woodlands West N.P.C.
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-363 9999 CONTINUATION OF REPORT

5 of 3 Report No. T/20220830/2127

Sketch Plan

Informant is not able to provide aketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report: L / SGT 3 CHOONG JIA LE, DION	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 30/08/2022 23:24
Officer In Charge Of Case: TP / GIA / SR STAFF SGT MUHAMMAD NOOR BIN ABDUL RAHMAN Contact No.: 65476219	Classification Of Case:
NP168	

Figure 4: Police Report #1 – Part 3



Figure 4:Police Report #2 – Part 1




Figure 4:Police Report #2 – Part 2




Figure 4:Police Report #2 – Part 3