



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA			Ref: CC4/ASM22008465/Kpa3q2 Date: 02/11/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 9409X	Veh. Inspected	SJV 786G
	Policy No.	P2465703	Coverage (\$)	0.00
	Claim No.	S2M049UO	Excess (\$)	0.00
	Assign From		Assign Date	30/08/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ E200K (A)	c.c	1796
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	WDB2110412B342320	Colour	METALLIC GREY
	Odometer	161030 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/45 R17	PIRELLI	7 mm
	L/H Front Tyre	245/45 R17	PIRELLI	7 mm
	R/H Rear Tyre	245/45 R17	PIRELLI	7 mm
	L/H Rear Tyre	245/45 R17	PIRELLI	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/08/2022	Inspection Date	31/08/2022
	Survey held at	CHEONG CHEONG MOTOR SERVICE PL BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-293 SINGAPORE 569535		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	