

ASSIGNMENT

From _____ Date: _____

File No: 8710 45582

Page 2019 March

Spec: Motor / H Cycle / Box / Van / Large / Fuel / Pump / Motor

Truck/Trailer at

Hyundai Ionig 1580

Color Blue

Sp. Reading: 359090

Eng No: G4LEB JU 192042

CNA: KMHC851CV KU141774

Gen. Cond: Good / Fair / Poor / Burnt

Steering Inboard / Jammed / Locked / Right or

Breaker: Inorder / Jammed / Leaked / Burnt or

1. STANDARD 1. STANDARD OF

Type Size: 195/65 R15

SS/DIA/EXDVA/GE/IS/LIA/INC/FOUO/IR/SUB/

3

5

LIBRARY S DATE

2022 26/08/2022

Superficial Biggest sin pump

Est. of Damages: \$K + \$R + \$S + \$T + \$U + \$V + \$W + \$X + \$Y + \$Z

... the ... of ...

~~The MC / Classic frame / Body Structure affected due to collision~~

HTWC SHC 7017A

03/01/23 Analyzed 41 (7.4%) - with 12 days of rain (red: 14,365.22, 45%)

☐ Preft Report

Final Report

4/1/23-typist

Days Of Repair 12

Reservoir No. of Traps 2

Add Fee: ☐ See Instructions

See Insp. (1)

Interviews

Topic: Jesus' life

Weekend 6

Report Format: TP

Lump Sum / LBL: (\$ 17,400

Summary

Transportation

... ..

There are

1998

10

1

•

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHD4558R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	31 Aug 2022
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	G4LEJU192042
Chassis No.:	KMHC851CVKU141474
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$24,921.00
Original Registration Date:	01 Mar 2019
First Registration Date:	01 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$11,890.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Feb 2027
PARF Rebate Amount:	\$8,917.00
Intended COE Rebate Details	
COE Expiry Date:	28 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$20,420.00
COE Rebate Amount:	\$11,486.00
Total Rebate Amount:	\$20,403.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 29 Aug 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	29/08/2022 11:14 (SGT)
Reported by	Driver
Date of Accident	26/08/2022 19:30 (SGT)
Exact Location of Accident	CTE, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD4558R
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-97790991
Alternative Phone No	(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Ae ioniq
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1580

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Policy Number / Cover Note Number	VFX/P2419138

DRIVER

Name of Driver	NASIR KHAN BIN PEROSIAH
NRIC No	SXXXX684F
Date Of Birth	25/04/1958
Occupation	Outdoor

Date Of Driving Pass	22/09/1986
Driving experience	35 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97790991
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 252 YISHUN RING ROAD #01-1071
Address complement	-
Postcode	760252
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	RELIEF DRIVER
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	UNKNOWN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Yishun North Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18008529999
Alt. Police Station Phone No	(Fax) +65-68522299
Police Station Address	31 Yishun Central Singapore 768827
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO POLICE REPORT NO. T/20220828/2046

ATTACHMENT(S)

Are accident photos available for attachment?	No
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE NOT SUITABLE

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFR96H
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	NASIR KHAN BIN PEROSIAH
Gender	Male
Phone No	(Phone) +65-97790991
Address	BLK 252 YISHUN RING ROAD #01-1071
Address Complement	-
Post Code	760252
Approximate Age Years Old	-
Injuries Sustained	GIDDINESS AND BACK PAIN
Injured person in which vehicle?	SHD4558R
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes


SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time
28/08/2022 2015HRS

Witnessed by Reporting Centre Personnel
FRO NAZREEN

Sketch Plan

A - SHD4558R

B - SFR96H

Describe Circumstances of the Accident

PLEASE REFER TO POLICE REPORT NO. T/20220828/2046

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time 28/08/2022 2015HRS

Witnessed by Reporting Centre
Personnel FRO NAZREEN

REPAIR ESTIMATE

31/08/2022 @ 1600m
 Hk + Ant 12 Check part price.
 + 15m last day.
 Bryan LKK Ant

Description	Qty	List Price	Amount
Boot Lid <i>src</i>	1	\$ 2,549.70	\$ 2,549.70
Boot Lid Rubber <i>damaged</i>	1	\$ 187.40	\$ 187.40
Boot Lid Hinge (LH/RH) <i>damaged</i>	2	\$ 71.30	\$ 142.60
Boot Lid Absorber (LH/RH) <i>src</i>	2	\$ 86.70	\$ 173.40
Boot Lid Lock Upper <i>Down / broken</i>	1	\$ 224.00	\$ 224.00
Boot Lid 'H' Emblem <i>Hec</i>	1	\$ 28.00	\$ 28.00
Emblem-Hybrid <i>Hec</i>	1	\$ 24.30	\$ 24.30
Emblem-Ioniq <i>Hec</i>	1	\$ 31.30	\$ 31.30
Rear Spoiler <i>monny broken</i>	1	\$ 665.40	\$ 665.40
Third Brake Light <i>src</i>	1	\$ 385.60	\$ 385.60
BOOT HANDLE <i>src</i>	1	\$ 31.80	\$31.80
Boot Lid Lamp(LH/RH) <i>crack / broken</i>	2	\$ 822.00	\$ 1,644.00
Boot Lid Trimboard <i>monny broken</i>	1	\$ 259.70	\$ 259.70
Boot Lid Trimboard Clips (10pcs) <i>Hec</i>	1	\$ 11.00	\$ 11.00
Boot Lid Trimboard, Centre <i>broken</i>	1	\$ 159.60	\$ 159.60
Boot Lid Trimboard SIDE (LH/RH) <i>damaged / monny broken</i>	2	\$ 92.50	\$ 185.00
Boot Lid Trimboard REAR <i>HW</i>	1	\$ 124.80	\$ 124.80
Boot Lid Glass, Lower <i>Shattered</i>	1	\$ 584.90	\$ 584.90
Boot Lid Glass Upper Moulding <i>HW</i>	1	\$ 186.30	\$ 186.30
Boot Lid Glass Lower Moulding <i>HW</i>	1	\$ 145.20	\$ 145.20
Rear Bumper <i>torn / Damaged</i>	1	\$ 459.40	\$ 459.40
Rear Bumper Reinforcement <i>crack / crack</i>	1	\$ 394.80	\$ 394.80
Rear Bumper Reinforcement Bracket (LH/RH) <i>st</i>	2	\$ 188.10	\$ 376.20
Antenna Assy-SMARTK outer <i>monny broken</i>	1	\$ 689.50	\$ 689.50
Rear Bumper Centre Moulding Assy <i>broken</i>	1	\$ 451.25	\$ 451.25
Rear Bumper Lower Centre Moulding Assy <i>monny broken</i>	1	\$ 155.00	\$ 155.00
Rear Bumper Stay <i>HW</i>	1	\$ 138.10	\$ 138.10
Rear Bumper Side retainer (LH/RH) <i>o/s broken w/s HW</i>	2	\$ 85.80	\$ 171.60
Rear Bumper Cover Clips <i>Hec</i>	1	\$ 22.00	\$ 22.00
Rear Bumper Under Centre <i>Crack</i>	1	\$ 123.85	\$ 123.85
Rear Bumper Side Under(LH/RH) <i>o/s broken w/s HW</i>	2	\$ 123.10	\$ 246.20
Rear Bumper Rear Hook <i>HW</i>	1	\$ 94.60	\$ 94.60
Rear Bumper Reflector Lamp(LH/RH) <i>o/s dislodged w/s HW</i>	2	\$ 82.90	\$ 165.80
Rear Bumper Towing Cover <i>disl-dgt</i>	1	\$ 98.80	\$ 98.80
Rear Bumper Reserve Light (Parking Brake Light) <i>broken</i>	1	\$ 328.60	\$ 328.60
Licence Lamp <i>monny broken</i>	1	\$ 193.53	\$ 193.53
Licence Lamp WIRE <i>HW</i>	1	\$ 135.80	\$ 135.80
Tail Lamp(LH/RH) <i>broken / monny broken</i>	2	\$ 935.40	\$ 1,870.80
Tail Lamp Quarter Panel(LH/RH) <i>o/s Damaged w/s src</i>	2	\$ 208.90	\$ 417.80
Rear Panel <i>src</i>	1	\$ 532.00	\$ 532.00
Antenna Assy - TRUNK <i>monny broken</i>	1	\$ 689.50	\$ 689.50
Rear Panel Garnish <i>damaged</i>	1	\$ 346.80	\$ 346.80
Spare Tyre Holder <i>broken</i>	1	\$ 223.10	\$ 223.10

Spare Tyre Panel <i>Hec</i>		1	\$ 892.50	\$ 892.50
Spare Tyre Panel Cushion <i>Hec/changed</i>		1	\$ 692.50	\$ 692.50
Spare Tyre Panel UNDER CENTRE PANEL <i>Hec</i>		1	\$ 338.80	\$ 338.80
Spare Tyre Panel UNDER SIDE PANEL (LH/RH) <i>Hec</i>		2	\$ 239.80	\$ 479.60
Panel Assy-Rear Floor Side (LH/RH) <i>o/s Renda H/S Hec</i>		2	\$ 39.40	\$ 78.80
Rear tray tools box RH <i>broken</i>		1	\$ 675.30	\$ 675.30
Rear tray tools box LH <i>broken</i>		1	\$ 693.20	\$ 693.20
REAR TRAY LUGGS CENTER <i>broken</i>		1	\$ 354.20	\$ 354.20
Exhaust Pipe Insulator <i>Hec</i>		1	\$ 235.00	\$ 235.00
Exhaust Silencer <i>Hec</i>		1	\$ 943.50	\$ 943.50
Exhaust Pipe Hanger <i>Hec</i>		2	\$ 29.20	\$ 58.40
Rear Fender(RH) <i>Dental</i>		1	\$ 1,768.30	\$ 1,768.30
Rear Fender SHIELD REAR PIECE (RH) <i>Hec</i>		1	\$ 173.60	\$ 173.60
Rear Fender SHIELD Frt Piece (RH) <i>Hec</i>		1	\$ 165.50	\$ 165.50
Rear Fender Corner inner upper garnish (LH/RH) <i>cut/broken</i>		2	\$ 486.70	\$ 973.40
Rear Fender Air-Duct (LH/RH) <i>o/s changed H/S Hec</i>		2	\$ 87.30	\$ 174.60
Rear Fender Trim Board (LH/RH) <i>then damaged</i>		2	\$ 788.75	\$ 1,577.50
Assy BSD Blind Spot Radar (LH/RH) <i>blackout 1st o/s H/S rep</i>		2	\$ 1,784.40	\$ 3,568.80
SUB TOTAL				\$ 29,912.53
LESS 20%				\$ 5,982.51
DISCOUNTED TOTAL				\$ 23,930.02
Reverse camera ASSY <i>Hec</i>	SN	1	\$ 983.20	\$983.20
Boot Lid Comfort Logo & Tel No. Sticker <i>Hec</i>	SN	1	\$ 35.00	\$ 35.00
Boot Lid Comfort Cablink Tel No. Sticker <i>Hec</i>	SN	1	\$ 30.00	\$ 30.00
Rear No.Plate + Trim Cover <i>distorted/broken</i>	SN	1	\$ 45.00	\$ 45.00
Rear Windscreen Sealant <i>Hec</i>	SN	2	\$ 46.00	\$ 92.00
Rear Bumper Rubber Mat <i>damaged</i>	SN	1	\$ 50.00	\$ 50.00
Rear Bumper Reverse Sensor <i>choi-dyul</i>	SN	1	\$ 180.00	\$ 180.00
SPARE TYRE PANEL TOP COVER SILICON <i>Hec</i>	SN	1	\$ 250.00	\$ 250.00
SUB TOTAL				\$ 1,665.20
Labour Charge				
Panel Beating		1	\$2,200.00	\$2,200.00
Spray Painting Charge		1	\$2,000.00	\$2,000.00
Wiring Charge		1	\$100.00	\$100.00
Tuff Kote		1	\$100.00	\$100.00
Towing Charge		1	\$80.00	\$80.00
Remove/Refix Cushion & Upholstery Rear		1	\$150.00	\$150.00
Remove/Refix Rear Windscreen Glass		2	\$120.00	\$240.00
Remove/Refix Reverse Sensor		1	\$120.00	\$120.00
Remove/Refix Exhaust Pipe		1	\$80.00	\$80.00
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00
Diagnostic & Resetting ADAS Optical sensor		1	\$550.00	\$550.00
TOTAL LABOUR				\$6,170.00
ESTIMATE TOTAL				\$31,765.22
Acknowledged by Repairer Signature: _____ This is an initial estimate based on visual inspection of the above vehicle. The final repair quantum				

23,548.13
18,838.50

801-

482.00

1200/- 1000/-
1200/- 1000/-

30/-
40/-

40/-
80/-

80/-
40/-

60/-

3.50/-

2480.00

21,800.50

1/5 17,400/-

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_ltr@bifrostauto.com