



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22008476/Kny3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 19/09/2022

ATTN: HELENA TAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBJ 2609E	Veh. Inspected	SCJ 7886B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1186224-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	31/08/2022

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ 200E (A)	c.c	1996
Engine No.	HIDDEN	Year of Reg.	1990
Chassis No.	WDB1240212B104124	Colour	METALLIC SILVER
Odometer	301927 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DUNLOP	8 mm
L/H Front Tyre	195/65 R15	DUNLOP	8 mm
R/H Rear Tyre	195/65 R15	DUNLOP	8 mm
L/H Rear Tyre	195/65 R15	DUNLOP	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/08/2022	Inspect Date / Time	31/08/2022 (10:15 AM)
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**