

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	INCOME INSURAN	ICE LTD	Ref:	CS3/INC22008478/Acy3m4	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE	Date:	30/09/2022	
	ATTN: CYNDIIE YO	ONG	Code:	INC	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GX 1206H	Veh. Inspected	SGK 4124J	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1186228-002	Excess (\$)	0.00	
	Assign From	ANNIE KOH	Assign Date	31/08/2022	
2. Vehicle Particulars & Condition					
	Make & Model	KIA FORTE K3	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	KNAFX411MF5471648	Colour	GREY	
	Odometer	210439 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	PIRELLI	6 mm	
	L/H Front Tyre	205/55 R16	PIRELLI	6 mm	
	R/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
	L/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
4. Description of Damages					
	THE VEHICLE SUS UNDERCARRIAGE	EHICLE SUSTAINED DAMAGES AT THE O/S BODY & RCARRIAGE.			
5.	General Information				
	Accident Date	28/08/2022	Inspect Date / Time	31/08/2022 (05:13 PM)	
	Survey held at	QMO ENGINEERING			
		10 KAKI BUKIT ROAD 2, #03-18, FIRST EAST CENTRE, SINGAPORE 417868			
5a.	5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/INC22008478/Acy3m4

Inspected By

ADRIAN LING WAI PING

K.K.LAU CPT(RET)

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

Licensed Appraiser REGD Auto Consultant-SAE, Licensed Appraiser